

Institution of Civil Engineers' journals include the following groundbreaking titles:

Engineering History and Heritage  
- an addition to ICE Proceedings

Advances in Cement Research  
Bridge Engineering  
Civil Engineering  
Construction Materials  
Dams and Reservoirs  
Energy  
Engineering and Computational Mechanics  
Engineering Sustainability  
Geosynthetics International  
Geotechnical Engineering  
Géotechnique  
Ground Improvement  
Magazine of Concrete Research  
Management, Procurement and Law  
Maritime Engineering  
Municipal Engineer  
Structural Concrete  
Structures and Buildings  
Transport  
Urban Design and Planning  
Waste and Resource

#### FREE Sample Copies


To download a free sample copy of one of our journals visit [www.thomastelford.com/journals](http://www.thomastelford.com/journals)

#### FREE eToc Alerts

Keep up to date with the latest articles published in ICE journals by registering for our email table of content alerts at [www.thomastelford.com/alerts](http://www.thomastelford.com/alerts)

#### Publish With Us

For information on publishing in ICE journals visit [www.thomastelford.com/journals/authors.asp](http://www.thomastelford.com/journals/authors.asp)



# Institution of Civil Engineers Journals

bringing you the latest thinking and best practice in international civil engineering

**AUTHORITY** - we've been publishing engineering journals since 1836 and are one of the leading providers of information for professionals and academics worldwide

**QUALITY** - all our journals are peer reviewed, supported by highly respected international editorial panels, and many are included in the Science Citation Index®. We also publish journals for prestigious societies, including the International Federation for Structural Concrete, the British Dam Society and the International Geosynthetics Society


**ACCESS** - the ICE Virtual Library gives you access to the full text of all materials published in the ICE Proceedings since 1836. Search over 20,000 articles seamlessly and quickly to find the information vital for your research or practice. We also offer online access for individual journals, and by subscribing you get all the papers published in the last five years at no extra cost

**EXPOSURE** - our journals are an outlet for the best engineers in the industry. We can bring you developments from academics and practitioners working on groundbreaking projects across the world

**SERVICE** - we provide email table of contents alerts so you don't have to keep checking the website, ahead of print publication to ensure new knowledge reaches you as rapidly as possible, and reference linking under CrossRef® for all our journals

[www.thomastelford.com/journals](http://www.thomastelford.com/journals)

# Materials Evaluation



March 2007

Volume 65/Number 3

**ASNT's  
16th Annual  
Research  
Symposium  
26-30 March 2007  
Orlando, Florida**

An Official Journal of the American Society for Nondestructive Testing



## We raised the resolution bar so high no other system even comes close.

Only **Dynamix™ HR** delivers a record-shattering 62-megapixel image. When it comes to image quality, Fujifilm has no competition. Our Dynamix HR is the only system on the market that offers truly square pixels at .002 inches. That's twice the resolution of our previous system – the same one that was already the image quality champion. Here's another incredible feat: even though the Dynamix HR is a 50-micron reader, its read and erase cycle time is an unbelievably fast 97 seconds. Plus it's surprisingly compact. And, as with all Fujifilm products, you'll get the kind of performance and technical support our NDT customers have come to expect from the industry leader. So call Fujifilm today at 1-800-323-2546. You'll flip when you see it for yourself.



**DYNAMIX™**

**FUJIFILM**

[www.fujindt.com](http://www.fujindt.com)

©2007 FUJIFILM Medical Systems USA, Inc.

Circle 1 on reader service card

# Structural Conservation of Robert Stephenson's High Level Bridge across the River Tyne

by Graham Herdman,\* Tim Abbott† and Jon Powell†

## History

Newcastle and Gateshead, in north-eastern England, are joined by 10 bridges. Newcastle stands on the northern bank of the Tyne Gorge, facing its smaller neighbor Gateshead on the opposite side of the river; both make up Tyneside. The Romans built the first bridge over the River Tyne, guarded by a fort on Hadrian's Wall, and named it Pons Aelius. They picked this site as it was the first point upstream at which the River Tyne could be bridged with their technology. The Normans, realizing the importance of the site, built a wooden castle in 1080, with the "New Castle" giving the area the name by which it continues to be known.

The abundance of local natural resources stimulated the growth of industry on Tyneside. Coal had been mined in the area since the 14th century and had directly stimulated the development of the world's earliest railways in the northeast during the 1800s. Also significant for Tyneside was the local availability of iron ore, which, in conjunction with coal, provided support for shipbuilding, locomotive engineering, civil engineering and armament manufacture.

Though Newcastle was considered a destination by the various companies that built lines to it, they felt that the city could not be a hub because the new railway could not descend to cross a low level bridge at the bottom of the gorge. Any connection would need to cross the gorge at a high level.

In 1845, the decision was taken to build a combined road and rail bridge. Robert Stephenson's High Level Bridge (completed 1849) was one of the world's first road and rail crossings, with the railway carried above and the roadway below. Stephenson's design followed at least 19 different proposals by the most prominent railway engineers of the time. The designs included both high and low level bridge crossings

between Gateshead and Newcastle. The fact that foot and cart passage was also required led to Stephenson's adoption of a two-tier structure — the first time this form was used.

Contracts for the construction of the bridge were handed out in July 1846, and in February 1847 the casting of the ironwork

began. By July 1847, the first span was ready for testing. It was intended to proof test the first span to 635 000 kg (700 tons), but during the testing a partner asked Stephenson to increase the load by another 90 000 kg (100 tons) to improve public confidence. Confidence in Stephenson's designs, and iron bridges in general, were at an all-time low after the failure of his River Dee bridge, which had collapsed under a train only eight weeks earlier.

The ironwork was completed in April 1849, and a full working load test was carried out in August of the same year using a test load of four tender locomotives and 18 wagons loaded with ballast weighing a total of 180 000 kg (200 tons). Queen Victoria officially opened the High Level Bridge on 28 September 1849 (Addyman and Fawcett, 1999). It now has Grade I Listed status (that is, it is a legally protected landmark), being recognized as among the world's finest ironwork structures (Figure 1).

**Once completed, this restoration project will extend the useful life of the bridge for at least another 50 years.**




Figure 1 — Stephenson's High Level Bridge viewed from Newcastle.

\* Bridges NDT Ltd., 6 Fellside, Delves Lane, Consett DH8 7AL, England; 44 1207 509964; fax 44 1207 509964; e-mail <gherdman@bridgesndt.co.uk>.

† Mott MacDonald Ltd., St. Anne House, Wellesley Rd., Croydon CR9 2UL, England; 44 20 8774 2997; fax 44 20 681 5706.




Figure 2 — Isometric cross-sectional drawing of a High Level Bridge span.

### The Bridge Today

The current owner of the Bridge, Network Rail, also owns a number of cast iron arch underbridges, but these work predominantly in compression; the High

Level Bridge is a rare example of an underbridge supporting a live railway with cast iron members in tension bending.

The use of cast iron as a structural material for arched bridges had been pioneered for the Ironbridge at Coalbrookdale in 1799 (Addyman and Fawcett, 1999). Although strong in compression, cast iron is known to be brittle in tension. Failures of a number of cast iron bridges in the late 1800s led to the decision to remove or strengthen all cast iron bridges subjected to live load bending. These failures have all, however, been attributed to the presence of major, internal casting anomalies.

Stephenson's High Level Bridge has six main spans, each comprising four cast iron arch ribs (tied arches) restrained by wrought iron tie chains anchored at the bearings (Figure 2). The road deck is suspended beneath the arch ribs by wrought iron bars, which support cast iron longitudinal girders and, originally, a timber deck. The rail deck is carried by cast iron U-shaped cross girders, which are supported above each arch rib by cast iron columns; longitudinal timber weigh beams supported in cast pockets of the cross girder then directly support the rails of the three tracks.

When the High Level Bridge was opened, maximum total train weights were around 445 000 kg (490 tons). Train weights can now be almost three times this value, although freight movements are restricted. Initially, the bridge with its three tracks carried an average of 25 trains per day; by 1890 there were 800 train movements per day.

Various modifications have been made to the bridge over its lifetime to accommodate these loading changes. The rail deck cross girders were strengthened in 1890 by the addition of steel "swan neck" girders.

In 1922, the road deck was strengthened by replacing the timber cross beams with steel cross girders, to take double-track electric tramcars (previously, horse-drawn trams had used the bridge). In the 1950s, the timber weigh beams and rail decking were replaced by a heavier ballasted track. In 1990, the three train tracks were reduced to two.

### Structural Health Assessment of the High Level Bridge

A principal inspection and structural assessment highlighted elements within the structure that were below strength or were in need of repair or replacement. Various strengthening and repair works have been designed over the last four years and have been implemented while the bridge was open to both road and rail traffic by the framework contractor, May Gurney. In February 2005, however, the road deck was closed to allow the replacement of the primary road deck elements to begin. Removal of the road deck paint (some 32 coats), resulted in the exposure of latent anomalies and it was subsequently decided that paint should be removed from the entire structure to allow detailed nondestructive testing (NDT) and subsequent repainting. Working closely with Bridges NDT and Dave Ackley NDT, Mott MacDonald are close to completing the NDT of 57,000 m<sup>2</sup> (614 000 ft<sup>2</sup>) of metalwork.

What follows is a description of some of the more interesting problems encountered during the nondestructive testing of the High Level Bridge.

### NDT of Metallic Elements

All metallic elements have been grit blasted to remove paintwork and corrosion to allow, where possible, 100% visual testing. Generally, a complete span has been blasted and handed over for NDT without holding primer. Magnetic particle testing with alternating current yokes, using black ink and white contrast paint, is used to confirm any visual indications. Once confirmed, depth sizing, using A-scan ultrasonic testing, was carried out. Where geometry or access to the anomaly inhibited ultrasonic testing, other NDT techniques were used. These included digital radiography, alternating current field measurement and alternating current potential drop.

Typical problems on the bridge can be split into six groups:

- original casting discontinuities
- discontinuities in the original dropforge welding
- fatigue induced anomalies
- corrosion
- weather damage
- heat damage.

Those anomalies classed as "original casting discontinuities" can be further divided into the following categories (Figure 3):

- gas holes and gas porosity caused by either hydrogen in the molten metal at

# CURTIS

QUALITY • EXPERIENCE • DEPENDABILITY

**Standard and Custom Ultrasonic Calibration Blocks**  
Custom block design assistance available.

**Custom Reference Standards**  
EDM notches and flat bottom holes

Certification traceable to NIST and documented in our files for repeatability and customer reference.

**CURTIS INDUSTRIES, INC.**  
105 West Park Drive  
Kittanning, PA 16201  
Tel.: 724-545-8333  
Fax: 724-545-8334  
www.curtis-test.com

Circle 17 on reader service card




Figure 3 — Original casting and forge discontinuities: (a) gas porosity and holes; (b) gas entrapment; (c) cold shuts; (d) unfused chills; (e) hot tears; (f) sand inclusions; (g) uneven wall thickness; (h) lack of weld fusion.




Figure 4 — Other forms of anomalies encountered on the bridge: (a) fatigue stress cracks; (b) girder corrosion; (c) weather damage; (d) heat damage.

tapping or dampness in the mold, resulting in gas holes or wormholes

- gas entrapment (airlock) caused by air that has been trapped in the mold during pouring, resulting in a large void

- cold shuts caused by low metal temperature splashes of the molten metal onto the mold or streams of molten metal not fusing in the mold, resulting in lack of fusion

- unfused chills and chaplets caused by low metal temperature or contamination of the insert

- hot tears caused by lack of mold/core breakdown or restriction during the solidification process

- inclusions caused by sand erosion at the ingate during pouring or poor mold closure, resulting in pieces of sand scattered on up-surfaces of the casting

- uneven wall thickness caused by misplaced cores.

The original dropforge welding discontinuities were caused by low metal temperature, contamination or lack of hammering on the joint, resulting in lack of fusion at the joint.

The other problems encountered on the bridge (Figure 4) include fatigue anomalies caused by cyclic loading, resulting in cracks in various structural members including tie chains, columns, cross girders and longitudinal girders. Corrosion, caused by wind and water erosion and salt corrosion, resulted in section loss. Weather damage, caused by freeze/thaw action, resulted in cracks and ruptures. Heat damage, caused by a warehouse fire beneath Span 6 in 1886 (Addyman and Fawcett, 1999), resulted in quench cracks.

#### Road Deck Longitudinal Girders

While dismantling the road decking and blast cleaning the retained members,

cracking of the original cast iron longitudinal girders was exposed (Figure 5). The same areas were targeted for testing throughout the structure and magnetic particle and ultrasonic testing were utilized extensively. A single girder was also extracted to validate the ultrasonic testing results. The decision was made to investigate the feasibility of providing an alternative load path. The requirements for working on protected structures in the UK, however, stipulate that the original members must be retained and that any solution should be concealed from the bridge users.

The solution was a compact fabricated steel overbeam that suspended the cross girders of both the road deck and pedestrian walkway and removed all vertical loads from the original cast iron girder. The overbeam was designed to lie beneath a




Figure 5 — Nondestructive testing of the columns: (a) visual testing; (b) ultrasonic testing.

maintenance cover plate at footpath level and with minimal intrusive fixings could, if required, be removed in the future.

#### Rail Deck Cross Girders

The cast iron rail deck cross girders were described within the assessment as being below strength. There are a total of 136 cast iron rail deck cross girders within the bridge, and a high percentage required strengthening. The chosen strengthening solution was an innovative post-tensioning system that required steel fabricated anchorages to be bonded and dowelled onto/into the cast iron of the cross girders such that the strands could be tensioned to reduce the tensile bending stresses. The solution was, however, not cheap.

In parallel with the detailed design of the strengthening solution, it was decided to undertake a study into the structure-specific fatigue performance of cast iron and, in particular, the cast iron rail deck cross girders. In order to do this, it was proposed to extract and remove three cross girders from an untrafficked area of the bridge for full scale testing. The testing was carried out in stages, each stage being more intrusive than the last but providing greater understanding of the material. The intention was to justify an improvement on

the limiting stress approach stipulated within the assessment code and thereby reduce, or even eliminate, the need for the expensive strengthening.

Each stage relied heavily upon NDT. Initially, ultrasonic testing was carried out on a representative sample of cross girders throughout the bridge in order to satisfy those involved that the girders to be removed were representative of those in the main spans. MT, RT and UT were utilized to investigate the existence of surface breaking and internal casting discontinuities or stress cracks. In-situ replication and hardness testing were also utilized throughout the bridge to confirm the microstructure and provide an estimate of ultimate tensile strength. Ultrasonic testing was also utilized to verify material thicknesses. Brinell hardness results showed that the material had an average hardness value of 151 H<sub>B</sub>, corresponding to an ultimate tensile strength of 125 MPa (18 100 lb/in.<sup>2</sup>).

Small samples were then removed for hardness testing, and metallurgical examinations were carried out to provide information on the physical and chemical composition of the material. Chemical and microstructure analysis showed the cast iron microstructure was mainly large

flake graphite in a matrix of pearlite and steadite.

Larger material specimens were then extracted from the cross girders, from which tensile test pieces were machined. These were used to confirm the ultimate tensile strength, modulus of elasticity and fatigue strength of the material. Fatigue testing was carried out to establish a statistically reliable fatigue performance spectrum (*S-N*) curve.

Following the small scale fatigue trial, three full cross girders were removed from an untrafficked part of the bridge rail deck and were sent for full scale fatigue trials (Figure 6). On arrival, all the girders were cut into test pieces. A total of 10 full scale fatigue specimens were tested at various stress ranges.




Figure 6 — Testing of the cast iron cross girders: (a) removal from the bridge; (b) full scale fatigue testing.

The first six samples were tested in a specially designed fatigue test rig and subjected to cyclic loads of predetermined range to a maximum of 2 million cycles.

The fatigue damage history was determined by detailed examination of historical records. Account was taken of modifications, such as change in dynamic effects, resulting from ballasting, relocating and reducing the number of tracks, as well as from other stress related aspects of the bridge's history.

Further testing was carried out utilizing the quarter sections, which were mounted within a smaller test rig and subjected to lower stress ranges at a higher number of cycles (up to 5 million), such that a nonpropagating stress limit could be established.

A condition of Listed Building consent was that all of the test pieces were to be re-assembled, repaired and reinstated back into the bridge. The girders are therefore to be mechanically stitched and reinforced using bonded carbon fiber reinforced plates. Reporting and conclusion of the testing program is ongoing.

### Tie Chains

The wrought iron tie chains between the arch bases are primary structural members as they act as a simple tie member restraining the longitudinal thrust of individual arches (Figure 7). Each span has six tie chains, two per inner arch and a single tie chain on each outer arch. Individual tie chains are made up of four links in either 3 or 6 m (9.8 or 19.7 ft) lengths that are connected together by fitted pins at a knuckle joint to form a tie chain 42 m (137.8 ft) in length.




Figure 7 — Tie chain link assembly: (a) showing repair; (b) showing forged joints.

The links were manufactured in three sections, consisting of two forged eyes and a flat plate. The sections were welded together by drop forging to produce the finished link. The links were all assembled into chains, with an eight eye-connecting knuckle. Historical evidence shows that all the links were proof loaded to 57 000 kg (63 tons) before they were incorporated into the permanent works.

An examination of the structure in 1999, prior to any blast cleaning work, uncovered a single fracture of a tie chain link at the forged joint between the eye and main body of the link. This was attributed to rust forcing between adjacent tie chain links (imparting secondary load effects onto the forge weld), and the probability that the forge weld contained anomalies that had not been highlighted during the original

proof loading. The fracture was repaired by a combination of welding and steel splice plates in order to prevent locked-in stresses due to welding.

In addition to visual and magnetic particle testing, various techniques of NDT were considered, with ultrasonic testing deemed the most appropriate. Radiography was not considered because of the isotope strength that would be required to penetrate the chains.

Ultrasonic testing of wrought iron can be difficult due to the microstructure.

Siliceous slag (stringers) and graphite in wrought iron can give spurious indications or absorb the ultrasonic beam. Benchmarking trials were undertaken to determine the limitations of the ultrasonic method.

An eye of a tie chain link was forged to the same profile from currently available wrought iron of a similar metallurgical composition to the wrought iron found on the structure. This allowed the benchmarking of the anomalies around the knuckle eye and adjacent forge welded joints.

## The World's #1 Portable Alloy Analysis Tool

### NITON Alloy Analyzers

- Real-time nondestructive chemical analysis
- Positive alloy grade identification
- Lab-quality data
- Sealed against moisture and dust
- Choice of x-ray tube or patented Infiniton™ isotope

**NEW!!**  
He-purge option  
provides true non-  
destructive light element  
analysis of  
Mg, Si, P and Al



NITON Analyzers  
Billerica, MA USA  
800-875-1578  
+1 978-670-7460  
Email: niton@  
thermofisher.com

Sales & Service Worldwide  
[www.thermo.com/niton](http://www.thermo.com/niton)

Part of Thermo Fisher Scientific

**Thermo**  
SCIENTIFIC

Circle 18 on reader service card




Figure 8 — Tie chain link data: (a) from finite element analysis; (b) from ultrasonic scanning.

Ultrasonic testing and digital radiography were carried out on the test piece to locate any anomalies inherent within the material. A 3 mm (0.12 in.) diameter hole, half through-thickness, was drilled in the main body of the link and used to calibrate the sensitivity of the ultrasonic equipment.

Benchmarking was undertaken by drilling a number of 3 mm (0.12 in.) diameter holes at known stressed areas determined from finite element analysis of the tie chain (Figure 8). The depth of each 3 mm (0.12 in.) hole was increased until the ultrasonic operator could consistently and accurately locate the hole. All benchmarking was undertaken replicating actual testing conditions on the structure, with holes concealed from the ultrasonic operator and all testing being limited to the accessible faces of the tie chains. Upon completion of the benchmarking, the test piece was used as a calibration block. Benchmarking has allowed the NDT of the tie chains to proceed with a greater degree of confidence.

### Remedial Measures

Structural repairs to the bridge have all been subject to Listed Building consent and comply with agreed conservation principles so that they are sympathetic to and in keeping with this heritage structure. Where possible, repairs or replacements have utilized traditional materials, and where not possible they have been designed to be reversible. For all anomalies, careful consideration has been given to the cause, whether they have resulted during manufacture (as in the case of many of the casting discontinuities), or from local or global loading effects (whether from live loads or environmental loads). Careful consideration is also given to the compatibility of materials, so that local strain incompatibilities and bimetallic corrosion is avoided.

Two methods of repair that have been popular with conservation officers include carbon fiber and steel bonded plates and mechanical stitching due to their subtle visual effects (Figure 9). Mechanical stitching





Figure 9 — Two methods of repairs: (a) plate bonding; (b) mechanical stitching.

# Automotive Industry Advancements with NDT

An ASNT Topical Conference



Find out how General Motors R&D Center's Dr. Cameron Dasch answers this critical question in his keynote address.

## ***"What's Driving NDE in the Auto Industry?"***

Plan now to join your colleagues 16 & 17 May 2007 in Dearborn, Michigan at the Doubletree Hotel Dearborn. The topical offers the forum to discuss the latest developments for implementation, inspection, training and quality control of NDT processes in production with managers, researchers, engineers, quality and manufacturing personnel.

Watch for program details at [www.asnt.org/events/events.htm](http://www.asnt.org/events/events.htm).

And to exhibit contact Ruth Staat at [rstaat@asnt.org](mailto:rstaat@asnt.org) or 614.274.6003 x227.



**Don't miss this dynamic industry focused event.**

## Contact ASNT

ASNT headquarters is open from 8:30 a.m. to 5:00 p.m. eastern time, Monday through Friday. Voicemail messages can be left 24 hours a day by following the recorded prompts. In the US and Canada, call toll free (800) 222-2768 or (614) 274-6003; fax (614) 274-6899. E-mail addresses for individual staff members are given below. If you prefer, write ASNT, 1711 Arlingate Lane, PO Box 28518, Columbus, OH 43228-0518. ASNT's Web site is available at <www.asnt.org>.

Area of Inquiry	Contact (Extension)	E-mail
<b>Executive Offices</b>		
Executive Director	Wayne Holliday (201)	wholliday@asnt.org
Administrative Assistant	Carole Chesla (223)	cchesla@asnt.org
<b>Awards</b>		
Committee participation	Carole Chesla (223)	cchesla@asnt.org
<b>Accounting Department</b>		
Senior Manager of Finance and Accounting	Mary Potter (203)	mpotter@asnt.org
Account balance inquiries	Jennifer Harris (237)	jharris@asnt.org
Credit and collections	Trina Coakley (220)	tcoakley@asnt.org
Dues payment inquiries	Carolyn Reed (229)	creed@asnt.org
<b>Book Department</b>		
Book and catalogue orders	Sandy Simpson (215)	ssimpson@asnt.org
Customer service inquiries	Trina Coakley (220)	tcoakley@asnt.org
<b>Conference Department</b>		
Senior Manager of Conferences	Michael O'Toole (202)	motoole@asnt.org
Conference registration	Angie Guzzo (228)	aguzzo@asnt.org
Exhibit and event coordination	Ruth Staat (227)	rstaat@asnt.org
Level III refresher courses	Jacque Giunta (213)	jgiunta@asnt.org
Program coordination	Jacque Giunta (213)	jgiunta@asnt.org
<b>Internet and Library</b>		
ASNT library inquiries	Brian Geary (245)	bgeary@asnt.org
ASNT Web site	Brian Geary (245)	bgeary@asnt.org
Advertising	Garra Liming (209)	gliming@asnt.org
<b>Marketing and Membership Department</b>		
Senior Manager of Marketing and Membership	Betsy Blazar (211)	bblazar@asnt.org
Corporate design services	Paul Conley (232)	pconley@asnt.org
Marketing and public relations	Betsy Blazar (211)	bblazar@asnt.org
Membership and member benefits	Ruth Dheel (216)	rdheel@asnt.org
Section activity and president's points	Tiffany Gates (217)	tgates@asnt.org
<b>Publications Department</b>		
Senior Manager of Publications	Tim Jones (204)	tjones@asnt.org
<b>Materials Evaluation</b>		
Advertising	Garra Liming (209)	gliming@asnt.org
Articles	David Fanning (207)	dfanning@asnt.org
Buyers Guide	David Fanning (207)	dfanning@asnt.org
Calendar	Emily Sellers (205)	esellers@asnt.org
Employment Service	Emily Sellers (205)	esellers@asnt.org
Ready Reference Guide	David Fanning (207)	dfanning@asnt.org
Reprints	Emily Sellers (205)	esellers@asnt.org
Section News	Emily Sellers (205)	esellers@asnt.org
NDT Handbook inquiries	Patrick Moore (224)	pmoore@asnt.org
NDTMarketplace inquiries	Emily Sellers (205)	esellers@asnt.org
Advertising	Garra Liming (209)	gliming@asnt.org
New publications authors	Cynthia Leeman (225)	cleeman@asnt.org
	Ann Spence (235)	aspence@asnt.org
	Emily Sellers (205)	esellers@asnt.org
RNDE inquiries	Hollis Humphries (206)	hhumphries@asnt.org
<i>The NDT Technician (TNT)</i> inquiries		
<b>Technical Services Department</b>		
Senior Manager of Technical Services	Jim Houf (212)	jhouf@asnt.org
Certification Supervisor	Charles Longo (241)	clongo@asnt.org
Application requests	Angela Evans (242)	aevans@asnt.org
ASNT Central Certification Program	Charles Longo (241)	clongo@asnt.org
ASNT NDT Level III examinations (International)	Lisa Law (226)	llaw@asnt.org
ASNT NDT Level III examinations (US)	Lisa Law (226)	llaw@asnt.org
ASNT NDT Level III recertification	Angela Evans (242)	aevans@asnt.org
CEU program	Roberta McGhee (218)	rmcghee@asnt.org
General inquiries	Angela Evans (242)	aevans@asnt.org
IRRSP/radiation safety	Jennifer Harris (237)	jharris@asnt.org
Technical inquiries	Jim Houf (212)	jhouf@asnt.org

If you are having trouble locating who should handle your inquiry, please ask the operator at extension 200 to direct your call to the appropriate department personnel.

requires the incorporation of nickel alloy keys that are peened into jig-drilled holes across cracks.

When it was first built, the total cost of Stephenson's High Level Bridge was £491,000 — equivalent to £40 million in today's money. The current estimated cost of the refurbishment work is £27 million. Once completed, this restoration project will extend the useful life of the bridge for at least another 50 years.

### Conclusion

The testing of the High Level Bridge has provided the opportunity to add to the information available on the fatigue performance and nondestructive testing of cast iron. This will enable industry to make better-informed decisions when dealing with the conservation of protected cast iron structures.

### Acknowledgments

The authors would like to thank Alistair Cooke, of Mott MacDonald, for his help in preparing this paper.

### References

Addyman, John and Bill Fawcett, *The High Level Bridge and the Central Station: 150 Years across the Tyne*, Stockton on Tees, England, North Eastern Railway Association, 1999.

## What's in a Name?

To ensure proper usage of NDT terminology, ASNT would like to remind readers that the following terms should be used when referring to the certification status of NDT personnel.

■ Personnel certified by examination by their employer (or through contracted examination agencies or training facilities other than ASNT) should be listed as being "certified in accordance with *Recommended Practice No. SNT-TC-1A*." In addition, employer certified Level IIIs may be called "Level IIIs."

■ Personnel certified by ASNT examination may be referred to as being "ASNT certified" and may be called by the proper name "ASNT NDT Level III."

■ Personnel certified through the ASNT Central Certification Program (ACCP) may be said to be "ASNT certified" or, more properly, to have been certified as an "ACCP Level II" or "ACCP Professional Level III."


Adherence to these simple distinctions will reduce confusion in the industry.

## C. Proposed Instrumentation


(referred to in Section 1.4)

Instrumentation for Long Term Monitoring – to end of Contract


Elevation



Plan



## Cross Section



CROSS SECTION LOOKING SOUTH

SCALE 1:50

Key:

←→ LVDT at bearings

★ Prism for total station (100% on 1 face, 75% on the other face)

★ Thermocouple on truss – top and bottom flange

★ Thermocouple on chain – inner, outer and centre leaves


★ Thermocouple in tower and ambient thermocouple

## Monitoring Equipment Schedule – Long Term


Equipment	Location	Number – Long Term (To end of Contract)
LVDT	4 tower bearings	4
Prisms	Cables and deck level + 2 control prisms	8
Thermocouples	6 on Cables, 4 on Main Truss, 1 Tower, 1 Ambient	12

Instrumentation for Short Term Monitoring – to end of Investigations Phase


Elevation



Plan



## Cross Section



## Tower

Strain measurements will be taken at 5 locations in 2 towers (diametrically opposite towers)



Key:

-  Strain measurement on hanger (2 adjacent hangers per location – i.e. one to top chain and one to bottom chain)
-  Strain measurement on longitudinal truss top chord
-  Strain measurement of outer and inner leaves of chain
-  Strain measurement of tower truss elements
-  Strain measurement bottom flange of cross girder
-  LVDT at bearings
-  Inclinerometers to pin bearings
-  Inclinerometers to hanger and corresponding cross-girder
-  Prism for total station (100% on 1 face, 75% on the other face)
-  Anemometers
-  Strain measurement at 6 locations at eye of chain
-  Thermocouple on truss – top and bottom flange
-  Thermocouple on chain – inner, outer and centre leaves
-  Thermocouple in tower and ambient thermocouple

**Monitoring Equipment Schedule – Short Term**

<b><u>Equipment</u></b>	<b><u>Location</u></b>	<b><u>Number – Short Term (To end of Investigations Phase)</u></b>
Strain Gauge	Hangers – at dead load strain monitoring locations	8
Strain Gauge	Longitudinal Truss - at dead load strain monitoring locations	5
Strain Gauge	Chains – inner and outer leaves – at dead load strain monitoring locations + chain saddles	24
Strain Gauge	Tower elements - at dead load strain monitoring locations	10
Strain Gauge	Cross girder	2
Strain Gauge	Chain eye	6
LVDT	4 tower bearings and at 2 anchorages	10
Inclinometers	Pin bearings	8
Inclinometers	Hangers and corresponding cross girder	4
Prisms	Cables and deck level + 2 control prisms	27
Anemometers	Top of towers	1
Thermocouples	6 on Cables, 4 on Main Truss, 1 Tower, 1 Ambient	12

## **D. M56 Helsby Junction Viaduct Assessment Report**

(referred to in Section 1.5)





















































































# Appendix A. SLS Bearing Assessment Calculations



































































































































# Appendix B. Jacking Options Drawings











# Appendix C. Jacking Options Assessment Calculations



























































































































# Appendix D. Seized Bearings Assessment Calculations































































## **E. Checking and Approval Procedure**

(referred to in Section 1.8)





















## Hammersmith Bridge

### Mott MacDonald Organisation Chart



## **G. Templates for Factual and Interpretive Reports**

(referred to in Section 1.4)



# **Hammersmith Bridge Strengthening and Refurbishment Works**

Site Testing and Monitoring: Interpretive Report

10 May 2017

Mott MacDonald House  
8-10 Sydenham Road  
Croydon CR0 2EE  
United Kingdom

T +44 (0)20 8774 2000  
F +44 (0)20 8681 5706  
mottmac.com

Hammersmith & Fulham  
Council  
Town Hall, King Street  
Hammersmith  
London W6 9JU

# **Hammersmith Bridge Strengthening and Refurbishment Works**

Site Testing and Monitoring: Interpretive Report

10 May 2017

# Issue and Revision Record

Revision	Date	Originator	Checker	Approver	Description
P1	10/04/17				Draft for comments
P2	10/05/17				First Issue

**Information class: Standard**

---

This document is issued for the party which commissioned it and for specific purposes connected with the above-captioned project only. It should not be relied upon by any other party or used for any other purpose.

We accept no responsibility for the consequences of this document being relied upon by any other party, or being used for any other purpose, or containing any error or omission which is due to an error or omission in data supplied to us by other parties.

This document contains confidential information and proprietary intellectual property. It should not be shown to other parties without consent from us and from the party which commissioned it.

---

# Contents

Executive summary	1
<b>1 Introduction</b>	<b>2</b>
1.1 Scope of Report	2
1.2 Background	2
1.3 Methodology	2
1.4 Limitations	2
<b>2 Site works</b>	<b>3</b>
2.1 Visual inspection of general condition	3
2.2 Non-Intrusive Investigation	3
2.2.1 Photographic Survey	3
2.2.2 Asbestos Survey	3
2.2.3 Electrical and Lighting	3
2.2.4 Topography and Geometric Survey	3
2.2.5 Ecology	3
2.2.6 Fatigue involving NDT	3
2.2.7 Hanger vibration tests	3
2.2.8 Bridge monitoring	3
2.2.9 Load testing	3
2.3 Intrusive Investigation	3
2.3.1 Protective Coat Survey	3
2.3.2 Hanger Load Tests	3
2.3.3 Chain Load Tests	3
2.3.4 Material Tests	3
2.3.5 Schedule of test areas	3
<b>3 Discussion</b>	<b>5</b>
3.1 The investigation findings	5
3.1.1 Inspection observations	5
3.1.2 Overall conclusions	5
<b>4 Factual Reports</b>	<b>6</b>
<b>5 References</b>	<b>7</b>
<b>Appendices</b>	<b>8</b>

## A. Site Layout

9

# Executive summary

# 1 Introduction

## 1.1 Scope of Report

## 1.2 Background

## 1.3 Methodology

## 1.4 Limitations

## 2 Site works

### 2.1 Visual inspection of general condition

### 2.2 Non-Intrusive Investigation

#### 2.2.1 Photographic Survey

#### 2.2.2 Asbestos Survey

#### 2.2.3 Electrical and Lighting

#### 2.2.4 Topography and Geometric Survey

#### 2.2.5 Ecology

#### 2.2.6 Fatigue involving NDT

#### 2.2.7 Hanger vibration tests

#### 2.2.8 Bridge monitoring

#### 2.2.9 Load testing

### 2.3 Intrusive Investigation

#### 2.3.1 Protective Coat Survey

#### 2.3.2 Hanger Load Tests

#### 2.3.3 Chain Load Tests

#### 2.3.4 Material Tests

#### 2.3.5 Schedule of test areas



## **3 Discussion**

### **3.1 The investigation findings**

#### **3.1.1 Inspection observations**

#### **3.1.2 Overall conclusions**

## 4 Factual Reports

The factual data on which this report is based can be found in the following reports:

Report Title	Company	Reference	Link
Photographic Survey	CAN	383488-MMD-00-ZZ-RP-F4-0001	<a href="#">Photographic Survey</a>
Asbestos Survey	XYZ Services	383488-MMD-00-ZZ-RP-F4-0002	<a href="#">Asbestos Survey</a>
Electrical and Lighting	ABC Circuits	383488-MMD-00-ZZ-RP-F4-0002	<a href="#">Electrical and Lighting</a>

**Table 2 Schedule of Factual Reports**

## 5 References


# Appendices

A. Site Layout

9

## A. Site Layout





# **Hammersmith Bridge Strengthening and Refurbishment Works**

Photographic Survey

10 May 2017

Mott MacDonald House  
8-10 Sydenham Road  
Croydon CR0 2EE  
United Kingdom

T +44 (0)20 8774 2000  
F +44 (0)20 8681 5706  
mottmac.com

Hammersmith & Fulham  
Council  
Town Hall, King Street  
Hammersmith  
London W6 9JU

# **Hammersmith Bridge Strengthening and Refurbishment Works**

Photographic Survey

10 May 2017

# Issue and Revision Record

Revision	Date	Originator	Checker	Approver	Description
P1	10/04/17				Draft for comments

**Information class: Standard**

This document is issued for the party which commissioned it and for specific purposes connected with the above-captioned project only. It should not be relied upon by any other party or used for any other purpose.

We accept no responsibility for the consequences of this document being relied upon by any other party, or being used for any other purpose, or containing any error or omission which is due to an error or omission in data supplied to us by other parties.

This document contains confidential information and proprietary intellectual property. It should not be shown to other parties without consent from us and from the party which commissioned it.

# Contents

Executive summary	1
1 Introduction	2
1.1 Scope of Report	2
1.2 Background	2
1.3 Methodology	2
1.4 Limitations	2
2 References	3
Appendices	4
A. Site Layout	5
B. List of Photographs	6
C. Photographs	7

# Executive summary

# 1 Introduction

## 1.1 Scope of Report

## 1.2 Background

## 1.3 Methodology

## 1.4 Limitations

## 2 References

# Appendices

A.	Site Layout	5
B.	List of Photographs	6
C.	Photographs	7

## A. Site Layout

## **B. List of Photographs**

## C. Photographs

--	--

Mott MacDonald Limited. Registered in  
England and Wales no. 1243967. Registered  
office: Mott MacDonald House, 8-10  
Sydenham Road, Croydon CR0 2EE, United  
Kingdom

**[mottmac.com](http://mottmac.com)**