




## WF-08

**String  
Course**



See below for enlarged proposed Mullion data

WF-08-  
WF-08-WF-08-2  
WF-09-2WF08-3  
WF09-3

Plan view



replacement.



are to be offered up and set within the rebate in a lime mortar bed.



**Refer to Drg 950-017**



Existing stone sections have eroded past the glass line.

**Individual Stone sections making up windows WF-08 and WF-09**


to be carefully selected and approved by the Conservation Architect



Million

millions.

of million



tooth tooling to the front exposed face.



WF-03


NORTH FACING ELEVATION  
Refer to drawing 950-Q18 for full details of all stone repairs to this north elevation.



Existing Photographic Record of Window WF-03




Existing red sandstone sill to be retained and redressed.



Window WF-03 External

Existing leaded lights. Individually sized to suit each individual window opening.  
The existing windows will need to be carefully removed and safely stored for later refitting. Allow for fully reconstructing the existing leaded lights to fit the new reveals with rebated glass lines.  
The repaired leaded lights and metal casements, (WF-03, WF-05, WF-07) are to be offered up and set within the rubble in a lime mortar bed.




Surveyed drawing of window WF-03

Existing stone sections forming the window jambs, mullion, sills and window heads to be reassessed to determine extent of replacement. As most of the existing stone window reveals to the north elevation have now eroded up to and in parts beyond the glass line.  
The stone sections forming WF-03 are a mix of a Forest of Dean and Ross Red/Brown sandstone. All stone sections have eroded back to the existing glass line and will require replacement all with approved Ross red sandstone.

- Window WF-03-External
- Forest Stone
  - Red Sandstone
  - Modern Mortar
  - Frosted glass
  - Modern Sill

Window WF-03-External




Existing red sandstone sill to be retained and redressed. WF03-1 Existing Stone in-situ  
Remainder of stone sections forming the window jambs, mullion and window heads to be reassessed to determine extent of replacement. As most of the existing stone window reveals to the north elevation have now eroded up to and in parts beyond the glass line.  
The stone mullion to WF-03 is of a Forest of Dean stone and not the original sandstone.  
An earlier stone repair scheme has seen the insertion of a new red sandstone sill to this window which will require re-dressing to the approved profiles.  
The remaining 2 jambs and window head sections are also eroded to the glass line and require re-facing with rebated detail and profiles.






NORTH FACING ELEVATION

Refer to drawing 950-018 for full repairs to this north facing elevation.



WF-04


Photographic record of the existing condition of WF-04



Measured Internal Arrangement for Window WF-04.

Scale 1:10 @ A1

- (Rose Brownstone)
- Devonian, medium grained sandstone
- (Forest of Dean) Sandstone
- Buff creamy grey
- Temporary lead sheet cappings fixed over eroded sills




56.00m

55.00m

54.00m

53.00m


Surveyed drawing of window WF-04



String Course

Existing leaded lights, individually sized to suit each individual window opening. The existing windows will need to be carefully removed and safely stored for later refitting. Allow for fully reconstructing the existing leaded lights to fit the new reveals with rebated glass lines. The repaired leaded lights, (WF-04) are to be offered up and set within the rebate in a lime mortar bed.

Section at Head B-B




56.00m

55.00m

54.00m

53.00m


Section A-A




Plan view

Existing external weathered stone face

Plan view, nts



Elevation of stone sections required for replacement





NOT TO SCALE



NORTH FACING ELEVATION

Refer to drawing 950-018 for full repairs to this north facing elevation.




Surveyed drawing of window WF-05


Existing leaded lights. Individually sized to suit each individual window opening.

The existing windows will need to be carefully removed and safely stored for later refitting. Allow for fully reconstructing the existing leaded lights to fit the new reveals with rebated glass lines.

The repaired leaded lights and metal casements, (WF-03, WF-05, WF-07) are to be offered up and set within the rebate in a lime mortar bed.



Extent of stone replacements to return the window with functioning sills, window heads, jambs and mullion safely securing the leaded light and opening casement in a serviceable position.




Window WF-05-External

1:20 @A3


Existing stone sections forming the window jambs, mullion, sills and window heads to be removed to determine extent of replacement. As most of the existing stone window reveals to the north elevation have now eroded up to and in parts beyond the glass line.

The stone sections forming WF-05 are a mix of a Forest of Dean and Rose Red/Brown sandstone. All stone sections have eroded back to the existing glass line and will require replacement all with approved Rose Brownstone.

NOT TO SCALE



Photographic record of Existing WF-05



Individual identified Stone sections making up window WF-05

All window stone replacements to be in Rose Brownstone to be carefully selected and approved by the Conservation Architect

WF-06



NORTH FACING ELEVATION

Refer to drawing 950-018 for full repairs to this north facing elevation.


- (Rose Brownstone)
- Devonshire, medium grained sandstone
- (Forest of Dean) Sandstone
- Buff creamy grey
- Temporary lead sheet cappings
- fixed over eroded sills

Window WF-06 External

55.00m

String Course

String Course



Surveyed Drawing of WF-06


Existing leaded lights. Individually sized to suit each individual window opening.

The existing windows will need to be carefully removed and safely stored for later refitting. Allow for fully reconstructing the existing leaded lights to fit the new reveals with reinstated glass lines.

The repaired leaded lights (WF-06) are to be opened up and set within the masonry in a time mortar bed. Adjusted within the bed to align with the opening.

Window WF-06-External


1:20 @ A3



String Course

String Course

Elevation of stone sections required for replacement




Plan View

Existing stone sections forming the window jambs, mullion, sills and window heads to be reassessed to determine extent of replacement. As most of the existing stone window reveals to the north elevation have now eroded up to and in parts beyond the glass line.

The stone sections forming WF-06 are a mix of a Forest of Dean and Rose Red/Brown sandstone. All stone sections have eroded back to the existing glass line and will require replacement all with approved Rose Brownstone, sandstone

NOT TO SCALE



WF-06

Photographic record of the existing condition of WF-04

WF-06-6

WF-06-7



WF-06-1

WF-06-2

Individual Identified Stone sections making up the window surrounds and sill.

Individual Stone sections making up window WF-06

All window stone replacements to be in Rose Brownstone to be carefully selected and approved by the Conservation Architect

NO. 1000000000

Issue To

Issue To

Issue To

**HAWKES EDWARDS**  
CHARTERED ARCHITECTS  
HISTORIC BUILDING CONSULTANTS  
1 Old Town  
Worcestershire CV2 2EQ  
01905 820000  
www.hawkesedwards.com


CLIENT: Ross-on-Wye Town Council  
PROJECT: North Elevation WF-06 Stone Repairs  
TITLE: WTS  
SCALE: 1:20 @ A3  
DATE: 11/04/22  
DRAWN BY: JRM  
CHECKED BY: JRM  
PROJECT NO: 950  
DRAWING NO: 034  
R.D.





Refer to drawing 950-018 for full repairs to this north facing elevation.

- (Ross Brownstone)
- Devonian, medium grained sandstone
- (Forest of Dean) Sandstone
- Buff creamy grey
- Temporary lead sheet cappings
- fixed over eroded sills



56.00m


55.00m

54.00m

53.00m

Window WF-07 External

Surveyed Drawing of WF-07




Existing leaded lights, individually etched to suit each individual window opening. The existing windows will need to be carefully removed and safely stored for later refitting. Allow for fully reconstructing the existing leaded lights to fit the new reveals with rebated glass lines.

The repaired leaded lights and metal casements, (WF-03, WF-05, WF-07) are to be offered up and set within the rebate in a lime mortar bed.


String Course

Window WF-07-External



String Course

Window WF-07 stone sections identified for replacement



Elevation of stone sections required for replacement


Plan View



Existing stone sections forming the window jambs, mullion, sill and window heads to be reassessed to determine extent of replacement. As most of the existing stone window reveals to the north elevation have now eroded up to and in parts beyond the glass line.

The stone sections forming WF-07 are a mix of a Forest of Dean and Ross Red/Brown sandstone. All stone sections have eroded back to the existing glass line and will require replacement all with approved Ross red sandstone.

NOT TO SCALE




WF-07


Photographic record of WF-07

Existing stone sections have eroded past the glass line.

WF07-6



WF07-7



Individual Stone sections making up window WF-07

All window stone replacements to be in Ross Brownstone to be carefully selected and approved by the Conservation Architect

PRELIMINARY

No. 1000

Issue 30

Issue Date

**HAWKES EDWARDS**  
CHARTERED ARCHITECTS  
HISTORIC BUILDING CONSULTANTS  
www.hawkesedwards.com

CLIENT: Ross-on-Wye Town Council  
PROJECT: Market House  
TITLE: North Elevation WF-07 Stone Repairs  
SCALE: 1/10 (see sheet 950-018) 1/20 (see sheet 950-019)  
DATE: 13/04/2021 (sheet 950-018) 1/20 (see sheet 950-019)  
JOB/CLIENT NUMBER: 950 035  
DRAWN BY: RGT



## A photograph of a stone wall with a large, arched wooden door and two small, arched windows below it. The wall is made of rough-hewn stones. The door is made of dark wood and has a small, arched window at the top. The two small windows below the door are also arched and have metal grates. A wooden handle or latch is visible on the door.

**Current existing stonework condition to archway opening**

Majority of excessive erosion is evident at the lower stones.



Small stone to be replaced  
half depth - externally

Allow for stonework to be replaced  
half depth - externally


**Allow for stonework to be replaced half depth - externally**



Right side

Existing sound stone and the rear face of the pinned repair have eroded resulting in a void being present.

Front plane of pinned stone is unsecure and prone to becoming entirely detached.




WEST FACING ELEVATION




WF-01

Photographic record of WF-01




Individual Stone sections making up window WF-01

All window stone repairs to replicate the existing Ross Brownstone  
The proposed mtk is to carefully selected, monitored and approved  
by the Conservation Architect.



Window WF-01, WF-02



Vertical stone sections identified for some repair,  
all sections to be uncovered and assessed.



WF-02

Photographic record of WF-02

53.00m



Existing head stones appear to be less eroded and  
with a careful assessment

Existing leaded lights. Individually sized to suit each individual window opening.  
The existing windows will need to be carefully removed and safely stored for  
later refitting. Allow for fully reconstructing the existing leaded lights to fit the new  
revels with remade glass lines.

The repaired leaded lights and metal casements, (WF-01 , WF-02) are to  
be offered up and set within the rubble in a lime mortar bed.

Section Line

Window WF-02 External survey drawing.  
Elevation and section

Existing stone sections forming the window jambs, mullion, sills  
to be reassessed to determine extent of repair.  
As most of the existing stone window reveals to the north elevation have  
now eroded up to and in parts beyond the glass line.

The stone sections forming WF-01 and WF-02 are of a Ross Red/Brown  
sandstone. All stone sections are heavily eroded, some back to the existing glass line.  
Repairs will be required, in parts with an approved suitable mortar mix to match the  
existing Ross red sandstone.

The existing sills are currently shielded by hand dressing to aid the  
shedding of rainwater, and arrest further erosion.  
Depending on their revealed current condition and further assessment  
allow for placing in clay tiles as shown to form the replacement sill.  
Form the sill in alternating the layers set in lime mortar with fine verticle  
joints, the leading edge extending slightly past the restoration line.  
Form a small verticle mortared upland to the existing glass line.

Left and right jambs, centre mullion to receive a sensitive  
mortar repair to bring the profile back and reform the edge  
to the glass line.  
The repair must be of the best quality, undertaken correctly  
in accordance to the specification to ensure compatibility with the  
existing existing host stone, matching the colour, texture and finish.  
The applied mortar mix will be approved by Historic England  
and the Conservation Architect and must be undertaken by a suitably  
qualified conservation craftsman familiar with such fine detailed  
plastic mortar applications and techniques.

Left and right jambs, centre mullion to receive a sensitive  
mortar repair to bring the profile back and reform the edge  
to the glass line.  
The repair must be of the best quality, undertaken correctly  
in accordance to the specification to ensure compatibility with the  
existing existing host stone, matching the colour, texture and finish.  
The applied mortar mix will be approved by Historic England  
and the Conservation Architect and must be undertaken by a suitably  
qualified conservation craftsman familiar with such fine detailed  
mortar applications and techniques.

The existing sills are currently shielded by hand dressing to aid the  
shedding of rainwater, and arrest further erosion.  
Depending on their revealed current condition and further assessment  
allow for placing in clay tiles as shown to form the replacement sill.  
Form the sill in alternating the layers set in lime mortar with fine verticle  
joints, the leading edge extending slightly past the restoration line.  
Form a small verticle mortared upland to the existing glass line.