





TV Tristram Refit Specification

TASK NO.	TASK/DESCRIPTION H9 MISCELLANEOUS	NOTES
H9.03	Gundeck Redundant Aerials	
	There are five in number redundant aerials fitted on the gundeck. Two aerials have already had their mountings so weakened by corrosion that they have come detached, therefore to avoid injury or damage in the future the five remaining aerials are to be REMOVED and disposed of by Contractor.	

TASK NO.	TASK/DESCRIPTION H9 MISCELLANEOUS	NOTES
H9.04	Ballast Tank One in number ballast tank requires topping up with fresh water. Contractor is to complete this task and provide the volume of water required to the Authorised Overseer to record in ships Stability records.	Ballast tank will be identified to contractor prior to RPSD
	ALLOW for 500m ³ fresh water.	
		-
		and the second
1		12.20
		1.1
Sec. 1		