NCM05

National Coal Mining Museum, Caphouse Colliery, WF4 4RH

Small works contract Nov 2025

REFERENCE PHOTOS:

Schedule section 2: Steam winding house





Roof: General views from North





Roof: Ridge dormer has lost its covering leaving just decaying plywood






Roof: Cracked and broken slates to North side

Roof: General view of south side







Elevations: North steps, mortar falling from joints and gathering on steps



Schedule section 3: 1842 Gallery







Roof: North side crudely detailed roof light

Roof: North side damaged roof slates






 ${\bf Roof: South \ side, \ Rooflight \ badly \ damaged}$



West elevation, Low wall could do to have a gruard rail 1.1m high



Elevation: south



South. Further stone replacement would be desirable to lower wall.




South. Door in poor order






East. Window in poor order. Elevation needs limewashing

Schedule section 4: Lancashire boilers and Control Room





Lancashire boilers. Replace eaves gutters





Lancashire boiler - Switch room general view


Lancashire boiler - Switch room door to replace





Control room: Front rainwater goods are still the old timber gutters and a poorly fixed plastic downpipe.






NATIONAL COAL MINING MUSEUM. Small Works Photo reference sheets

Control room: mortar loss from ridge





Control room: Access door in poor condition


Schedule section 5: lamp room and screens building


















Screens: Roof over lamp room waiting area is very badly made. The sheets do not extend to the edge and the RWP from the upper roof soaks the gap






Screens: Underside view of above showing soaked and rotten timbers





General views of garages





Door of north garage in poor order.





 $\begin{tabular}{ll} NATIONAL COAL MINING MUSEUM. Small Works \\ Photo reference sheets \\ \end{tabular}$

Screens: high level window by the top of the gantry in poor order.





Modern Workshop / entrance to underground tour: Brickwork on north face almost complete loss of mortar



Lamp room south – 2no small square windows need replacing



Lamp room south – 2no long windows need replacing

