


WATER FOR GROWTH



Glynn Weir Photo Record

Pre-works/ Baseline Photos – Spring 2019




Photo 1: View upstream from left hand bank in low spring flow



Photo 2: View downstream from left hand bank in low spring flows

WATER FOR GROWTH



Glynn Weir Photo Record




Photo 3: View downstream - weir crest, low flow notch with leaf control structure to left



Photo 4: Aerial view of leaf control structure

WATER FOR GROWTH



Glynn Weir Photo Record



Photo 5: View upstream – weir glacia and low flow notch





Photo 6: Upstream view – damage on weir glacia

WATER FOR GROWTH



Glynn Weir Photo Record



Photo 7: Leat control structure