

Homes & Communities Agency (Bristol)

Northfleet, Crete Hall Road, Old Sun
Wharf, Gravesend, DA11 9AA

WYG Asbestos Demolition Survey Report

20 Mar 2015





Document Control

Project:
Client: Homes & Communities Agency (Bristol)
Job Number: J017397 / A090070-17
File Origin: 15

Document Checking:

Lead Surveyor: Mark Thomson
Senior Asbestos Consultant

Signed:

A handwritten signature in black ink, appearing to be 'M. Thomson', written over a horizontal line.

Prepared by: Mark Thomson
Senior Asbestos Consultant

Signed:

A handwritten signature in black ink, appearing to be 'M. Thomson', written over a horizontal line.

Approved by: Duncan Gibb
Associate Director

Signed:

A handwritten signature in black ink, appearing to be 'D. Gibb', written over a horizontal line.

| Issue | Date | Status |
|-------|-------------|--------|
| 1 | 20 Mar 2015 | |



Contents Page

0.0 Executive Summary..... 4

1.0 Introduction..... 5

2.0 Site Details..... 6

3.0 Survey Methodology..... 8

4.0 Survey Conditions..... 9

5.0 Asbestos Register..... 11

6.0 Recommendations..... 13

7.0 Glossary of Terms..... 17

8.0 References..... 18

Table Contents

Table 1 Areas of No Access..... 10

Appendix Contents

- Appendix A – Report Conditions for WYG Asbestos Demolition Survey
- Appendix B – Inspection Reports
- Appendix C – Material Risk Assessment Criteria
- Appendix D – Site Sketches
- Appendix E – Analysis Certificates



0.0 Executive Summary

| | |
|--|---|
| Site Address | The site address is Northfleet, Crete Hall Road, Old Sun Wharf, Gravesend DA11 9AA. |
| General Site Description | The site comprises 1 building. The site is a derelict factory. |
| Date and type of survey undertaken | <p>It is understood from the client that the survey was undertaken to provide a higher level of information to demolition contractors. A WYG Asbestos Demolition Survey was undertaken in accordance with HSG 264 Asbestos; The Survey Guide.</p> <p>The WYG Asbestos Demolition Survey was conducted on the 26 Feb 2015 by Mark Thomson and Duncan Gibb of WYG Environment Planning Transport Ltd.</p> <p>Sample analysis techniques were UKAS accredited in accordance with HSG 248 – Asbestos: The Analysts Guide for Sampling, Analysis and Clearance Procedures, 2005.</p> |
| Summary of Asbestos Containing Materials Identified | <p>A total of 15 no. samples were analysed following the survey. Of these, 4 no. samples were confirmed as asbestos. This led to the identification of 7 no. items. These include the following material types:</p> <ul style="list-style-type: none">• Asbestos Cement• Asbestos Insulation/Coating• Asbestos Textiles/Paper |
| Areas of No Access | <p>Every effort was made to access all areas of the site. Inaccessible areas and limitations of a WYG Asbestos Demolition Survey are detailed in Sections 4.2 and 4.3 of this report. Inaccessible areas should be presumed to contain asbestos containing materials (ACM's) until such time as an inspection can be made that proves otherwise, as required by the Control of Asbestos Regulations (CAR) 2012.</p> |
| <p>This sheet is intended to provide a summary only of the asbestos survey findings. It does not provide a definitive engineering analysis for the purposes of costing or construction and is subject to the limitations of this WYG Asbestos Demolition Survey.</p> | |



1.0 Introduction

1.1 General

WYG Environment Planning Transport Ltd (WYG) was commissioned by Homes & Communities Agency (Bristol) to undertake a WYG Asbestos Demolition survey at the Northfleet, Crete Hall Road, Old Sun Wharf, Gravesend DA11 9AA.

Mark Thomson and Duncan Gibb undertook the survey on 26 Feb 2015.

1.2 Objectives

A WYG Asbestos Demolition survey was undertaken at the site in order to meet the following objectives:

- To identify the presence, location and condition of reasonably accessible asbestos containing materials (ACM's).
- To produce a report to identify areas of confirmed and suspected asbestos and to provide an indication as to their location, condition and extent.

1.3 Report Conditions

This report has been prepared in accordance with the accepted service details, terms and conditions of our accepted proposal letter Q017364. The report is further subject to the conditions detailed in Appendix A.

2.0 Site Details

2.1 Location

The site address is Northfleet, Crete Hall Road, Old Sun Wharf, Gravesend.

2.2 Buildings

The site comprises 1 building. The site is a derelict factory.

Specific areas included within the survey scope are as follows:

- Main building/Ground Floor/01 Side entrance
- Main building/Ground Floor/02 Store
- Main building/Ground Floor/03 Warehouse
- Main building/Ground Floor/04 Undercroft store
- Main building/Ground Floor/05 Undercroft store
- Main building/Ground Floor/06 Undercroft store
- Main building/Ground Floor/07 Undercroft store
- Main building/Ground Floor/08 Undercroft store
- Main building/Ground Floor/09 Corridor
- Main building/Ground Floor/010 Office
- Main building/Ground Floor/011 Foyer
- Main building/Ground Floor/012 Office
- Main building/Ground Floor/013 Office
- Main building/Ground Floor/014 Office
- Main building/Ground Floor/015 WC
- Main building/1st Floor/01 Stairwell
- Main building/1st Floor/02 Office
- Main building/1st Floor/03 Office
- Main building/1st Floor/04 Office
- Main building/1st Floor/05 Office
- Main building/1st Floor/06 Office
- Main building/1st Floor/18 Cloakroom
- Main building/1st Floor/07 Female W.C.
- Main building/1st Floor/08 Male W.C.
- Main building/1st Floor/09 Workshop
- Main building/1st Floor/10 Office
- Main building/1st Floor/11 Office
- Main building/1st Floor/12 Store
- Main building/1st Floor/16 Store
- Main building/1st Floor/013 Corridor
- Main building/1st Floor/14 Store
- Main building/1st Floor/15 Store
- Main building/1st Floor/17 Male W.C.
- Main building/2nd Floor/01 Stairwell
- Main building/2nd Floor/02 Office



- Main building/2nd Floor/03 Office
- Main building/2nd Floor/04 Office
- Main building/2nd Floor/05 Office
- Main building/2nd Floor/06 Office
- Main building/2nd Floor/07 Kitchen
- Main building/External/01 Flat roof
- Main building/External/02 External areas
- Main building/3rd Floor/01 and 02 Office
- Main building/4th Floor/01 Tank room



3.0 Survey Methodology

A WYG Asbestos Demolition survey, using the methodology set out in HSG 264 was undertaken. Each accessible area was inspected to locate materials presumed or strongly presumed to contain asbestos, all of which must be removed prior to demolition. Photographs of each sample location were taken, however where similar materials were identified these are referenced to similar homogeneous materials.

Each sample is assessed using a material assessment algorithm, which assigns a score of risk to each individual ACM based the following criteria:

- Product Type;
- Extent of Damage or Deterioration;
- Surface Treatment; and
- Asbestos Type

Each criterion has various scores and when all the scores for each are added together a value of risk is generated for the material. This is only a requirement of HSG 264 for Management Surveys; however, the algorithm values have been applied during this survey as we understand that contractors may visit the site prior to demolition. All samples were analysed by a UKAS accredited laboratory using Polarised Light Microscopy and Dispersion Staining techniques in accordance with HSG 248.

If the client has determined priority scoring for the identified ACM's, the combined material and priority assessment results can be used to establish the priority for those ACMs needing remedial action and the type of action that will be taken. There are various remedial options available: in many cases the ACMs can be protected or enclosed, sealed or encapsulated, or repaired. These options should be considered first. Where such actions are not practical, ACMs should be removed. Further information on risk assessments and management of asbestos is available in A comprehensive guide to managing asbestos in premises.

Sampling of suspect materials is completed in accordance with HSG264 and accreditation by UKAS to ISO17020. By its nature, sampling building materials may include a limited damage and WYG accept no responsibility for making good such areas, unless agreed in writing in advance of the survey.



4.0 Survey Conditions

4.1 Access Constraints

All areas within the scope of works were assessed (unless stated in Section 4.3) for the presence of ACM's and where ACM's were presumed and/or strongly presumed samples were taken. These presumptions are based upon surveyors experience associated with identification of a particular material.

4.2 Survey Limitations

Whilst the surveyors made every effort, WYG cannot guarantee that all asbestos containing materials have been identified, or that survey results are definitive. Specific areas of the site where suitable access was not available are recorded in Section 4.3 of this document.

Features that generally fall outside the scope of a WYG Asbestos Demolition survey include:

- Within solid floor voids (e.g. Concrete Slab), where no inspection hatch is present.
- Areas behind or above suspected asbestos containing materials¹
- Within solid concrete floors where asbestos shuttering may have been used
- Within confined spaces etc. where reasonable access is unavailable²
- Within live plant or electrical apparatus
- Beneath lagging or cladding of live pipes where a burn hazard may be present
- Concealed pipe runs, where reasonable access is unavailable
- Areas that are considered to present a significant Health & Safety risk.
- Within live plant or electrical apparatus
- Areas where access may involve damaging the fabric of the building

¹ Areas behind or above suspected asbestos containing materials are required to be inspected by HSG264. Where such areas could not be identified prior to the commission of the survey, a provisional sum should have been allowed for by the client to enable the surveyor to return to site with a licensed asbestos contractor in order to gain access. Such access may also necessitate 14-day (ASB5) notification to the HSE and may require concurrent air monitoring to be carried out. Should this type of access have been required, we liaises and sought agreement from the project team before commencing beyond the agreed project scope.

² Where access is restricted due to confined space or other health & safety concerns, these areas will be detailed in the report and recommendations given for the most appropriate means of investigation, and if necessary, any additional costs which would be entailed. A strategy of using representative samples of suspected asbestos materials has been used to minimise the number of samples taken to a practical level and keep to a minimum the disturbance of potential asbestos containing materials at the site. Because of this strategy the results of the survey should be interpreted such that all visually similar materials in the same area must be assumed to be composed of the same material until proven otherwise.

In accordance with The Control of Asbestos Regulations 2012, it must be assumed that materials visually assessed as asbestos containing materials contain amphibole asbestos fibres (i.e. Amosite and Crocidolite), unless sampled to prove otherwise.

4.3 Areas of No Access

Table 1 Areas of No Access

| Room Number | Room Name | Extent of Access Limitation, Including Reason |
|-------------|-----------|---|
| 012 | Office | Limited access due to stored materials |
| 07 | Kitchen | Limited access due to stored materials |

4.4 Survey Specific Notes

There is always a possibility that asbestos materials other than those highlighted by this report are present in those areas not accessed fully at the time of the survey.

Inaccessible areas should be presumed to contain amphibole asbestos and appropriate management planning should be implemented in order to control access and maintenance activities to these areas until such a time as they can be accessed and the presence or absence of asbestos containing materials can be confirmed.

A strategy of using representative samples of suspected asbestos materials has been used to minimise the number of samples taken to a practical level and keep to a minimum the disturbance of potential asbestos containing materials. Because of this strategy the results of the survey should be interpreted such that all visually similar materials in the same area must be assumed to be composed of the same material until proven otherwise.

In accordance with The Control of Asbestos Regulations 2012, it must be assumed that materials visually assessed as asbestos containing materials contain amphibole asbestos fibres (i.e. Amosite and Crocidolite), unless strongly presumed otherwise or sampled to prove otherwise.

Asbestos products and non-asbestos products in some areas of the building are located in close proximity to each other. Care must be taken when removing the asbestos in order that contamination of the non-asbestos materials is not caused, as this will increase disposal costs.

Material assessments have been undertaken on the various items inspected. These assessments are carried out according to the material assessment algorithm appended to this report, which is based on the assessment criteria in HSG 264.

5.0 Asbestos Register

| Inspection Number | Area | Feature | Material Type – (Friability) | Asbestos Fibre | Material Assessment Score | Priority Assessment Score | Total Assessment Score | Sample Number | Recommendations |
|-------------------|--|---|------------------------------------|-------------------|---------------------------|---------------------------|------------------------|---------------|----------------------------------|
| 6 | Main building, Ground Floor, Undercroft store (08) | Cement panel | Asbestos Cement (Low) | (1) Chrysotile | 4 | N/A | N/A | BE001311 | Remove if likely to be disturbed |
| 9 | Main building, Ground Floor, Office (010) | Debris to wall | Asbestos Insulation/Coating (High) | (2) Amosite | 10 | N/A | N/A | BE001314 | Restrict access and remove |
| 10 | Main building, Ground Floor, Office (010) | Insulation to pipework in ceiling void (as sample BE001314) | Asbestos Insulation/Coating (High) | (2) Amosite | 10 | N/A | N/A | BE001314 | Restrict access and remove |
| 11 | Main building, Ground Floor, Office (010) | Debris to floor | Asbestos Insulation/Coating (High) | (2) Amosite | 11 | N/A | N/A | BE001315 | Restrict access and remove |
| 37 | Main building, External, Flat roof (01) | Cement tiles | Asbestos Cement (Low) | (1) Chrysotile | 4 | N/A | N/A | BE001321 | Remove if likely to be disturbed |
| 38 | Main building, External, Flat roof (01) | Presumed textiles to roof lights | Asbestos Textiles/Paper (Medium) | (1) Chrysotile | 5 | N/A | N/A | - | Remove if likely to be disturbed |



| Inspection Number | Area | Feature | Material Type – (Friability) | Asbestos Fibre | Material Assessment Score | Priority Assessment Score | Total Assessment Score | Sample Number | Recommendations |
|-------------------|--|--------------------------------|------------------------------------|-------------------|---------------------------|---------------------------|------------------------|---------------|----------------------------|
| 48 | Main building, 4th Floor, Tank room (01) | Debris to pipe, wall and floor | Asbestos Insulation/Coating (High) | (1) Chrysotile | 10 | N/A | N/A | - | Restrict access and remove |

6.0 Recommendations

6.1 Summary

Survey inspection reports detail the ACM identified and its approximate extent, these reports are contained within Appendix B of this report. The asbestos register, Section 5.0 of this report summarises asbestos containing materials and presumed asbestos materials identified during the course of the survey.

6.2 Further Investigation

This WYG Demolition survey was carried out to a specific scope of works as per section 2.2 and was subject to the general limitations described in section 4.2 and the specific limitations described in section 4.3. There is a possibility that asbestos material may be present in those areas that were concealed or inaccessible at the time of the survey or otherwise fell outside the scope of this investigation. Prior to demolition or any activity that disturbs the fabric of the building in these excluded areas it is recommended that they are also subjected to a fully intrusive WYG Demolition asbestos survey, under controlled conditions where appropriate.

As any Demolition asbestos survey is limited by issues of practical access, all areas of the site should still be approached with caution during intrusive works. We suggest that the contractor has an appropriate procedure within his method statement such that if suspected asbestos materials are encountered, a sample can be taken to confirm the nature of the material prior to any work in that area.

6.3 General

If asbestos removal is required, it is recommended that a site-specific asbestos removal specification and method statements be produced in order to facilitate any asbestos removal works.

The waste generated from asbestos removal should be notified and disposed of in accordance with the Hazardous Waste (England & Wales) Regulations 2005, Amended 2009.

The contractor must ensure that adequate Duty of Care provisions are put in place for the transportation and disposal of wastes from the site in line with the obligations of the Environmental Protection Act 1990.

In accordance with Regulation 4 of The Control of Asbestos Regulations 2012, it is advised that a management plan is produced and a duty holder be appointed to coordinate and oversee the management of the asbestos at the site.

Where asbestos insulation materials are removed, the building manager should ensure that non-asbestos replacement materials are installed, to maintain fire proofing.

If asbestos containing materials (ACM's) are to remain in-situ across the premises, CAR 2012 requires a Duty Holder be appointed/identified, who will be responsible for producing and implementing an Asbestos Management Plan, as defined by HSG 227.

Due to the nature of a WYG Asbestos Demolition Survey there is always the possibility of asbestos being present within inaccessible areas and those areas outlined within Sections 4.2 and 4.3 of the report as outside the scope of this type of survey. If any work is to be carried out within these areas then materials encountered should be presumed to



contain asbestos unless there is strong evidence for a reasoned argument that the material does not contain asbestos. This can be achieved by taking a sample and having subsequent analysis undertaken on the sample in accordance with HSG 248.

Prior to demolition or any other works that might disturb the asbestos materials identified, they should be removed. It is recommended that a site-specific method statement be produced in order to facilitate the removal of the asbestos. It is advised that a competent person be appointed to coordinate and oversee the management of asbestos at the site.

The detailed extent of asbestos materials presented in this report are approximate values only and should not be used in isolation to prepare quotations for asbestos repair or removal. It is recommended that any asbestos repair or removal be evaluated by an asbestos removal contractor, who should attend site to confirm the extent of asbestos.

6.4 Asbestos Management Plan (AMP)

The Control of Asbestos Regulations 2012 stipulates under Regulation 4, that persons responsible by virtue of ownership, contract or tenancy of a non-domestic premise are responsible for undertaking a suitable and sufficient assessment for the presence of asbestos materials within those premises and implement an appropriate Asbestos Management Plan (AMP).

Areas highlighted in Sections 4.2 and 4.3 as areas of 'no access' should be presumed to contain amphibole asbestos and appropriate management planning should be implemented in order to control access and maintenance activities to these areas until such a time as they can be accessed and the presence or absence of asbestos containing materials can be confirmed.

Asbestos materials were encountered in the survey as detailed in Section 5.0. The AMP should stipulate the requirements for working in these areas identified as containing asbestos as well as the areas of 'no access' as stated in Sections 4.2 and 4.3. For example the requirements for working in these areas may be a permit to work system, appropriate risk assessments or by other means to ensure people are not exposed to asbestos.

The Approved Code of Practice L143: Managing & Working With Asbestos (*Control of Asbestos Regulations 2012*) outlines the procedures that should be followed when developing and implementing an AMP.

In accordance with Regulation 4 of The Control of Asbestos Regulations 2012, it is advised that a 'Duty Holder' be appointed to coordinate and oversee the management of asbestos at the site. The most appropriate person to be considered to be a Duty Holder is the person responsible for coordinating maintenance activities for the premises.

The Duty Holder has the responsibility to incorporate the results of this survey into an AMP for the building. The Duty Holder must ensure that an appropriate Priority Assessment is undertaken as detailed in HSG 227: *A Comprehensive Guide to Managing Asbestos in Premises*, taking into account factors such as:

- Normal Occupant Activity – assessment based upon the interaction of occupants and the area being assessed.
- Likelihood of disturbance – assessment based upon location of asbestos, its accessibility and quantity of material that has the potential to be disturbed.
- Human Exposure Potential – assessment based upon number of occupants, frequency of use and duration of use.
- Maintenance Activity – assessment based upon type of maintenance activity and frequency.

Combining the Material Risk Assessment with the Priority Assessment provides an overall assessment with respect to ACM's present within a building. This overall assessment will then determine the management requirements for the building.



WYG can assist in the process of risk assessment to further develop the AMP in accordance with L143 and HSG 227. Priority Assessment is outside the scope of our UKAS accreditation.

6.5 MMMF

A number of materials associated with Machine Made Mineral Fibre (MMMF) are present with areas in the building (e.g. within ceiling voids). These materials are covered by the COSHH regulations and persons working on or near these materials should undertake sufficient risk assessments and/or wear appropriate Personal Protective Equipment.

6.6 Fire Protection

Where asbestos insulation materials are removed, the building manager should ensure that non-asbestos replacement materials are installed, to maintain fire proofing.

If fire-rated materials are removed there may be a requirement to review and revise the site Fire Risk Assessment. WYG has a dedicated Fire Risk Assessment team, who would be pleased to provide further guidance in this respect required.

6.7 Other Safety Management and Compliance Services

We provide a range of safety management and compliance services to a variety of clients across the public and private sector. Services include:

Health and Safety Management

- Development and implementation of safety management systems such as OHSAS 18001, BS8800, HSG65
- Advice on preparing effective health and safety policies, procedures and systems of work
- Risk assessments (including workplace and work activity, manual handling, display screen equipment (DSE), CoSHH etc)
- Advice on setting key performance indicators for driving improvements in safety performance
- Accident and incident investigation
- Independent compliance audits
- Occupational exposure monitoring – dusts, fumes, vapours, etc
- Noise monitoring and noise control
- Indoor air quality and working environment investigation.

Legionella Assessment

- L8 compliant Legionella risk assessments
- Legionella awareness seminars and training
- Independent compliance audits

CDM Co-ordinator Services

- Full proactive CDM co-ordinator service on notifiable projects of all sizes
- Client's construction health and safety advisor for non-notifiable projects
- Design of health and safety risk workshops
- CDM regulations compliance audits of all duty holders.



Fire and Explosion

- Regulatory reform (fire safety) order compliant fire risk assessments
- Expert advice on means of escape, structural protection, automatic detection and fire fighting systems
- Liaison with enforcing authorities
- Dangerous substances and explosive atmospheres regulations (DSEAR) risk assessment

Training

- Institution of occupational safety and health accredited courses:
- Directing safely
- Managing safely
- Working safely
- Executive update – key health and safety legislative requirements
- Health & safety responsibilities of line managers
- H&S risk assessments – a practical approach
- DSE safety and user awareness
- Handling loads, preventing injury – good manual handling practice
- COSHH assessment, assessor training
- CDM Regulations 2007 – introduction
- CDM Regulations 2007 for designers
- Asbestos awareness & training for non-licensable activities.

Asbestos Consultancy

- Asbestos surveys (management, refurbishment & demolition surveys)
- Removal specifications
- On-site inspection and monitoring of works
- Asbestos management plans
- Completion and validation reporting
- Asbestos awareness seminars and training
- Expert witness



7.0 Glossary of Terms

| | |
|-------|--|
| ACM | Asbestos Containing Material |
| AIB | Asbestos Insulating Board |
| AMP | Asbestos Management Plan |
| CAR | Control of Asbestos Regulations |
| EA | Environment Agency |
| HSE | Health and Safety Executive |
| HSG | Health and Safety Guidance |
| MMMF | Machine Made Mineral Fibre |
| NADIS | No Asbestos Detected in Sample |
| UKAS | United Kingdom Accreditation Service |
| WYG | WYG Environment Planning Transport Ltd |



8.0 References

- HSG 264 Asbestos: The Survey Guide, 2nd Edition, 2012
- HSG 248 Asbestos: The Analysts Guide for Sampling, Analysis and Clearance Procedures, 2005.
- CAR 2012 Control of Asbestos Regulations 2012, April 2012.



Appendices



Appendix A – Report Conditions for WYG Asbestos Demolition Survey



WYG ENVIRONMENT PLANNING TRANSPORT LTD

This report is produced solely for the benefit of Homes & Communities Agency (Bristol), no account is taken for any reliance placed on it by any other party unless specifically agreed in writing otherwise.

This report refers, within the limitations stated, to the condition of the site at the time of the inspections. No warranty is given as to the possibility of future changes in the condition of the site.

This report is based on a site inspection in the accessed areas as noted, the physical investigation as detailed, information supplied by those parties referenced in the text. Some of the opinions are based on unconfirmed data and information and are presented as the best that can be obtained without further extensive dismantling and disturbance. The test results that are available can only be regarded as a limited but likely representative sample assessed against current guidelines. The impact of our assessment on other aspects of the development requires evaluation by other involved parties. The possibility of the presence of asbestos, perhaps in higher concentrations, elsewhere on the site, cannot be discounted.

Whilst the findings detailed within this report reflect our best assessment, because there are no exact UK definitions of these matters, being subject to risk analysis, we are unable to give categoric assurances that they will be accepted by authorities or funds without question as such bodies have unpublished, more stringent objectives. This report is prepared and written for the purposed uses stated in the report and should not be used in a different context without reference to WYG. In time improved practices or amended legislation may necessitate a re-assessment.

The report is limited to those aspects specifically reported on and is necessarily restricted and no liability is accepted for any other aspect. The opinions expressed cannot be absolute due to the limitations of time and resources accepted by the agreed brief and the possibility of unrecorded previous use and abuse of the site and adjacent sites. The report concentrates on the site as defined in the report.



Appendix B – Inspection Reports

Priority Assessments have not been conducted as part of this survey.

| | | | |
|--|--|--|----------------------------------|
| Inspection Number | | Reference Number: | N/A |
| Inspection / Sample | Visual Inspection | Inspection Cross Reference / Visual I.D. | Asbestos Inaccessible (Presumed) |
|  | | | |
| Notes | Limited access due to stored materials | | |

| | |
|---------------|--------------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 012 Office |
| Feature | Lilimited access to room |
| Product Type | |
| Extent Amount | |

| | |
|----------------|------------------------------|
| Recommendation | Inspect Prior to Disturbance |
|----------------|------------------------------|

| | | |
|-------------------|--|---|
| Product Score | | 0 |
| Extent of Damage | | 0 |
| Surface Treatment | | 0 |
| Asbestos Type | | 0 |

| | |
|---------------------------|---|
| Material Assessment Score | 0 |
|---------------------------|---|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--|--|----------------------------------|
| Inspection Number | | Reference Number: | N/A |
| Inspection / Sample | Visual Inspection | Inspection Cross Reference / Visual I.D. | Asbestos Inaccessible (Presumed) |
|  | | | |
| Notes | Limitad access due to stored materials | | |

| | |
|---------------|--|
| Building | Main building |
| Floor Level | 2nd Floor |
| Area / Room | 07 Kitchen |
| Feature | Limitad access due to stored materials |
| Product Type | |
| Extent Amount | |

| | |
|----------------|------------------------------|
| Recommendation | Inspect Prior to Disturbance |
|----------------|------------------------------|

| | | |
|-------------------|--|---|
| Product Score | | 0 |
| Extent of Damage | | 0 |
| Surface Treatment | | 0 |
| Asbestos Type | | 0 |

| | |
|---------------------------|---|
| Material Assessment Score | 0 |
|---------------------------|---|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|-----------|
| Inspection Number | 1 | Reference Number: | BE001309 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | N.A.D.I.S |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 02 Store |
| Feature | Bitumen to parquet |
| Product Type | Well Bound Material |
| Extent Amount | 10 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|-----------|
| Inspection Number | 2 | Reference Number: | BE001310 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | N.A.D.I.S |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 03 Warehouse |
| Feature | Bitumen to parquet |
| Product Type | Well Bound Material |
| Extent Amount | 1000 m2 |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 3 | Reference Number: | As Sample BE001309 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 04 Undercroft store |
| Feature | Bitumen to parquet |
| Product Type | Well Bound Material |
| Extent Amount | 20 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 4 | Reference Number: | As Sample BE001309 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 05 Undercroft store |
| Feature | Bitumen to parquet |
| Product Type | Well Bound Material |
| Extent Amount | 20 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 5 | Reference Number: | As Sample BE001309 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 08 Undercroft store |
| Feature | Bitumen to parquet |
| Product Type | Well Bound Material |
| Extent Amount | 50 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|---------------------|
| Inspection Number | 6 | Reference Number: | BE001311 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | Asbestos Identified |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 08 Undercroft store |
| Feature | Cement panel |
| Product Type | Asbestos Cement |
| Extent Amount | 1 m ² |

| | |
|----------------|----------------------------------|
| Recommendation | Remove if likely to be disturbed |
|----------------|----------------------------------|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 1 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 1 |
| Surface Treatment | Enclosed sprays and lagging, Sealed AIB, asbestos cement, textured coating, gasket | 1 |
| Asbestos Type | Chrysotile | 1 |

| | |
|---------------------------|---|
| Material Assessment Score | 4 |
|---------------------------|---|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|-----------|
| Inspection Number | 7 | Reference Number: | BE001312 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | N.A.D.I.S |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 09 Corridor |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 20 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|-----------|
| Inspection Number | 8 | Reference Number: | BE001313 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | N.A.D.I.S |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 010 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 80 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|---------------------|
| Inspection Number | 9 | Reference Number: | BE001314 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | Asbestos Identified |
|  | | | |
| Notes | | | |

| | |
|---------------|-----------------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 010 Office |
| Feature | Debris to wall |
| Product Type | Asbestos Insulation/Coating |
| Extent Amount | 1 m ² |

| | |
|----------------|----------------------------|
| Recommendation | Restrict access and remove |
|----------------|----------------------------|

| | | |
|-------------------|--|---|
| Product Score | High Fibre Release - Thermal insulation (e.g. pipe and boiler lagging) sprayed asbestos, loose asbestos, asbestos mattresses and packing | 3 |
| Extent of Damage | Medium damage - significant breakage of materials or several small areas where material has been damaged revealing loose asbestos fibres | 2 |
| Surface Treatment | Unsealed lagging and sprays | 3 |
| Asbestos Type | Amosite | 2 |

| | |
|---------------------------|----|
| Material Assessment Score | 10 |
|---------------------------|----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 10 | Reference Number: | As Sample BE001314 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|--|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 010 Office |
| Feature | Insulation to pipework in ceiling void |
| Product Type | Asbestos Insulation/Coating |
| Extent Amount | 8 m |

| | |
|----------------|----------------------------|
| Recommendation | Restrict access and remove |
|----------------|----------------------------|

| | | |
|-------------------|--|---|
| Product Score | High Fibre Release - Thermal insulation (e.g. pipe and boiler lagging) sprayed asbestos, loose asbestos, asbestos mattresses and packing | 3 |
| Extent of Damage | Medium damage - significant breakage of materials or several small areas where material has been damaged revealing loose asbestos fibres | 2 |
| Surface Treatment | Unsealed lagging and sprays | 3 |
| Asbestos Type | Amosite | 2 |

| | |
|---------------------------|----|
| Material Assessment Score | 10 |
|---------------------------|----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | | |
|--|--------------|--|---------------------|
| Inspection Number | 11 | Reference Number: | BE001315 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | Asbestos Identified |
|  | | | |
| Notes | | | |

| | |
|---------------|-----------------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 010 Office |
| Feature | Debris to floor |
| Product Type | Asbestos Insulation/Coating |
| Extent Amount | < 1 m ² |

| | |
|----------------|----------------------------|
| Recommendation | Restrict access and remove |
|----------------|----------------------------|

| | | |
|-------------------|--|---|
| Product Score | High Fibre Release - Thermal insulation (e.g. pipe and boiler lagging) sprayed asbestos, loose asbestos, asbestos mattresses and packing | 3 |
| Extent of Damage | High damage - or delamination of materials, sprays and thermal insulation. Visible asbestos debris | 3 |
| Surface Treatment | Unsealed lagging and sprays | 3 |
| Asbestos Type | Amosite | 2 |

| | |
|---------------------------|----|
| Material Assessment Score | 11 |
|---------------------------|----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 12 | Reference Number: | As Sample BE001312 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 012 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 20 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 13 | Reference Number: | As Sample BE001312 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 013 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 20 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 14 | Reference Number: | As Sample BE001312 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | Ground Floor |
| Area / Room | 014 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 30 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|-----------|
| Inspection Number | 15 | Reference Number: | BE001316 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | N.A.D.I.S |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 02 Office |
| Feature | Window mastic |
| Product Type | Well Bound Material |
| Extent Amount | 10 lm |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 16 | Reference Number: | As Sample BE001316 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 03 Office |
| Feature | Window mastic |
| Product Type | Well Bound Material |
| Extent Amount | 10 lm |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 17 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 03 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 20 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 18 | Reference Number: | As Sample BE001316 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 04 Office |
| Feature | Window mastic |
| Product Type | Well Bound Material |
| Extent Amount | 30 lm |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 19 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 04 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 30 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|-----------|
| Inspection Number | 20 | Reference Number: | BE001320 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | N.A.D.I.S |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 05 Office |
| Feature | Window mastic |
| Product Type | Well Bound Material |
| Extent Amount | 60 lm |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 21 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 05 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 250 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 22 | Reference Number: | As Sample BE001309 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 06 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 20 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 23 | Reference Number: | As Sample BE001309 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 18 Cloakroom |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 10 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 24 | Reference Number: | As Sample BE001316 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 09 Workshop |
| Feature | Window mastic |
| Product Type | Well Bound Material |
| Extent Amount | 150 lm |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 25 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 09 Workshop |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 300 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 26 | Reference Number: | As Sample BE001316 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 10 Office |
| Feature | Window mastic |
| Product Type | Well Bound Material |
| Extent Amount | 20 lm |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 27 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 10 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 40 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|---------------------|---------------------|--|--------------------|
| Inspection Number | 28 | Reference Number: | As Sample BE001316 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |



| | |
|-------|--|
| Notes | |
|-------|--|

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 11 Office |
| Feature | Window mastic |
| Product Type | Well Bound Material |
| Extent Amount | 20 lm |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 29 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 11 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 30 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|-----------|
| Inspection Number | 30 | Reference Number: | BE001318 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | N.A.D.I.S |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 12 Store |
| Feature | Bitumen to parquet |
| Product Type | Well Bound Material |
| Extent Amount | 30 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|-----------|
| Inspection Number | 31 | Reference Number: | BE001319 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | N.A.D.I.S |
|  | | | |
| Notes | | | |

| | |
|---------------|-------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 12 Store |
| Feature | Paper within door |
| Product Type | Textiles/Paper |
| Extent Amount | 2 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|--|---|
| Product Score | Medium Fibre Release - Asbestos insulating board, mill board, other low density insulation board, asbestos textiles, gaskets, rope and woven textiles, asbestos paper and felt | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Enclosed sprays and lagging, Sealed AIB, asbestos cement, textured coating, gasket | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 32 | Reference Number: | As Sample BE001318 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 16 Store |
| Feature | Bitumen to parquet |
| Product Type | Well Bound Material |
| Extent Amount | 10 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 33 | Reference Number: | As Sample BE001318 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 14 Store |
| Feature | Bitumen to parquet |
| Product Type | Well Bound Material |
| Extent Amount | 30 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 34 | Reference Number: | As Sample BE001318 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 15 Store |
| Feature | Bitumen to parquet |
| Product Type | Well Bound Material |
| Extent Amount | 30 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|---------------------|---------------------|--|--------------------|
| Inspection Number | 35 | Reference Number: | As Sample BE001320 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |



| | |
|-------|--|
| Notes | |
|-------|--|

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 1st Floor |
| Area / Room | 17 Male W.C. |
| Feature | Window mastic |
| Product Type | Well Bound Material |
| Extent Amount | 10 lm |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 36 | Reference Number: | As Sample BE001320 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|-----------------------------|
| Building | Main building |
| Floor Level | 2nd Floor |
| Area / Room | 01 Stairwell |
| Feature | Window mastic to all levels |
| Product Type | Well Bound Material |
| Extent Amount | 40 lm |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|---------------------|
| Inspection Number | 37 | Reference Number: | BE001321 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | Asbestos Identified |
|  | | | |
| Notes | | | |

| | |
|---------------|-----------------|
| Building | Main building |
| Floor Level | External |
| Area / Room | 01 Flat roof |
| Feature | Cement tiles |
| Product Type | Asbestos Cement |
| Extent Amount | 2 no. |

| | |
|----------------|----------------------------------|
| Recommendation | Remove if likely to be disturbed |
|----------------|----------------------------------|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 1 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 1 |
| Surface Treatment | Enclosed sprays and lagging, Sealed AIB, asbestos cement, textured coating, gasket | 1 |
| Asbestos Type | Chrysotile | 1 |

| | |
|---------------------------|---|
| Material Assessment Score | 4 |
|---------------------------|---|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|-------------------|--|-------------------|
| Inspection Number | 38 | Reference Number: | N/A |
| Inspection / Sample | Visual Inspection | Inspection Cross Reference / Visual I.D. | Asbestos Presumed |
|  | | | |
| Notes | | | |

| | |
|---------------|----------------------------------|
| Building | Main building |
| Floor Level | External |
| Area / Room | 01 Flat roof |
| Feature | Presumed textiles to roof lights |
| Product Type | Asbestos Textiles/Paper |
| Extent Amount | 40 m2 |

| | |
|----------------|----------------------------------|
| Recommendation | Remove if likely to be disturbed |
|----------------|----------------------------------|

| | | |
|-------------------|--|---|
| Product Score | Medium Fibre Release - Asbestos insulating board, mill board, other low density insulation board, asbestos textiles, gaskets, rope and woven textiles, asbestos paper and felt | 2 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 1 |
| Surface Treatment | Enclosed sprays and lagging, Sealed AIB, asbestos cement, textured coating, gasket | 1 |
| Asbestos Type | Chrysotile | 1 |

| | |
|---------------------------|---|
| Material Assessment Score | 5 |
|---------------------------|---|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|-----------|
| Inspection Number | 39 | Reference Number: | BE001322 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | N.A.D.I.S |
|  | | | |
| Notes | | | |

| | |
|---------------|----------------------------|
| Building | Main building |
| Floor Level | External |
| Area / Room | 01 Flat roof |
| Feature | Bitumen to pipe insulation |
| Product Type | Well Bound Material |
| Extent Amount | 20 lm |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 40 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 2nd Floor |
| Area / Room | 02 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 16 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 41 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 2nd Floor |
| Area / Room | 03 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 30 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 42 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 2nd Floor |
| Area / Room | 04 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 20 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 43 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 2nd Floor |
| Area / Room | 05 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 20 |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 44 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 2nd Floor |
| Area / Room | 06 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 20 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 45 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 2nd Floor |
| Area / Room | 07 Kitchen |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 10 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---------------------|--|--------------------|
| Inspection Number | 46 | Reference Number: | As Sample BE001310 |
| Inspection / Sample | Visually similar to | Inspection Cross Reference / Visual I.D. | As Sample |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | 3rd Floor |
| Area / Room | 01 and 02 Office |
| Feature | Bitumen to floor |
| Product Type | Well Bound Material |
| Extent Amount | 20 m ² |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|-----------|
| Inspection Number | 47 | Reference Number: | BE001323 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | N.A.D.I.S |
|  | | | |
| Notes | | | |

| | |
|---------------|--------------------------------|
| Building | Main building |
| Floor Level | 3rd Floor |
| Area / Room | 01 and 02 Office |
| Feature | Debris to pipe, wall and floor |
| Product Type | Dust/Debris |
| Extent Amount | 2 m |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|--|---|
| Product Score | High Fibre Release - Thermal insulation (e.g. pipe and boiler lagging) sprayed asbestos, loose asbestos, asbestos mattresses and packing | 0 |
| Extent of Damage | High damage - or delamination of materials, sprays and thermal insulation. Visible asbestos debris | 0 |
| Surface Treatment | Unsealed lagging and sprays | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|


| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|---|--|-------------------|
| Inspection Number | 48 | Reference Number: | N/A |
| Inspection / Sample | Visual Inspection | Inspection Cross Reference / Visual I.D. | Asbestos Presumed |
|  | | | |
| Notes | Chrysotile identified in 2012 Management Survey - presume still present | | |

| | |
|---------------|--------------------------------|
| Building | Main building |
| Floor Level | 4th Floor |
| Area / Room | 01 Tank room |
| Feature | Debris to pipe, wall and floor |
| Product Type | Asbestos Insulation/Coating |
| Extent Amount | 2 m ² |

| | |
|----------------|----------------------------|
| Recommendation | Restrict access and remove |
|----------------|----------------------------|

| | | |
|-------------------|--|---|
| Product Score | High Fibre Release - Thermal insulation (e.g. pipe and boiler lagging) sprayed asbestos, loose asbestos, asbestos mattresses and packing | 3 |
| Extent of Damage | High damage - or delamination of materials, sprays and thermal insulation. Visible asbestos debris | 3 |
| Surface Treatment | Unsealed lagging and sprays | 3 |
| Asbestos Type | Chrysotile | 1 |

| | |
|---------------------------|----|
| Material Assessment Score | 10 |
|---------------------------|----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | N/A | |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | N/A | |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|

| | | | |
|--|--------------|--|-----------|
| Inspection Number | 49 | Reference Number: | BE001325 |
| Inspection / Sample | Sample taken | Inspection Cross Reference / Visual I.D. | N.A.D.I.S |
|  | | | |
| Notes | | | |

| | |
|---------------|---------------------|
| Building | Main building |
| Floor Level | External |
| Area / Room | 02 External areas |
| Feature | Damp proof course |
| Product Type | Well Bound Material |
| Extent Amount | 300 m |

| | |
|----------------|--|
| Recommendation | |
|----------------|--|

| | | |
|-------------------|---|---|
| Product Score | Low Fibre Release - Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement, etc.) | 0 |
| Extent of Damage | Low damage - a few scratches or surface marks; broken edges on boards, tiles etc. | 0 |
| Surface Treatment | Reinforced plastics, resins, vinyl tiles, well bound materials, bitumen adhesives, damp proof course | 0 |
| Asbestos Type | No Asbestos Detected | 0 |

| | |
|---------------------------|-----|
| Material Assessment Score | N/A |
|---------------------------|-----|

| | |
|----------------------|-----|
| Total Material Score | N/A |
|----------------------|-----|

| | | |
|--------------------------|-----|-----|
| Normal occupant activity | N/A | N/A |
|--------------------------|-----|-----|

| | | |
|---------------------------|-----|-----|
| Likelihood of disturbance | N/A | N/A |
| Accessibility | N/A | N/A |
| Extent / Amount | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------|-----|-----|
| Number of occupants | N/A | N/A |
| Frequency of use of area | N/A | N/A |
| Average time area is in use | N/A | N/A |
| Average | | N/A |

| | | |
|-----------------------------------|-----|-----|
| Type of maintenance activity | N/A | N/A |
| Frequency of maintenance activity | N/A | N/A |
| Average | | N/A |

| | |
|---------------------------|-----|
| Priority Assessment Score | N/A |
|---------------------------|-----|



Appendix C – Risk Assessment Criteria

Material Risk Assessment

Product Type

| SAMPLE VARIABLE | SCORE | EXAMPLES OF SCORE VARIABLES |
|---------------------------------------|-------|--|
| Product type (or debris from product) | 1 | Asbestos reinforced composites (plastics, resins, mastics, roofing felts, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc) |
| | 2 | Asbestos insulating board (AIB), mill boards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper and felt |
| | 3 | Thermal insulation (e.g. pipe and boiler lagging) sprayed asbestos, loose asbestos, asbestos mattresses and packing. |

Extent of Damage

| SAMPLE VARIABLE | SCORE | EXAMPLES OF SCORE VARIABLES |
|----------------------------------|-------|--|
| Extent of damage / deterioration | 0 | Good condition: no visible damage |
| | 1 | Low damage: a few scratches or surface marks, broken edges on boards, tiles etc. |
| | 2 | Medium damage: significant breakage of material or several small areas where material has been damaged revealing loose asbestos fibres |
| | 3 | High damage or de-lamination: of materials, sprays and thermal insulation. Visible asbestos debris |

Surface Treatment


| SAMPLE VARIABLE | SCORE | EXAMPLES OF SCORE VARIABLES |
|-------------------|-------|--|
| Surface treatment | 0 | Composite materials containing asbestos: reinforced plastics, resins, vinyl tiles, asbestos cement (with exposed face painted or encapsulated) |
| | 1 | Enclosed sprays and lagging, AIB with (exposed face painted or encapsulated), unsealed asbestos cement sheets etc. |
| | 2 | Unsealed AIB or encapsulated lagging and sprays |
| | 3 | Unsealed lagging and sprays |

Asbestos Type


| SAMPLE VARIABLE | SCORE | EXAMPLES OF SCORE VARIABLES |
|-----------------|-------|--|
| Asbestos type | 1 | Chrysotile |
| | 2 | Amphibole asbestos excluding crocidolite (ie. Amosite) |
| | 3 | Crocidolite |




Appendix D – Site Sketches




Northfleet, Crete Hall Road, Old Sun Wharf, Gravesend DA11 9AA




Northfleet, Crete Hall Road, Old Sun Wharf, Gravesend DA11 9AA



Northfleet, Crete Hall Road, Old Sun Wharf, Gravesend DA11 9AA



Northfleet, Crete Hall Road, Old Sun Wharf, Gravesend DA11 9AA



Northfleet, Crete Hall Road, Old Sun Wharf, Gravesend DA11 9AA



Appendix E – Analysis Certificates



WYG Environment Planning Transport Ltd
Arndale Court, Headingley
Leeds, LS6 2UJ
Phone: 0113 278 7111
Fax: 0113 275 0623
email: asbestos.leeds@wyg.com
www.wyg.com



6060

ANALYSIS OF BULK MATERIALS FOR ASBESTOS

Client: Homes & Communities Agency (Bristol)
2 Riversgate, Temple Quay, Bristol

Site: Northfleet, Crete Hall Road, Old Sun Wharf, Gravesend

Order Reference: N/A

Number of Samples: 15

Sample(s) taken by: Mark Thomson, WYG

Date Received: 16th March 2015

Date Analysed: 16th March 2015

Analysed by: Peter Hurst

Analysed at: WYG EPT Ltd, Arndale Court

Method: Samples of materials, referenced as shown above, have been analysed qualitatively to determine the presence of asbestos fibres. Fibres in the sample were identified using a stereo microscope, polarised light and dispersion staining in accordance with in-house Procedure 07 based on Appendix 2 of HSG 248 'Asbestos: The analyst's guide for sampling, analysis and clearance procedures'.

Report Number: J017397

Report Date: 20 Mar 2015



RESULTS

| Sample Reference | Location | Feature | Material Type | Type of Asbestos Detected |
|------------------|-----------------------|--------------------|-----------------------------|---------------------------|
| BE001309 | 02 - Store | Bitumen to parquet | Well Bound Material | NADIS |
| BE001310 | 03 - Warehouse | Bitumen to parquet | Well Bound Material | NADIS |
| BE001311 | 08 - Undercroft store | Cement panel | Asbestos Cement | Chrysotile |
| BE001312 | 09 - Corridor | Bitumen to floor | Well Bound Material | NADIS |
| BE001313 | 010 - Office | Bitumen to floor | Well Bound Material | NADIS |
| BE001314 | 010 - Office | Debris to wall | Asbestos Insulation/Coating | Amosite |
| BE001315 | 010 - Office | Debris to floor | Asbestos Insulation/Coating | Amosite |
| BE001316 | 02 - Office | Window mastic | Well Bound Material | NADIS |
| BE001318 | 12 - Store | Bitumen to parquet | Well Bound Material | NADIS |
| BE001319 | 12 - Store | Paper within door | Textiles/Paper | NADIS |
| BE001320 | 05 - Office | Window mastic | Well Bound Material | NADIS |



RESULTS

| Sample Reference | Location | Feature | Material Type | Type of Asbestos Detected |
|------------------|---------------------|--------------------------------|---------------------|---------------------------|
| BE001321 | 01 - Flat roof | Cement tiles | Asbestos Cement | Chrysotile |
| BE001322 | 01 - Flat roof | Bitumen to pipe insulation | Well Bound Material | NADIS |
| BE001323 | 01 and 02 - Office | Debris to pipe, wall and floor | Dust/Debris | NADIS |
| BE001325 | 02 - External areas | Damp proof course | Well Bound Material | NADIS |

Key: NADIS = No Asbestos Detected in Sample

J017397

REPORTED BY

A black ink signature, appearing to read 'Peter Hurst', is written over a light blue horizontal line.

Name: Peter Hurst

Position: Bulk Sample Analyst

Disclaimer.

Opinions and interpretations, including the description of material type, are outside the scope of our UKAS accreditation. Results apply only to the sample(s) listed in the table above. WYG Environment Ltd accepts no responsibility for errors which may have arisen during sampling or transportation and cannot take responsibility for the accuracy, representative nature and location of samples taken by external customers. This test report shall not be reproduced except in full without the written approval of WYG Environment Ltd

creative minds safe hands

www.wyg.com

Issuing Authority: Stephen Robinson (Deputy Quality & Technical Manager)
Version: 3

Document: CERT01
Issue Date:

Appendix F – Descriptions of general items in each room

| Area | Description of Materials |
|----------------------|---|
| Main building | |
| External | |
| 01. Flat roof | Poured bitumen roof, brick walls, slate and timber pitched roofs, bitumen wrap to straw pipe insulation, timber and felt over redundant light wells |
| 02. External areas | Brick walls, timber and metal windows, metal rainwares, |
| Ground Floor | |
| 01. Side entrance | Concrete floor, solid walls and ceilings, timber doors and frames, concrete stairs, metal bannisters, timber panels beneath stairs |
| 02. Store | Solid walls, floor, ceiling, timber door and frame timber parquet flooring |
| 03. Warehouse | Solid walls, floor, ceiling, timber door and frame timber parquet flooring |
| 04. Undercroft store | Solid walls, floor, ceiling, timber door and frame timber parquet flooring |
| 05. Undercroft store | Solid walls, floor, ceiling, timber door and frame timber parquet flooring |
| 06. Undercroft store | Solid walls, floor, ceiling, timber door and frame |
| 07. Undercroft store | Solid walls, floor, ceiling, timber door and frame |
| 08. Undercroft store | Solid walls, floor, ceiling, timber door and frame timber parquet flooring |
| 09. Corridor | Solid walls, floor, ceiling, timber doors and frames, |
| 010. Office | Solid walls, floor, ceiling, timber doors and frames, |
| 011. Foyer | Solid floor, wals, ceiling, |
| 012. Office | Solid walls, floor, ceiling, timber doors and frames, |
| 013. Office | Solid walls, floor, ceiling, timber doors and frames, timber sills and metal windows |
| 014. Office | Solid walls, floor, ceiling, timber doors and frames, fibreboard false ceiling, timber sills and metal windows |
| 015. WC | Solid floor, wals, ceiling, plasterboard false ceiling, timber boxing, ceramic sanitary wares, timber doors and frames |
| 1st Floor | |
| 01. Stairwell | Solid walls, floor, ceiling, bare pipes, timber dors and frames |



| | |
|------------|---|
| 02. Office | Solid walls, floor, ceiling, bare pipes, timber dors and frames, carpet, timber sill, metal windows, |
| 03. Office | Solid walls, floor, ceiling, bare pipes, timber dors and frames, carpet, timber sill, metal windows, |
| 04. Office | Solid walls, floor, ceiling, bare pipes, timber dors and frames, carpet, timber sill, metal windows, timber boxing to bare pipes |
| 05. Office | Solid walls, floor, ceiling, bare pipes, timber dors and frames, carpet, timber sill, metal windows, timber boxing to bare pipes |

| Area | Description of Materials |
|-------------------|--|
| 06. Office | Solid floor, walls, ceiling, timber f)doors and frames, upvc windows, timber sills, timber windows to 1/05 |
| 18. Cloakroom | Solid floor, walls, ceiling, timber f)doors and frames, upvc windows, timber sills, timber windows to 1/05 |
| 07. Female W.C. | Solid walls, floor, ceiling, bare pipes, timber dors and frames, timber partitions |
| 08. Male W.C. | Solid walls, floor, ceiling, bare pipes, timber dors and frames, timber partitions, ceramic cisterns, plastic seats |
| 09. Workshop | Solid walls, floor, ceiling, bare pipes, timber dors and frames, carpet, timber sill, metal windows, timber boxing to bare pipes |
| 10. Office | Solid walls, floor, ceiling, bare pipes, timber dors and frames, carpet, timber sill, metal windows, bare pipes in wall |
| 11. Office | Solid walls, floor, ceiling, bare pipes, timber dors and frames, carpet, timber sill, metal windows, bare pipes |
| 12. Store | Solid walls, floor, ceiling, timber door and frame timber parquet flooring |
| 16. Store | Solid walls, floor, ceiling, timber door and frame timber parquet flooring |
| 013. Corridor | Solid walls, floor, ceiling, bare pipes, timber doors and frames |
| 14. Store | Solid walls, floor, ceiling, timber door and frame timber parquet flooring |
| 15. Store | Solid walls, floor, ceiling, timber door and frame timber parquet flooring, timber store cupboard |
| 17. Male W.C. | Solid walls, floor, ceiling, bare pipes, timber dors and frames, timber partitions, ceramic cisterns, plastic seats |
| 2nd Floor | |
| 01. Stairwell | Solid walls, floor, ceiling, bare pipes, timber dors and frames, timber partitions, ceramic cisterns, plastic seats |
| 02. Office | Solid walls, floor, ceiling, plasterboard false ceiling, timber doors and frames |
| 03. Office | Solid walls, floor, ceiling, fibreboard false ceiling, timber doors and frames |
| 04. Office | Solid walls, floor, ceiling, plasterboard false ceiling, timber doors and frames |
| 05. Office | Solid walls, floor, ceiling, fibreboard false ceiling, timber doors and frames |
| 06. Office | Solid walls, floor, ceiling, fibreboard false ceiling, timber doors and frames |
| 07. Kitchen | Solid walls, floor, ceiling, plasterboard false ceiling, timber doors and frames |
| 3rd Floor | |
| 01 and 02. Office | Solid walls, floor, ceiling, timber doors and frames |
| 4th Floor | |



| | |
|---------------|---|
| 01. Tank room | Solid walls, floor, ceiling, metal tanks, metal ladder, mmmf and straw to pipes |
|---------------|---|