

FAAM Bridge – Photo Record – as of 16th August 2017.



Fig 1 - Current View of the bridge structure and deck area.



Fig 2 - Current View of the bridge structure and deck area.



Fig 3 - Current View of the existing staircase configuration.



Fig 4 - General view under bridge area from roadway. Corrosion to both fixings and surfaces alike.



Fig 5 - General view under staircase. Corrosion to both fixings and surfaces alike.



Fig 6 – Corrosion to both surfaces and bolts / nuts securing main bridge steps to truss etc.



Fig 7 – Corrosion to staircase angle base support truss, area where base support meets ground.



Fig 8 - Corrosion to buried steel truss support structure (under ground level).



Fig 9 – Railings and Cable, some corrosion and discolouring.



Fig 10 – Corrosion and Wear to Anti Slip Step Plate and Surfacing.



Fig 11 - Fig 9 – Support Rails and Cable, some corrosion and discolouring.