


EXISTING ROOF PLAN

- Mortar/render sample for analysis
- 図 Careful High level opening up to verify structure
- Careful Low level opening up to verify structure \mathbf{X}
- Areas of embedded metals causing spalling/cracking needing investigation
 - Location of cracking

KEY

 $\left(\right\}$



1. 2. 3. 4.



NOTES

- 1. DO NOT SCALE THIS DRAWING. WORK TO FIGURED DIMENSIONS ONLY. ALL DIMENSIONS ARE IN MILLIMETRES (mm) UNLESS NOTED OTHERWISE.
- 2. This drawing is to be read in conjunction with all relevant Architect's, Engineer's and Specialist's drawings and their respective Specifications.
- 3. All work to comply with the relevant British Standards, Codes of Practice and the Building Regulations.
- 4. Any discrepancies between all working drawings, specifications and schedules of all disciplines to be immediately notified to CTP for clarification/correction prior to construction of relevant structure.
- 5. See schedule for description of areas to be investigated

PRELIMINARY

Revision	Amendments	Date	Rev'd	Chk'd
Created by:	Date created:		Discipline:	
-	-		STR	UCT



consulting engineers

Suffolk House 154 High Street Sevenoaks Kent TN13 1XE UK UK: +44 (0)1732 740195 www.ctp-llp.com

RADFORD HOUSE, EFFINGHAM STREET RAMSGATE

Drawing Title

Drawing Nu

Project Title:

CDM 2015 RESIDUAL RISKS Asbestos found in roof voids

PROPOSED STRUCTURAL OPENING UP WORKS SECOND FLOOR & ROOF



1: @A3 Unless Noted Otherwise Revision

PЗ