



Photograph 3: Debonding and deterioration of upper level deck waterproofing.



Photograph 4: Missing areas of waterproofing on upper levels.




Photograph 5: Water penetration and spalling of reinforcement at level 7 ramp joint.




Photograph 6: Partially blocked internal drains.



Photograph 7: Local cracking of block facing at level 6.



Photograph 8: Spalling at ramp soffit level 6.



Photograph 9: Missing waterproofing near ramp on level 4.



Photograph 10: Damaged waterproofing entrance on level 2.



Photograph 7: Missing waterproofing on exit ramp to level 2.



Photograph 8: Missing waterproofing on entrance ramp to level 2.



Photograph 9: Missing waterproofing around entrance on level 2.



Photograph 10: Damaged waterproofing around drainage gully on level 2.



Photograph 11: Worn waterproofing showing exposed aggregate on level 2 main vehicle route.



Photograph 12: Water runoff from entrance ramp into level 1.

