

Existing brickwork
cleaned and repaired

Concrete frame repaired
and painted white

Dark grey panels and frame

Clear glazing
Incorporating automatic
opening smoke vents

Gap between Level 02
& Level 01 to be retained



Elevation - North facing Everest Lane

ROOF LEVEL

LEVEL 04

LEVEL 03

LEVEL 02

LEVEL 01

LEVEL 00

Existing brickwork
cleaned and repaired


Concrete frame repaired
and painted white

Dark grey panels and frame

Clear glazing
Incorporating automatic
opening smoke vents

Existing sign board retained

Gap between Level 02
& Level 01 to be retained



Elevation - South facing Corporation Street

