

PHOTO 15 - SECURITY ALARM AND FLOODLIGHT TO BE RELOCATED, PROTECTED AND MAINTAINED DURING THE WORKS



PHOTO 16 - WEST ELEVATION COUNCIL CHAMBER ROOF
ENTRANCE HALL ROOF AND ROOFLIGHTS



PHOTO 17 - EAST ELEVATION CHIMNEY TO BE RECONSTRUCTED



**PHOTO 18 - EAST COUNCIL CHAMBER CHIMNEY CAP AND
FLAUNCHING PRIOR TO DISMANTLING**



PHOTO 19 - EAST ELEVATION CHIMNEY PRIOR TO DISMANTLING



PHOTO 20 - BASE OF EAST CHIMNEY PRIOR TO DISMANTLING



PHOTO 21 - RECLAIMED BRICKS FROM EAST CHIMNEY FLUE
STACKED FOR STORAGE AND REUSE AFTER DISMANTLING



PHOTO 22 - STACK BRICK COURSES FROM EAST CHIMNEY
FOR STORAGE AND REUSE



PHOTO 23 - TYPICAL ROOF TRUSS AND STRUCTURE OVER
COUNCIL CHAMBER



**PHOTO 24 - TYPICAL RAFTER, PURLIN AND PROP TO TRUSS
ARRANGMENT OVER COUNCIL CHAMBER**



PHOTO 25 - SMOKE ALARM IN REGISTRAR'S OFFICE ROOF TO BE PROTECTED DURING WORKS



PHOTO 26 - TIMBER FRAME AND WATTLE & DAUB / COB INFILL TO WEST GABLE ELEVATION OVER REGISTRAR'S OFFICE TO BE REPAIRED



PHOTO 27 - MISC CABLES TO BE RE-ROUTED AND AND
REDUNDANT TIMBER PLATFORM OVER REGISTRAR'S OFFICE
TO BE REMOVED



PHOTO 28 - EXPOSED CEILING TO REGISTRAR'S OFFICE TO BE INSULATED AS PART OF WORKS

