

**National Asset Delivery
Technical Surveys and Testing**

**Site Information for
570122 A38 Middle Drift EB & WB
Pavement Coring Survey**

1 SITE INFORMATION

1.1 Site boundary, extents and access arrangements

The survey is to be undertaken on the A38 in both the eastbound and westbound directions between marker posts 6.9 and 8.8

All the work is within Highways England's boundary.

Access to the site will be via the traffic management.

The location of the site is as shown on Figure 01 below:




Figure 01: Location Plan

1.2 Pavement

The surface course consists of a Thin Surface Course sections of which were laid in 2012 and 2020.

1.3 Drainage

There are highways drainage systems within the site. For details please refer to the STATs drawings attached with PCI.

Pre - survey stats check shall be undertaken prior to works. It is anticipated however, that the survey work will not interfere with any drainage apparatus.

1.4 Geotechnical

Not applicable.

1.5 Soft Estate and Environment

Not applicable.

1.6 Traffic Signs, Road Markings

Not applicable.

1.7 Lighting

There are no street Lights within extents of scheme.

1.8 Structures and Buildings

There are six structures within proposed survey works. These are

- White Lodge Culvert ID No. 30368
- Drift Culvert ID No. 11835
- Drift Culvert Extension ID No. 11836
- Drift Lane Culvert North Extension ID No. 38925
- Drift Culvert North Extension ID No. 38739
- Chapel Hayes Culvert ID No. 6739

1.9 Tunnels

Not applicable

1.10 Technology

Not applicable

1.11 Statutory Undertakers

Utility apparatus are contained within the site, refer to STATs drawings and Pre-Construction Information.

1.12 Traffic

The site is subject to an eastbound 24hr AADT of 8125 with an HGV usage of 9.0% and a westbound 24hr AADT of 8286 with an HGV usage of 9.2% (Webtris 2019)

To provide a safe working area, traffic management will be provided by the employer.

FOR INFORMATION ONLY