


**Jubilee Hall
Station Road
Anstey
Leicestershire
LE7 7AY**

15/07/2021

Job Number: 9675





Project Information

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Job Number
9675

Surveyed by (Operator)
L Butler & R Rosindell

Base Unit
A7S6ICKJXY

Date
15/07/2021

Client Details:

Anstey Parish Council

Site Details:

Jubilee Hall
Station Road
Anstey
Leicestershire
LE7 7AY

Contractor Details:

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Office Contact Number: 07968 993 001

Purpose of Survey:

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
---------------------------	---	--------------------------------	---------------------------

Report Contents

Page 1	Cover Page
Page 2	Job Overview
Page 3	Contents Page
Page 5	Grade Defect Descriptions
Page 6	Survey Run Sheet(Survey 1 - MH1 to A)
Page 8	Survey Run Sheet(Survey 2 - IC2 to MH1)
Page 10	Survey Run Sheet(Survey 3 - IC2 to SP1)
Page 12	Survey Run Sheet(Survey 4 - IC2 to IC3)
Page 14	Survey Run Sheet(Survey 5 - IC3 to SP2)
Page 16	Survey Run Sheet(Survey 6 - IC3 to SP3)
Page 18	Survey Run Sheet(Survey 7 - IC3 to IC4)
Page 21	Survey Run Sheet(Survey 8 - IC4 to SP4)
Page 23	Survey Run Sheet(Survey 9 - IC4 to SP5)
Page 25	Survey Run Sheet(Survey 10 - IC4 to SP6)
Page 27	Survey Run Sheet(Survey 11 - MH1 to MH4)
Page 29	Survey Run Sheet(Survey 12 - IC6 to RWP1)
Page 31	Survey Run Sheet(Survey 13 - IC6 to IC7)
Page 33	Survey Run Sheet(Survey 14 - IC6 to C)



Contents Page

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
---------------------------	---	--------------------------------	---------------------------

Report Contents

Page 35	Survey Run Sheet(Survey 15 - IC8 to D)
Page 37	Survey Run Sheet(Survey 16 - IC8 to E)
Page 39	Survey Run Sheet(Survey 17 - IC8 to F)
Page 41	Survey Run Sheet(Survey 18 - IC9 to IC10)
Page 43	Survey Run Sheet(Survey 19 - IC10 to RWP2)
Page 45	Survey Run Sheet(Survey 20 - IC10 to G)
Page 47	Survey Run Sheet(Survey 21 - IC7 to RWP3)
Page 49	Survey Run Sheet(Survey 22 - IC11 to H)
Page 51	Defect Summary
Page 53	Job Summary

Defect Grade Descriptions


Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
<p>1: Occurences without damage. For example, laterals, joints,etc.</p> <p>NO DEFECTS WERE DETECTED.</p>			
<p>2: Constructional deficiencies or occurences with insignificant influence to tightness, hydraulic or static pressure or pipe: Eg. wide joints, badly torched intakes, minor deformation of plastic pipes, minor erosions etc.</p> <p>REHABILITATION CAN BE SCHEDULED LONG-TERM.</p>			
<p>3: Constructional deficiencies diminishing static, hydraulic and tightness: Eg. untorched intakes, cracks, minor drainage obstructions such as calcite build ups, protruding laterals, minor damages to pipe wall, individual root penetrations, corroded pipe walls etc.</p> <p>REHABILITATION IS NECESSARY MEDIUM-TERM WITHIN 3 TO 5 YEARS.</p>			
<p>4: Constructional damages with insufficient static safety, hydraulic or tightness: Eg. axial/radial pipe bursts, pipe deformations, visually noticeable infiltration/exfiltration, cavities, in pipe-wall, severe protruding, laterals severe root penetrations, severe corrosion of pipe wall etc.</p> <p>REHABILITATION PROCEDURE IS URGENT AND HAS TO BE COMPLETED WITHIN 1 TO 2 YEARS. NECESSITY FOR EMERGENCY OPERATIONS HAS TO BE EXAMINED.</p>			
<p>5: Pipe is already or will shortly be impermeable: Eg. collapsed pipe, deeply rooted pipe or other drainage obstructions. Pipe loses water or danger of backwater in basements etc.</p> <p>REHABILITATION IS URGENT AND SHORT-TERM. IN ORDER TO PREVENT FURTHER DAMAGE, NECESSARY TEMPORARY SPOT REPAIR HAS TO BE CONDUCTED ON EMERGENCY LEVEL.</p>			







CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) A X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 1
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Foul Catchment	Shape/Size 150mm Material Polyvinyl chloride Category	Start Node MH1 End Node A Total length 1.31 metres		
Scale 1:0.05 Direction Upstream				




Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, manhole, reference MH1</p>			
 <p>0.00 M</p> <p>Water level 0% height/diameter</p>			
 <p>1.02 M</p> <p>Line of drain/sewer deviates up full</p>			
 <p>1.31 M</p> <p>Finish node type, outfall, reference A (Dropper)</p>			








CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) IC2 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 2
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Foul Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC2 End Node MH1 Total length 13.4 metres	
Scale 1:0.68 Direction Downstream				




Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC2</p>			
 <p>0.00 M</p> <p>Water level 0% height/diameter</p>			
 <p>0.00 M</p> <p>Line of drain/sewer deviates right half</p>			
 <p>3.69 M</p> <p>Junction at 3 o'clock, diameter 100mm</p>			
 <p>13.40 M</p> <p>Finish node type, manhole, reference MH1</p>			








CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) SP1 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 3
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Foul Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC2 End Node SP1 Total length 2.95 metres	
Scale 1:0.10 Direction Upstream				




Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC2</p>		 <p>0.00 M</p> <p>Water level 0% height/diameter</p>	
 <p>2.02 M</p> <p>Line of drain/sewer deviates right half</p>		 <p>2.43 M</p> <p>Line of drain/sewer deviates up full</p>	
 <p>2.95 M</p> <p>Finish node type, outfall, reference SP1</p>			









CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference (PLR) IC3 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 4
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Foul Catchment	Shape/Size 100mm Material Polyvinyl chloride Category	Start Node IC2 End Node IC3 Total length 3.83 metres		
Scale 1:0.16 Direction Upstream				



Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC2</p>		 <p>0.00 M</p> <p>Water level 10% height/diameter</p>	
 <p>0.00 M</p> <p>Line of drain/sewer deviates left half</p>		 <p>1.31 M</p> <p>Water level 25% height/diameter</p>	
 <p>2.71 M</p> <p>Water level 0% height/diameter</p>		 <p>3.83 M</p> <p>Finish node type, inspection chamber, reference IC3</p>	




CCTV Inspection Report







TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) SP2 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 5
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Foul Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC3 End Node SP2 Total length 2.52 metres	
Scale 1:0.10 Direction Upstream				

Start Node Ref:IC3 | I/L :0.800 metres | Depth: 0.800 metres

Position	Code	Description	Photo	Type/Grade
	0.00 IC	Start node type, inspection chamber, reference IC3	5293396	Comment / 0
	0.00 WL	Water level 0% height/diameter	5293397	Comment / 0
	0.00 LL	Line of drain/sewer deviates left half	5293398	Comment / 0
	1.81 LL	Line of drain/sewer deviates left half	5293401	Comment / 0
	2.26 LU	Line of drain/sewer deviates up full	5293403	Comment / 0
	2.52 OFF	Finish node type, outfall, reference SP2	5293411	Comment / 0

End Node Ref:SP2 | I/L : metres

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC3</p>		 <p>0.00 M</p> <p>Water level 0% height/diameter</p>	
 <p>0.00 M</p> <p>Line of drain/sewer deviates left half</p>		 <p>1.81 M</p> <p>Line of drain/sewer deviates left half</p>	
 <p>2.26 M</p> <p>Line of drain/sewer deviates up full</p>		 <p>2.52 M</p> <p>Finish node type, outfall, reference SP2</p>	



CCTV Inspection Report







TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) SP3 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 6
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Foul Catchment	Shape/Size 100mm Material Polyvinyl chloride Category	Start Node IC3 End Node SP3 Total length 6 metres		
Scale 1:0.31 Direction Upstream				

Start Node Ref:IC3 | I/L : metres | Depth: 0.800 metres

Position	Code	Description	Photo	Type/Grade
0.00	IC	Start node type, inspection chamber, reference IC3	5293414	Comment / 0
0.00	WL	Water level 0% height/diameter	5293415	Comment / 0
0.00	LL	Line of drain/sewer deviates left quarter	5293420	Comment / 0
2.17	JN	Junction at 3 o'clock, diameter 100mm	5293424	Comment / 0
5.57	LU	Line of drain/sewer deviates up full	5293425	Comment / 0
6.00	OFF	Finish node type, outfall, reference SP3	5293427	Comment / 0

End Node Ref:SP3 | I/L : metres

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC3</p>		 <p>0.00 M</p> <p>Water level 0% height/diameter</p>	
 <p>0.00 M</p> <p>Line of drain/sewer deviates left quarter</p>		 <p>2.17 M</p> <p>Junction at 3 o'clock, diameter 100mm</p>	
 <p>5.57 M</p> <p>Line of drain/sewer deviates up full</p>		 <p>6.05 M</p> <p>Finish node type, outfall, reference SP3</p>	



CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) IC4 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 7
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Foul Catchment	Shape/Size 100mm Material Polyvinyl chloride Category	Start Node IC3 End Node IC4 Total length 19.14 metres		
Scale 1:1.00 Direction Upstream				

Start Node Ref:IC3 | I/L : metres | Depth: 0.800 metres

Position	Code	Description	Photo	Type/Grade
0.00	IC	Start node type, inspection chamber, reference IC3	5293453	Comment / 0
0.00	WL	Water level 0% height/diameter	5293454	Comment / 0
0.71	WL	Water level 10% height/diameter	5293455	Comment / 0
4.88	JN	Junction at 9 o'clock, diameter 100mm	5293456	Comment / 0
6.02	WL	Water level 0% height/diameter	5293461	Comment / 0
16.60	WL	Water level 10% height/diameter	5293463	Comment / 0
17.62	WL	Water level 0% height/diameter	5293464	Comment / 0
18.81	LL	Line of drain/sewer deviates left half	5293473	Comment / 0
19.14	ICF	Finish node type, inspection chamber, reference IC4	5293475	Comment / 0

End Node Ref:IC4 | I/L : metres

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC3, Water level 0% height/diameter, Water level 10% height/diameter</p>			
 <p>4.88 M</p> <p>Junction at 9 o'clock, diameter 100mm</p>			
 <p>6.05 M</p> <p>Water level 0% height/diameter</p>			
 <p>16.60 M</p> <p>Water level 10% height/diameter</p>			
 <p>17.62 M</p> <p>Water level 0% height/diameter</p>			
 <p>18.81 M</p> <p>Line of drain/sewer deviates left half</p>			

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
---------------------------	---	--------------------------------	---------------------------



Finish node type, inspection chamber, reference IC4



CCTV Inspection Report





TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) SP4 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 8
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Foul Catchment		Shape/Size 100mm Material Polyvinyl chloride Category	Start Node IC4 End Node SP4 Total length 7.57 metres	
Scale 1:0.37 Direction Upstream				

Start Node Ref:IC4 | I/L :0.550 metres | Depth: 0.550 metres

Position	Code	Description	Photo	Type/Grade
0.00	IC	Start node type, inspection chamber, reference IC4	5293527	Comment / 0
0.00	WL	Water level 0% height/diameter	5293528	Comment / 0
5.95	JN	Junction at 3 o'clock, diameter 100mm	5293537	Comment / 0
7.57	OFF	Finish node type, outfall, reference SP4	5293545	Comment / 0

End Node Ref:SP4 | I/L : metres


Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC4</p>		 <p>0.00 M</p> <p>Water level 0% height/diameter</p>	
 <p>5.95 M</p> <p>Junction at 3 o'clock, diameter 100mm</p>		 <p>7.57 M</p> <p>Finish node type, outfall, reference SP4</p>	








CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) SP5 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 9
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Foul Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC4 End Node SP5 Total length 6.21 metres	
Scale 1:0.31 Direction Upstream				




Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC4</p>		 <p>0.00 M</p> <p>Water level 0% height/diameter</p>	
 <p>0.00 M</p> <p>Line of drain/sewer deviates left half</p>		 <p>5.71 M</p> <p>Line of drain/sewer deviates up full</p>	
 <p>6.21 M</p> <p>Finish node type, outfall, reference SP5</p>			









CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) SP6 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 4/0	Base Unit A7S6ICKJXY	Section Number 10
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Foul Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC4 End Node SP6 Total length 8.93 metres	
Scale 1:0.42 Direction Upstream				




Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p>		 <p>0.00 M</p>	
<p>Start node type, inspection chamber, reference IC4</p>		<p>Water level 0% height/diameter</p>	
 <p>6.50 M</p>		 <p>7.83 M</p>	
<p>Line of drain/sewer deviates left half</p>		<p>Junction at 11 o'clock, diameter 100mm</p>	
 <p>8.93 M</p>		 <p>8.93 M</p>	
<p>Settled deposits fine 25% cross-sectional area loss</p>		<p>Survey abandoned - Remark: Due to debris (B)</p>	









CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) MH1 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 11
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Foul Catchment	Shape/Size 150mm Material Polyvinyl chloride Category		Start Node MH1 End Node MH4 Total length 2 metres	
Scale 1:0.10 Direction Downstream				



Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, manhole, reference MH1</p>			
 <p>0.00 M</p> <p>Water level 0% height/diameter</p>			
 <p>1.17 M</p> <p>Line of drain/sewer deviates down half</p>			
 <p>1.17 M</p> <p>Line of drain/sewer deviates left half</p>			
 <p>1.88 M</p> <p>Line of drain/sewer deviates up half</p>			
 <p>1.98 M</p> <p>Finish node type, manhole, reference MH5</p>			



CCTV Inspection Report





TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) RWP1 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 12
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Surface water Catchment		Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC6 End Node RWP1 Total length 1.52 metres
Scale 1:0.05 Direction Upstream				

Start Node Ref:IC6 | I/L : metres

Position	Code	Description	Photo	Type/Grade
0.00	IC	Start node type, inspection chamber, reference IC6	5293979	Comment / 0
0.00	WL	Water level 0% height/diameter	5293981	Comment / 0
0.93	LU	Line of drain/sewer deviates up full	5293982	Comment / 0
1.52	OFF	Finish node type, outfall, reference RWP1	5293983	Comment / 0

End Node Ref:RWP1 | I/L : metres

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC6</p>		 <p>0.00 M</p> <p>Water level 0% height/diameter</p>	
 <p>0.93 M</p> <p>Line of drain/sewer deviates up full</p>		 <p>1.52 M</p> <p>Finish node type, outfall, reference RWP1</p>	



CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) IC7 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 13
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Surface water Catchment	Shape/Size 100mm Material Polyvinyl chloride Category	Start Node IC6 End Node IC7 Total length 10.69 metres		
Scale 1:0.52 Direction Upstream				

Start Node Ref:IC6 | I/L : metres

Position	Code	Description	Photo	Type/Grade
0.00	IC	Start node type, inspection chamber, reference IC6	5293988	Comment / 0
0.00	WL	Water level 0% height/diameter	5293989	Comment / 0
				
10.69	ICF	Finish node type, inspection chamber, reference IC7	5293994	Comment / 0

End Node Ref:IC7 | I/L : metres

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
---------------------------	---	--------------------------------	---------------------------



Start node type, inspection chamber, reference IC6



Water level 0% height/diameter




Finish node type, inspection chamber, reference IC7







CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) IC6	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 4/0	Base Unit A7S6ICKJXY	Section Number 14
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Surface water Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC6 End Node C Total length 1.81 metres	
Scale 1:0.05 Direction Downstream				



Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC6</p>			
 <p>0.00 M</p> <p>Water level 0% height/diameter</p>			
 <p>0.74 M</p> <p>Settled deposits cause 25% cross-sectional area loss</p>			
 <p>1.81 M</p> <p>Survey abandoned - Remark: Due to debris (C)</p>			







CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) D	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 15
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Surface water Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC8 End Node D Total length 8.57 metres	
Scale 1:0.42 Direction Upstream				

Start Node Ref:IC8 I/L : metres					Photo	Type/Grade
Position	Code	Description				
0.00	IC	Start node type, inspection chamber, reference IC8 Water level 10% height/diameter			5294091	Comment / 0
0.00	WL				5294096	Comment / 0
7.24	JN	Junction at 2 o'clock, diameter 100mm			5294112	Comment / 0
8.57	SA	Survey abandoned - Remark: Due to debris (D)			5294113	Comment / 0
End Node Ref:D I/L : metres						

CCTV Inspection Photos


Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC8</p>		 <p>0.00 M</p> <p>Water level 10% height/diameter</p>	
 <p>7.24 M</p> <p>Junction at 2 o'clock, diameter 100mm</p>		 <p>8.57 M</p> <p>Survey abandoned - Remark: Due to debris (D)</p>	







CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) E X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 4/0	Base Unit A7S6ICKJXY	Section Number 16
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Surface water Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC8 End Node E Total length 3.07 metres	
Scale 1:0.16 Direction Upstream				




Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC8</p>		 <p>0.00 M</p> <p>Water level 10% height/diameter</p>	
 <p>3.07 M</p> <p>Settled deposits fine 75% cross-sectional area loss</p>		 <p>3.07 M</p> <p>Survey abandoned - Remark: Due to Debris (E)</p>	







CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) IC8	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 4/0	Base Unit A7S6ICKJXY	Section Number 17
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Surface water Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC8 End Node F Total length 5.93 metres	
Scale 1:0.26 Direction Downstream				



CCTV Inspection Photos

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC8</p>		 <p>0.00 M</p> <p>Water level 0% height/diameter</p>	
 <p>0.00 M</p> <p>Settled deposits fine 50% cross-sectional area loss</p>		 <p>5.93 M</p> <p>Survey abandoned, Remark: Due to Debris (F)</p>	



CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) IC10 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 18
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Surface water Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC9 End Node IC10 Total length 11.5 metres	
Scale 1:0.58 Direction Upstream				

Start Node Ref:IC9 | I/L :0.800 metres | Depth: 0.800 metres

Position	Code	Description	Photo	Type/Grade
0.00	IC	Start node type, inspection chamber, reference IC9	5294301	Comment / 0
0.00	WL	Water level 0% height/diameter	5294305	Comment / 0
11.50	ICF	Finish node type, inspection chamber, reference IC10	5294308	Comment / 0

End Node Ref:IC10 | I/L : metres

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
---------------------------	---	--------------------------------	---------------------------



Start node type, inspection chamber, reference IC9



Water level 0% height/diameter



Finish node type, inspection chamber, reference IC10



CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) RWP2	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 19
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Surface water Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC10 End Node RWP2 Total length 2.29 metres	
Scale 1:0.10 Direction Upstream				

Start Node Ref:IC10 | I/L : metres

Position	Code	Description	Photo	Type/Grade
0.00	IC	Start node type, inspection chamber, reference IC10	5294323	Comment / 0
0.00	WL	Water level 0% height/diameter	5294324	Comment / 0
2.29	OFF	Finish node type, outfall, reference RWP2	5294326	Comment / 0

End Node Ref:RWP2 | I/L : metres


Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
---------------------------	---	--------------------------------	---------------------------



Start node type, inspection chamber, reference IC10



Water level 0% height/diameter



Finish node type, outfall, reference RWP2



CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) IC10 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 4/0	Base Unit A7S6ICKJXY	Section Number 20

Road Jubilee Hall Place Station Road Location Anstey	Division District Location Details
---	--





Purpose Duty Surface water Catchment	Shape/Size 100mm Material Polyvinyl chloride Category	Start Node IC10 End Node G Total length 2.43 metres
---	---	--

Scale 1:0.10 Direction Downstream	
--	--

Start Node Ref:IC10 | I/L : metres

Position	Code	Description	Photo	Type/Grade
0.00	IC	Start node type, inspection chamber, reference IC10	5294331	Comment / 0
0.00	WL	Water level 0% height/diameter	5294332	Comment / 0
1.14	DES	Settled deposits fine 25% cross-sectional area loss	5294334	Service / 4
2.43	SA	Survey abandoned - Remark: Due to debris (G)	5294336	Comment / 0

End Node Ref:G | I/L : metres

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC10</p>		 <p>0.00 M</p> <p>Water level 0% height/diameter</p>	
 <p>1.14 M</p> <p>Settled deposits fine 25% cross-sectional area loss</p>		 <p>2.40 M</p> <p>Survey abandoned - Remark: Due to debris (G)</p>	



CCTV Inspection Report

TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH


Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) RWP3 X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 0/0	Base Unit A7S6ICKJXY	Section Number 21
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Surface water Catchment	Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC7 End Node RWP3 Total length 0.95 metres	
Scale 1:0.00 Direction Upstream				

Start Node Ref:IC7 | I/L :0.400 metres | Depth: 0.400 metres


Position	Code	Description	Photo	Type/Grade
0.00	IC	Start node type, inspection chamber, reference IC7	5294850	Comment / 0
0.00	WL	Water level 0% height/diameter	5294852	Comment / 0
0.95	OFF	Finish node type, outfall, reference RWP3	5294853	Comment / 0

End Node Ref:RWP3 | I/L : metres

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
---------------------------	---	--------------------------------	---------------------------



Start node type, inspection chamber, reference IC7



Water level 0% height/diameter



Finish node type, outfall, reference RWP3



CCTV Inspection Report







TBL Survey Ltd
Delvin Brae
Amisfield
Dumfries
Dumfriesshire
DG1 3LH

Surveyed by (Operator) L Butler & R Rosindell	Job Number 9675	Pipe Length Reference(PLR) H X	Date 15/07/2021	Pre Cleaned Not Cleaned
Weather 1 - Dry	Customer Present	Service Grade/Structural Grade 4/0	Base Unit A7S6ICKJXY	Section Number 22
Road Jubilee Hall Place Station Road Location Anstey		Division District Location Details		
Purpose Duty Surface water Catchment		Shape/Size 100mm Material Polyvinyl chloride Category		Start Node IC11 End Node H Total length 14.21 metres
Scale 1:0.73 Direction Upstream				

Start Node Ref:IC11 | I/L : metres

Position	Code	Description	Photo	Type/Grade
0.00	IC	Start node type, inspection chamber, reference IC11	5294872	Comment / 0
0.00	WL	Water level 0% height/diameter	5294874	Comment / 0
4.07	JN	Junction at 11 o'clock, diameter 100mm	5294884	Comment / 0
13.43	JN	Junction at 10 o'clock, diameter 100mm	5294920	Comment / 0
14.21	DES	Settled deposits fine 75% cross-sectional area loss	5294923	Service / 4
14.21	SA	Survey abandoned - Remark: Due to debris	5294953	Comment / 0

End Node Ref:H | I/L : metres

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
 <p>0.00 M</p> <p>Start node type, inspection chamber, reference IC11</p>		 <p>0.00 M</p> <p>Water level 0% height/diameter</p>	
 <p>4.07 M</p> <p>Junction at 11 o'clock, diameter 100mm</p>		 <p>13.43 M</p> <p>Junction at 10 o'clock, diameter 100mm</p>	
 <p>14.21 M</p> <p>Settled deposits fine 75% cross-sectional area loss</p>		 <p>14.21 M</p> <p>Survey abandoned - Remark: Due to debris</p>	

Structural Defects (SRM 4)

Job Number 9675				Surveyed by (Operator) L Butler & R Rosindell		Base Unit A7S6ICKJXY			Date 15/07/2021				
No.	PLR	Dir.	Use	Shape/Size	Date	Mat.	Total Length	Inspection Length	Cat.	Peak Score	Grade	Mean Score	Total Score
1	A X	U	F	150	15/07/2021	Polyvinyl chloride	1.31 metres	1.31		0	1	0	0
2	IC2 X	D	F	100	15/07/2021	Polyvinyl chloride	13.4 metres	13.4		0	1	0	0
3	SP1 X	U	F	100	15/07/2021	Polyvinyl chloride	2.95 metres	2.95		0	1	0	0
4	IC3 X	U	F	100	15/07/2021	Polyvinyl chloride	3.83 metres	3.83		0	1	0	0
5	SP2 X	U	F	100	15/07/2021	Polyvinyl chloride	2.52 metres	2.52		0	1	0	0
6	SP3 X	U	F	100	15/07/2021	Polyvinyl chloride	6 metres	6		0	1	0	0
7	IC4 X	U	F	100	15/07/2021	Polyvinyl chloride	19.14 metres	19.14		0	1	0	0
8	SP4 X	U	F	100	15/07/2021	Polyvinyl chloride	7.57 metres	7.57		0	1	0	0
9	SP5 X	U	F	100	15/07/2021	Polyvinyl chloride	6.21 metres	6.21		0	1	0	0
10	SP6 X	U	F	100	15/07/2021	Polyvinyl chloride	8.93 metres	8.93		0	1	0	0
11	MH1 X	D	F	150	15/07/2021	Polyvinyl chloride	2 metres	1.88		0	1	0	0
12	RWP1 X	U	S	100	15/07/2021	Polyvinyl chloride	1.52 metres	1.52		0	1	0	0
13	IC7 X	U	S	100	15/07/2021	Polyvinyl chloride	10.69 metres	10.69		0	1	0	0
14	IC6	D	S	100	15/07/2021	Polyvinyl chloride	1.81 metres	1.81		0	1	0	0
15	D	U	S	100	15/07/2021	Polyvinyl chloride	8.57 metres	8.57		0	1	0	0
16	E X	U	S	100	15/07/2021	Polyvinyl chloride	3.07 metres	3.07		0	1	0	0
17	IC8	D	S	100	15/07/2021	Polyvinyl chloride	5.93 metres	5.93		0	1	0	0
18	IC10 X	U	S	100	15/07/2021	Polyvinyl chloride	11.5 metres	11.5		0	1	0	0
19	RWP2	U	S	100	15/07/2021	Polyvinyl chloride	2.29 metres	2.29		0	1	0	0
20	IC10 X	D	S	100	15/07/2021	Polyvinyl chloride	2.43 metres	2.43		0	1	0	0
21	RWP3 X	U	S	100	15/07/2021	Polyvinyl chloride	0.95 metres	0.95		0	1	0	0
22	H X	U	S	100	15/07/2021	Polyvinyl chloride	14.21 metres	14.21		0	1	0	0

Service Defects (SRM 4)

Job Number 9675				Surveyed by (Operator) L Butler & R Rosindell		Base Unit A7S6ICKJXY			Date 15/07/2021				
No.	PLR	Dir.	Use	Shape/Size	Date	Mat.	Total Length	Inspection Length	Cat.	Peak Score	Grade	Mean Score	Total Score
1	A X	U	F	150	15/07/2021	Polyvinyl chloride	1.31 metres	1.31		0	1	0	0
2	IC2 X	D	F	100	15/07/2021	Polyvinyl chloride	13.4 metres	13.4		0	1	0	0
3	SP1 X	U	F	100	15/07/2021	Polyvinyl chloride	2.95 metres	2.95		0	1	0	0
4	IC3 X	U	F	100	15/07/2021	Polyvinyl chloride	3.83 metres	3.83		0	1	0	0
5	SP2 X	U	F	100	15/07/2021	Polyvinyl chloride	2.52 metres	2.52		0	1	0	0
6	SP3 X	U	F	100	15/07/2021	Polyvinyl chloride	6 metres	6		0	1	0	0
7	IC4 X	U	F	100	15/07/2021	Polyvinyl chloride	19.14 metres	19.14		0	1	0	0
8	SP4 X	U	F	100	15/07/2021	Polyvinyl chloride	7.57 metres	7.57		0	1	0	0
9	SP5 X	U	F	100	15/07/2021	Polyvinyl chloride	6.21 metres	6.21		0	1	0	0
10	SP6 X	U	F	100	15/07/2021	Polyvinyl chloride	8.93 metres	8.93		5	4	0.56	5
11	MH1 X	D	F	150	15/07/2021	Polyvinyl chloride	2 metres	1.88		0	1	0	0
12	RWP1 X	U	S	100	15/07/2021	Polyvinyl chloride	1.52 metres	1.52		0	1	0	0
13	IC7 X	U	S	100	15/07/2021	Polyvinyl chloride	10.69 metres	10.69		0	1	0	0
14	IC6	D	S	100	15/07/2021	Polyvinyl chloride	1.81 metres	1.81		5	4	2.76	5
15	D	U	S	100	15/07/2021	Polyvinyl chloride	8.57 metres	8.57		0	1	0	0
16	E X	U	S	100	15/07/2021	Polyvinyl chloride	3.07 metres	3.07		8	4	2.61	8
17	IC8	D	S	100	15/07/2021	Polyvinyl chloride	5.93 metres	5.93		8	4	1.35	8
18	IC10 X	U	S	100	15/07/2021	Polyvinyl chloride	11.5 metres	11.5		0	1	0	0
19	RWP2	U	S	100	15/07/2021	Polyvinyl chloride	2.29 metres	2.29		0	1	0	0
20	IC10 X	D	S	100	15/07/2021	Polyvinyl chloride	2.43 metres	2.43		5	4	2.06	5
21	RWP3 X	U	S	100	15/07/2021	Polyvinyl chloride	0.95 metres	0.95		0	1	0	0
22	H X	U	S	100	15/07/2021	Polyvinyl chloride	14.21 metres	14.21		8	4	0.56	8

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
---------------------------	---	--------------------------------	---------------------------

Job Information

Total Distance Surveyed: **136.83 metres**
Engineer: **L Butler & R Rosindell**
Number of Surveys: **22**
Number of Surveys grade 4 or above: **0**

Section 1 Overview (15/07/2021)

Manholes: **MH1 to A**
Pipe Length: **1.31 metres**
Structural Grade: **0**
Service Grade: **0**
Material: **Polyvinyl chloride**
Pipe Size: **150mm**
Use: **Foul**

Section 2 Overview (15/07/2021)

Manholes: **IC2 to MH1**
Pipe Length: **13.4 metres**
Structural Grade: **0**
Service Grade: **0**
Material: **Polyvinyl chloride**
Pipe Size: **100mm**
Use: **Foul**

Section 3 Overview (15/07/2021)

Manholes: **IC2 to SP1**
Pipe Length: **2.95 metres**
Structural Grade: **0**
Service Grade: **0**
Material: **Polyvinyl chloride**
Pipe Size: **100mm**
Use: **Foul**

Section 4 Overview (15/07/2021)

Manholes: **IC2 to IC3**
Pipe Length: **3.83 metres**
Structural Grade: **0**
Service Grade: **0**
Material: **Polyvinyl chloride**
Pipe Size: **100mm**
Use: **Foul**

Section 5 Overview (15/07/2021)

Manholes: **IC3 to SP2**
Pipe Length: **2.52 metres**
Structural Grade: **0**
Service Grade: **0**
Material: **Polyvinyl chloride**
Pipe Size: **100mm**
Use: **Foul**

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
Section 6 Overview (15/07/2021) Manholes: IC3 to SP3 Pipe Length: 6 metres Structural Grade: 0 Service Grade: 0 Material: Polyvinyl chloride Pipe Size: 100mm Use: Foul			
Section 7 Overview (15/07/2021) Manholes: IC3 to IC4 Pipe Length: 19.14 metres Structural Grade: 0 Service Grade: 0 Material: Polyvinyl chloride Pipe Size: 100mm Use: Foul			
Section 8 Overview (15/07/2021) Manholes: IC4 to SP4 Pipe Length: 7.57 metres Structural Grade: 0 Service Grade: 0 Material: Polyvinyl chloride Pipe Size: 100mm Use: Foul			
Section 9 Overview (15/07/2021) Manholes: IC4 to SP5 Pipe Length: 6.21 metres Structural Grade: 0 Service Grade: 0 Material: Polyvinyl chloride Pipe Size: 100mm Use: Foul			
Section 10 Overview (15/07/2021) Manholes: IC4 to SP6 Pipe Length: 8.93 metres Structural Grade: 0 Service Grade: 4 Material: Polyvinyl chloride Pipe Size: 100mm Use: Foul			
Section 11 Overview (15/07/2021) Manholes: MH1 to MH4 Pipe Length: 2 metres Structural Grade: 0 Service Grade: 0 Material: Polyvinyl chloride Pipe Size: 150mm Use: Foul			

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
Section 12 Overview (15/07/2021) Manholes: IC6 to RWP1 Pipe Length: 1.52 metres Structural Grade: 0 Service Grade: 0 Material: Polyvinyl chloride Pipe Size: 100mm Use: Surface water			
Section 13 Overview (15/07/2021) Manholes: IC6 to IC7 Pipe Length: 10.69 metres Structural Grade: 0 Service Grade: 0 Material: Polyvinyl chloride Pipe Size: 100mm Use: Surface water			
Section 14 Overview (15/07/2021) Manholes: IC6 to C Pipe Length: 1.81 metres Structural Grade: 0 Service Grade: 4 Material: Polyvinyl chloride Pipe Size: 100mm Use: Surface water			
Section 15 Overview (15/07/2021) Manholes: IC8 to D Pipe Length: 8.57 metres Structural Grade: 0 Service Grade: 0 Material: Polyvinyl chloride Pipe Size: 100mm Use: Surface water			
Section 16 Overview (15/07/2021) Manholes: IC8 to E Pipe Length: 3.07 metres Structural Grade: 0 Service Grade: 4 Material: Polyvinyl chloride Pipe Size: 100mm Use: Surface water			
Section 17 Overview (15/07/2021) Manholes: IC8 to F Pipe Length: 5.93 metres Structural Grade: 0 Service Grade: 4 Material: Polyvinyl chloride Pipe Size: 100mm Use: Surface water			

Job Number 9675	Surveyed by (Operator) L Butler & R Rosindell	Base Unit A7S6ICKJXY	Date 15/07/2021
Section 18 Overview (15/07/2021) Manholes: IC9 to IC10 Pipe Length: 11.5 metres Structural Grade: 0 Service Grade: 0 Material: Polyvinyl chloride Pipe Size: 100mm Use: Surface water			
Section 19 Overview (15/07/2021) Manholes: IC10 to RWP2 Pipe Length: 2.29 metres Structural Grade: 0 Service Grade: 0 Material: Polyvinyl chloride Pipe Size: 100mm Use: Surface water			
Section 20 Overview (15/07/2021) Manholes: IC10 to G Pipe Length: 2.43 metres Structural Grade: 0 Service Grade: 4 Material: Polyvinyl chloride Pipe Size: 100mm Use: Surface water			
Section 21 Overview (15/07/2021) Manholes: IC7 to RWP3 Pipe Length: 0.95 metres Structural Grade: 0 Service Grade: 0 Material: Polyvinyl chloride Pipe Size: 100mm Use: Surface water			
Section 22 Overview (15/07/2021) Manholes: IC11 to H Pipe Length: 14.21 metres Structural Grade: 0 Service Grade: 4 Material: Polyvinyl chloride Pipe Size: 100mm Use: Surface water			