



Photograph 1. General view of site, of proposed new barn looking north-eastwards.



Photograph 2. Trench 1 excavated in fallow field to north of proposed new barn location.



Photograph 3. Detail of horizons of weathered fractured, in-situ, undisturbed, unmineralised sedimentary bedrock, overlain by soils. exposed in Trench 1.



Photograph 4 Trench 2 excavated from inside of the garden area to the south of the proposed new barn .



Photograph 5. Detail of intact, undisturbed horizons of soil and stony clays underlain by fractured weathered bedrock in Trench 2.



Photograph 6. Pit excavated for percolation testing, showing undisturbed fractured, weathered sedimentary bedrock, overlain by stony red clay and soil.