

Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	Broken	Headstone broken into 4 main pieces, with some sections missing
Surface condition :	Organic growth	Some green staining
Condition of inscription :	Good	

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	Corroded	Iron cramps fixing headstone to granite base?
------------------------	----------	---

GENERAL CONDITION/COMMENTS

General condition :	Poor	Heritage significance:	A
General comments:	Granite base has since been re-erected, with broken headstone attached (see photo). High risk of further loss.		

PROPOSED REPAIRS

Proposed repairs:	Clean off organic growth and dirt. Sink granite base into ground to original depth in original location. Pin surviving sections (4? no plus base) together to 25mm thick slate backing. Make good joints with mortar. Refix to granite base and re-erect headstone.
Schedule of Work clauses:	2.01 and 2.09a

HEALTH AND SAFETY HAZARDS

Hazards:	Trip hazard	Broken pieces on the ground
----------	-------------	-----------------------------

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	<input type="text" value="Broken"/>	<input type="text" value="Headstone broken into nine main pieces plus fragment still in ground"/>
Surface condition :	<input type="text" value="Organic growth"/>	<input type="text"/>
Condition of inscription :	<input type="text" value="Good"/>	<input type="text" value="Most covered with moss"/>

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	<input type="text" value="None"/>	<input type="text"/>
------------------------	-----------------------------------	----------------------

GENERAL CONDITION/COMMENTS

General condition :	<input type="text" value="Poor"/>	Heritage significance:	<input type="text" value="C"/>
General comments:	<input type="text" value="High risk of further damage. Sandstone broken into several pieces, upright fragment giving true position"/>		

PROPOSED REPAIRS

Proposed repairs:	<input type="text" value="Clean off organic growth and dirt. Excavate base section. Pin broken sections (9 no plus base) together with stainless steel dowels, and pin to 25mm thick slate backing. Make good joints with mortar. Re-erect in original location."/>
-------------------	---

Schedule of Work clauses:	<input type="text" value="2.04 and 2.09a."/>
---------------------------	--

HEALTH AND SAFETY HAZARDS

Hazards:	<input type="text" value="Trip hazard"/>	<input type="text" value="Headstone broken on ground"/>
----------	--	---

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	Broken	Broken off at base, but complete
Surface condition :	Organic growth	Moss
Condition of inscription :	Other	Unreadable

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	None	
------------------------	------	--

GENERAL CONDITION/COMMENTS

General condition :	Fair	Heritage significance:	B
General comments:	Slate intact but lying face down, at risk of further damage if left in current location		

PROPOSED REPAIRS

Proposed repairs:	Clean off organic growth and dirt. Excavate base and pin base and top of headstone to 25mm thick slate backing. Make good joints with mortar. Re-erect in original location of existing base.
Schedule of Work clauses:	2.02 and 2.09a

HEALTH AND SAFETY HAZARDS

Hazards:	Trip hazard	Headstone lying flat
----------	-------------	----------------------

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	<input type="text" value="Broken"/>	<input type="text" value="Headstone broken into 11 pieces"/>
Surface condition :	<input type="text" value="Organic growth"/>	<input type="text" value="and surface dirt"/>
Condition of inscription :	<input type="text" value="Other"/>	<input type="text" value="Growth and dirt covering parts of inscription"/>

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	<input type="text" value="None"/>	<input type="text"/>
------------------------	-----------------------------------	----------------------

GENERAL CONDITION/COMMENTS

General condition :	<input type="text" value="Poor"/>	Heritage significance:	<input type="text" value="C"/>
General comments:	<input type="text" value="Sandstone broken into several pieces. High risk of further damage"/>		

PROPOSED REPAIRS

Proposed repairs:	<input type="text" value="Clean off organic growth and dirt. Excavate base section. Pin broken sections (at least 11 no plus base) together with stainless steel dowels, and pin to 25mm thick slate backing. Make good joints with mortar. Re-erect in original location."/>
Schedule of Work clauses:	<input type="text" value="2.04 and 2.09a."/>

HEALTH AND SAFETY HAZARDS

Hazards:	<input type="text" value="Trip hazard"/>	<input type="text" value="Headstone lying flat in pieces"/>
----------	--	---

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	<input type="text" value="Broken"/>	<input type="text" value="Headstone broken off at base?"/>
Surface condition :	<input type="text" value="Surface dirt"/>	<input type="text" value="De-colouration of sandstone"/>
Condition of inscription :	<input type="text" value="Good"/>	<input type="text" value="De-colouration over inscription"/>

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	<input type="text" value="None"/>	<input type="text"/>
------------------------	-----------------------------------	----------------------

GENERAL CONDITION/COMMENTS

General condition :	<input type="text" value="Poor"/>	Heritage significance:	<input type="text" value="B"/>
General comments:	<input type="text" value="Sandstone broken into two pieces. High risk of further damage"/>		

PROPOSED REPAIRS

Proposed repairs:	<input type="text" value="Clean off organic growth and dirt. Excavate base section. Pin broken sections together (2 no plus base) with stainless steel dowels, and pin to 25mm thick slate backing. Make good joints with mortar. Re-erect in original location."/>
-------------------	---

Schedule of Work clauses:	<input type="text" value="2.04 and 2.09a."/>
---------------------------	--

HEALTH AND SAFETY HAZARDS

Hazards:	<input type="text" value="Trip hazard"/>	<input type="text" value="Headstone lying flat in pieces"/>
----------	--	---

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	<input type="text" value="Other"/>	<input type="text" value="Leaning headstone"/>
Surface condition :	<input type="text" value="Organic growth"/>	<input type="text" value="Lichen (see photo)"/>
Condition of inscription :	<input type="text" value="Other"/>	<input type="text" value="Some of inscription covered in lichen as above"/>

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	<input type="text" value="None"/>	<input type="text"/>
------------------------	-----------------------------------	----------------------

GENERAL CONDITION/COMMENTS

General condition :	<input type="text" value="Fair"/>	Heritage significance:	<input type="text" value="A"/>
General comments:	<input type="text" value="Sandstone with drastic lean, currently not unstable but may be advisable to deal with during any repair works to avoid need in the future"/>		

PROPOSED REPAIRS

Proposed repairs:	<input type="text" value="Carefully excavate headstone, and re-set vertically in the same location"/>
Schedule of Work clauses:	<input type="text" value="2.09a"/>

HEALTH AND SAFETY HAZARDS

Hazards:	<input type="text" value="Leaning headstone"/>	<input type="text" value="Headstone seems to be stable"/>
----------	--	---

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	<input type="text" value="Other"/>	<input type="text" value="Leaning headstone"/>
Surface condition :	<input type="text" value="Organic growth"/>	<input type="text" value="Lichen / tree deposit"/>
Condition of inscription :	<input type="text" value="Good"/>	<input type="text" value="Some of inscription covered with growth"/>

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	<input type="text" value="None"/>	<input type="text"/>
------------------------	-----------------------------------	----------------------

GENERAL CONDITION/COMMENTS

General condition :	<input type="text" value="Fair"/>	Heritage significance:	<input type="text" value="A"/>
General comments:	<input type="text" value="Drastic lean, currently not unstable but may be advisable to deal with during any repair works to avoid need in the future."/>		

PROPOSED REPAIRS

Proposed repairs:	<input type="text" value="Carefully excavate headstone, and re-set vertically in the same location"/>
Schedule of Work clauses:	<input type="text" value="2.09a"/>

HEALTH AND SAFETY HAZARDS

Hazards:	<input type="text" value="Leaning headstone"/>	<input type="text" value="Headstone seems to be stable"/>
----------	--	---

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	Broken	Headstone broken off at base?
Surface condition :	Good	
Condition of inscription :	Good	

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	None	
------------------------	------	--

GENERAL CONDITION/COMMENTS

General condition :	Good	Heritage significance:	B
General comments:	Good, slate lying on ground. Medium to high risk of further damage in current location.		

PROPOSED REPAIRS

Proposed repairs:	Clean off organic growth and dirt. Re-erect in original location.
-------------------	---

Schedule of Work clauses:	2.09a
---------------------------	-------

HEALTH AND SAFETY HAZARDS

Hazards:	Trip hazard	Headstone lying flat
----------	-------------	----------------------

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	Broken	Headstone broken off at base?
Surface condition :	Organic growth	Surface dirt / lichen
Condition of inscription :	Good	Some surface dirt over inscription

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	None	
------------------------	------	--

GENERAL CONDITION/COMMENTS

General condition :	Good	Heritage significance:	B
General comments:	Good, slate lying on ground. Medium to high risk of further damage		

PROPOSED REPAIRS

Proposed repairs:	Clean off organic growth and dirt. Re-erect in original location.
Schedule of Work clauses:	2.09a

HEALTH AND SAFETY HAZARDS

Hazards:	Trip hazard	Headstone lying flat
----------	-------------	----------------------

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	Broken	Headstone broken off at base?
Surface condition :	Organic growth	Surface dirt / growth
Condition of inscription :	Good	Dirt covering some of inscription

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	None	
------------------------	------	--

GENERAL CONDITION/COMMENTS

General condition :	Good	Heritage significance:	B
General comments:	Good, slate lying on ground. Medium to high risk of further damage		

PROPOSED REPAIRS

Proposed repairs:	Clean off organic growth and dirt. Re-erect in original location.
Schedule of Work clauses:	2.09a

HEALTH AND SAFETY HAZARDS

Hazards:	Trip hazard	Headstone flat on ground
----------	-------------	--------------------------

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	<input type="text" value="Missing elements"/>	<input type="text"/>
Surface condition :	<input type="text" value="Good"/>	<input type="text"/>
Condition of inscription :	<input type="text" value="Good"/>	<input type="text"/>

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	<input type="text" value="None"/>	<input type="text"/>
------------------------	-----------------------------------	----------------------

GENERAL CONDITION/COMMENTS

General condition :	<input type="text" value="Poor"/>	Heritage significance:	<input type="text" value="C"/>
General comments:	<input type="text" value="Broken headstone laid flat, only one large piece apparent, not large enough to re-erect. Not included in CMP schedule of monuments to be repaired"/>		

PROPOSED REPAIRS

Proposed repairs:	<input type="text" value="Clean off organic growth and dirt. Allow to lay back down in current location at a slope on new limecrete bed. Add J30a if it established that this is part of J28."/>
Schedule of Work clauses:	<input type="text" value="2.09b"/>

HEALTH AND SAFETY HAZARDS

Hazards:	<input type="text" value="Trip hazard"/>	<input type="text" value="Headstone laid flat on ground"/>
----------	--	--

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	<input type="text" value="Broken"/>	<input type="text" value="Headstone broken off at base"/>
Surface condition :	<input type="text" value="Good"/>	<input type="text"/>
Condition of inscription :	<input type="text" value="Good"/>	<input type="text" value="Some dirt in inscriptions"/>

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	<input type="text" value="None"/>	<input type="text"/>
------------------------	-----------------------------------	----------------------

GENERAL CONDITION/COMMENTS

General condition :	<input type="text" value="Poor"/>	Heritage significance:	<input type="text" value="B"/>
General comments:	<input type="text" value="Fair / poor - slate lying on ground, belongs to broken base J14"/>		

PROPOSED REPAIRS

Proposed repairs:	<input type="text" value="Clean off organic growth and dirt. Excavate base J14 and pin base and main section J29 to 25mm thick slate backing with stainless steel dowels. Make good joints with mortar. Re-erect at position J14."/>
Schedule of Work clauses:	<input type="text" value="2.01 and 2.09a"/>

HEALTH AND SAFETY HAZARDS

Hazards:	<input type="text" value="Trip hazard"/>	<input type="text" value="Headstone flat on ground"/>
----------	--	---

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	Other	Good condition
Surface condition :	Surface dirt	Organic growth
Condition of inscription :	Other	Inscription not visible

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	None	
------------------------	------	--

GENERAL CONDITION/COMMENTS

General condition :	Good	Heritage significance:	B
General comments:	Slate lying on ground, but in good condition. Medium to high risk of further damage		

PROPOSED REPAIRS

Proposed repairs:	Clean off organic growth and dirt. Re-erect in original location.
-------------------	---

Schedule of Work clauses:	2.09a
---------------------------	-------

HEALTH AND SAFETY HAZARDS

Hazards:	Other	Fallen headstone
----------	-------	------------------

PHOTOGRAPHS

J29. SEE J14

J30. NAME UNKNOWN



Slate, good condition, needs re-erecting.



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	Loose elements	Top corner of slate headstone broken
Surface condition :	Organic growth	Surface dirt / moss growth
Condition of inscription :	Other	Moss and other growths over most of inscription

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	None	
------------------------	------	--

GENERAL CONDITION/COMMENTS

General condition :	Poor	Heritage significance:	B
General comments:	Fair/Poor, slate lying on ground, top corner broken. Medium to high risk of further damage		

PROPOSED REPAIRS

Proposed repairs:	Clean off organic growth and dirt. Excavate base. Pin broken sections (2 no plus base) to 25mm thick slate backing with stainless steel dowels. Make good joints with mortar. Re-erect in original location.
Schedule of Work clauses:	2.01 and 2.09a

HEALTH AND SAFETY HAZARDS

Hazards:	Trip hazard	Broken and fallen headstone, flat on ground
----------	-------------	---

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	<input type="text" value="Broken"/>	<input type="text" value="Headstone broken off at base?"/>
Surface condition :	<input type="text" value="Organic growth"/>	<input type="text" value="Surface dirt"/>
Condition of inscription :	<input type="text" value="Good"/>	<input type="text"/>

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	<input type="text" value="None"/>	<input type="text"/>
------------------------	-----------------------------------	----------------------

GENERAL CONDITION/COMMENTS

General condition :	<input type="text" value="Good"/>	Heritage significance:	<input type="text" value="B"/>
General comments:	<input type="text" value="Slate headstone lying on ground, but in good condition. Medium to high risk of further damage"/>		

PROPOSED REPAIRS

Proposed repairs:	<input type="text" value="Clean off organic growth and dirt. Allow to lay back down in current location at a slope on new limecrete bed. Headstone will be re-erected if original location can be established."/>
Schedule of Work clauses:	<input type="text" value="2.09b"/>

HEALTH AND SAFETY HAZARDS

Hazards:	<input type="text" value="Trip hazard"/>	<input type="text" value="Headstone laid flat on grass"/>
----------	--	---

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	Broken	Headstone broken off at base?
Surface condition :	Surface dirt	
Condition of inscription :	Good	

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	None	
------------------------	------	--

GENERAL CONDITION/COMMENTS

General condition :	Good	Heritage significance:	B
General comments:	Slate lying on ground, but in good condition. Medium to high risk of further damage		

PROPOSED REPAIRS

Proposed repairs:	Clean off organic growth and dirt. Re-erect in original location.
-------------------	---

Schedule of Work clauses:	2.09a
---------------------------	-------

HEALTH AND SAFETY HAZARDS

Hazards:	Trip hazard	Headstone flat on ground
----------	-------------	--------------------------

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	Broken	Headstone broken off at base?
Surface condition :	Organic growth	Surface dirt
Condition of inscription :	Good	

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	None	
------------------------	------	--

GENERAL CONDITION/COMMENTS

General condition :	Fair	Heritage significance:	B
General comments:	Slate lying on ground but in good condition. Medium to high risk of further damage		

PROPOSED REPAIRS

Proposed repairs:	Clean off organic growth and dirt. Allow to lay back down in current location at a slope on new limecrete bed. Headstone will be re-erected if original location can be established.
Schedule of Work clauses:	2.09b

HEALTH AND SAFETY HAZARDS

Hazards:	Trip hazard	Headstone laid flat on ground
----------	-------------	-------------------------------

PHOTOGRAPHS



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	<input type="text" value="Other"/>	<input type="text" value="None - in very good condition"/>
Surface condition :	<input type="text" value="Surface dirt"/>	<input type="text"/>
Condition of inscription :	<input type="text" value="Good"/>	<input type="text"/>

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	<input type="text" value="None"/>	<input type="text"/>
------------------------	-----------------------------------	----------------------

GENERAL CONDITION/COMMENTS

General condition :	<input type="text" value="Good"/>	Heritage significance:	<input type="text" value="B"/>
General comments:	<input type="text" value="Slate lying on ground, but in good condition. Broken fragment beside J30a, Kelland transposes J30a and J41. Medium to high risk of further damage"/>		

PROPOSED REPAIRS

Proposed repairs:	<input type="text" value="Clean off organic growth and dirt. Re-erect in original location."/>
Schedule of Work clauses:	<input type="text" value="2.09a"/>

HEALTH AND SAFETY HAZARDS

Hazards:	<input type="text" value="Trip hazard"/>	<input type="text" value="Headstone fallen, flat on ground"/>
----------	--	---

PHOTOGRAPHS



J30A. PHOEBE MOSES, d. 1804 (Feigle daughter of Moses, d. 5565)
(Recently uncovered, beneath J41)



Slate, very good condition, should be re-erected.

Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	<input type="text" value="Broken"/>	<input type="text" value="Headstone broken off at base?"/>
Surface condition :	<input type="text" value="Surface dirt"/>	<input type="text" value="Organic growth"/>
Condition of inscription :	<input type="text" value="Good"/>	<input type="text"/>

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	<input type="text" value="None"/>	<input type="text"/>
------------------------	-----------------------------------	----------------------

GENERAL CONDITION/COMMENTS

General condition :	<input type="text" value="Good"/>	Heritage significance:	<input type="text" value="B"/>
General comments:	<input type="text" value="Slate lying on ground, but in good condition. Two pieces are lying at this location; J41 bedded flat into the turf (Phoebe Moses) with J30a beside. Medium to high risk of further damage"/>		

PROPOSED REPAIRS

Proposed repairs:	<input type="text" value="Clean off organic growth and dirt. Allow to lay back down in current location at a slope on new limecrete bed. Headstone will be re-erected if original location can be established."/>
-------------------	---

Schedule of Work clauses:	<input type="text" value="2.09b"/>
---------------------------	------------------------------------

HEALTH AND SAFETY HAZARDS

Hazards:	<input type="text" value="Trip hazard"/>	<input type="text" value="Fallen headstone flat on ground"/>
----------	--	--

PHOTOGRAPHS

Slate, upright and stable.

J41. PERHAPS PART OF 28

J42. NAME UNKNOWN



Slate, good condition, needs re-erecting.



Jewish Cemetery, Ponsharden

Proforma Condition and Repairs Schedule

IDENTIFICATION Monument reference: Date surveyed:

Name of burial (if known): Date of burial:

Others commemorated: Date of burial:

Monument type: Heritage designation:

Headstone dimensions (in mm): Height: Width: Thickness:

Tomb dimensions (in mm): Height: Width: Length:

Designer/sculptor/mason: Orientation:

DESCRIPTION Principal materials:

Technique of inscription:

Previous interventions :

STRUCTURAL CONDITION

Overall structural condition:

Ground condition :

Impact of vegetation:

Condition of foundation:

MATERIAL CONDITION (Masonry)

Types of deterioration:	<input type="text" value="Broken"/>	<input type="text" value="Headstone broken off at base"/>
Surface condition :	<input type="text" value="Other"/>	<input type="text" value="Good condition"/>
Condition of inscription :	<input type="text" value="Good"/>	<input type="text"/>

MATERIAL CONDITION (Ironwork)

Condition of ironwork:	<input type="text" value="None"/>	<input type="text"/>
------------------------	-----------------------------------	----------------------

GENERAL CONDITION/COMMENTS

General condition :	<input type="text" value="Poor"/>	Heritage significance:	<input type="text" value="B"/>
General comments:	<input type="text" value="Fair/Poor, slate broken off at base. Main section of the broken base recorded as J21. Medium to high risk of further damage"/>		

PROPOSED REPAIRS

Proposed repairs:	<input type="text" value="Clean off organic growth and dirt. Excavate base of J21 and pin base and main section to 25mm thick slate backing with stainless steel pins. Make good joints with mortar. Re-erect in original location at J21."/>
Schedule of Work clauses:	<input type="text" value="2.01 and 2.09a"/>

HEALTH AND SAFETY HAZARDS

Hazards:	<input type="text" value="Trip hazard"/>	<input type="text" value="Fallen headstone flat on ground"/>
----------	--	--

