



Notes

1. Dimensions are approximate and have been based on the most up-to-date video data.
2. Only overhead lines shown on the treatment plans. For other utilities, please refer to the C2 plans for the area.
3. Due to potential inaccuracy of video data regarding exact chainages, where core locations are within the vicinity of a gully, coring Contractor to adjust the location to avoid potential coring into / through carrier pipes.

TREATMENT KEY:

- 50mm inlay TSCS (Do Min)
- Fill and overbanding repair system for crack exceeding 5mm but not exceeding 10mm wide (Do Min)
- Deep repair/ inlay (Do Something)

Scheme Title: A36 Serrington NB & SB MP 51.6 - 52.8 RS
Drawing Title: Defect Treatment Plan 1
Drawing No: VCS Plan 2 **Rev:** A
Drawn: O L Roberts **Date:** 11/03/2021
Design: G Reed **Date:** 15/03/2021
Checked: M R Owen **Date:** 23/03/2021