

| TASK NO. | TASK/DESCRIPTION | NOTES |
|----------|--|-------|
| H9.03 | <p data-bbox="655 327 962 353">H9 MISCELLANEOUS</p> <p data-bbox="400 387 783 421">Gundeck Redundant Aerials</p> <div data-bbox="400 439 1233 1395"> </div> <p data-bbox="400 1397 1246 1541">There are five in number redundant aerials fitted on the gundeck. Two aerials have already had their mountings so weakened by corrosion that they have come detached, therefore to avoid injury or damage in the future the five remaining aerials are to be REMOVED and disposed of by Contractor.</p> | |



| TASK NO. | TASK/DESCRIPTION | NOTES |
|------------------|---|--|
| H9 MISCELLANEOUS | | |
| H9.04 | <p>Ballast Tank</p> <p>One in number ballast tank requires topping up with fresh water. Contractor is to complete this task and provide the volume of water required to the Authorised Overseer to record in ships Stability records.</p> <p>ALLOW for 500m³ fresh water.</p> | <p>Ballast tank will be identified to contractor prior to RPSD</p> |

| TASK NO. | TASK/DESCRIPTION | NOTES |
|----------|--|--|
| | L1 ELECTRICAL | |
| L1.01 | <p>Main Deck Floodlights</p> <p>Main Deck floodlights are no longer working. Investigate fault/change lamps as required. Required spares to be supplied by Contractor. Access tower or equivalent to be supplied by Contractor.</p> | <p>Working at Height precautions required.</p> |



| TASK NO. | TASK/DESCRIPTION | NOTES |
|----------|--|--|
| | L1 ELECTRICAL | |
| L1.02 | <p data-bbox="411 389 719 421">Training Area Lighting</p>  <p data-bbox="411 689 1217 831">Current festoon light strings throughout training areas are not fit for purpose and do not provide the controllability required by training staff. Renew lighting with 110v dimmable LED strip lights and provide individual zone control switches in designated locations (to be identified by training staff during contractor ships visits).</p> <p data-bbox="411 846 1217 902">ALLOW for 8 separate zones and associated fittings. ALLOW for 40 LED light fittings in total.</p> | <p data-bbox="1257 394 1390 510">Working at Height precautions required.</p> |

| TASK NO. | TASK/DESCRIPTION | NOTES |
|----------|--|--|
| | L1 ELECTRICAL | |
| L1.03 | <p>CCTV System</p> <p>Currently unable to monitor all vessel access points on board. Contractor to supply and INSTALL CCTV security system with 4 camera points (to be identified by training staff). CCTV system does not require a recording capability, live feed monitoring only. Monitor to be sited in range staff office block. Minimum ingress protection rating of IP65.</p> | <p>Hotwork Required – Appropriate precautions to be taken iaw General 8.4.</p> <p>Minimum IP65 rating.</p> <p>In conjunction with H9.02.</p> |

