

Fleet Air Museum

Project Ref: 8920

Digital Image Record (Site Visit 15th October 2015)



P01 – General view of existing bridge deck structure and entrance canopy over.



P02 – General view of existing staircase structure.



P03 – General view under cantilevering deck adjacent to staircase structure. Note moderate surface corrosion to fixings and locally to member surfaces.



P04 – Typical detail to frame over door opening in adjacent building. Note, moderate corrosion to bolted fixing.



P05 – Typical moderate surfaces corrosion to bolt head securing deck beam to principal truss.



P06 – Moderate corrosion to nuts securing staircase members and locally on surfaces of staircase members.



P07 – Significant corrosion to staircase stringers at interface with ground surface.



P08 – Significant corrosion and surface delamination of buried steel support structure.

Fleet Air Museum

Project Ref: 8920

Digital Image Record (Site Visit 22nd November 2017)



P09 – General view of existing bridge deck structure.



P10 –General view of CCTV system



P11 –General view of electrical fitting



P12 –General view of stainless steel handrail panel



P13 –General view of mesh infill panel



P14 –General view of paving slabs at base of stairs



P15 –General view of bridge and entrance to museum