


TASK NO.	TASK/DESCRIPTION	NOTES
	H2 HULL AND STRUCTURE – EXTERNAL DECKS AND ASSOCIATED FITTINGS	
H2.13	<p><b>Flight Deck Paint Coating</b></p>  <p>The flight deck has many areas of paint coating breakdown leading to active corrosion of the deck. Carry out patch repair REPRESENTATION.</p> <p>ALLOW for 25m<sup>2</sup>. REPRESENTATION.</p>	<p>IAW Paint scheme -General 12 and Annex B refer.</p> <p>To be completed in conjunction with H2.14.</p>

TASK NO.	TASK/DESCRIPTION	NOTES
H2	HULL AND STRUCTURE – EXTERNAL DECKS AND ASSOCIATED FITTINGS	
H2.14	<p><b>Flight Deck Monitors</b></p> <div style="display: flex; justify-content: space-around;">   </div> <p>Both flight deck monitors are redundant, and excessive pipe corrosion has resulted in them becoming detached from the deck. Contractor to dispose of both monitors, cut remaining pipework to deck level and weld blanks in place. REPRESENTATION on completion.</p> <p>ALLOW for 2m<sup>2</sup> REPRESENTATION.</p>	<p>Hotwork Required – Appropriate precautions to be taken iaw General 8.4.</p> <p>IAW Paint scheme -General 12 and Annex B refer.</p> <p>To be completed in conjunction with H2.13.</p>

TASK NO.	TASK/DESCRIPTION	NOTES
H2.15	<p data-bbox="432 327 1145 383">H2 HULL AND STRUCTURE – EXTERNAL DECKS AND ASSOCIATED FITTINGS</p> <p data-bbox="397 416 858 450"><b>Port and Stbd Bridge Wing Decks</b></p>  <p data-bbox="397 1043 1238 1144">Port and stbd Bridge Wing decks have large areas of paint coating breakdown and active corrosion present. REPRESERVE deck coatings. Allow for 30m<sup>2</sup> total. REPRESENTATION.</p>	<p data-bbox="1248 416 1445 528">IAW Paint scheme -General 12 and Annex B refer.</p> <p data-bbox="1248 562 1445 640">To be completed in conjunction with H3.05.</p>