Slide - Freestanding - Wave

Manufactured by Record Playground Equipment Ltd



Risk level:

Low

Potential risk score reduction:

2

Remedial tasks:

5



Surface: Rubber - Tile

Standards:

EN 1176-1:2017, EN 1176-3:2017

The item is not compliant with the requirements of the relevant standards. The surfacing meets with the requirements of the relevant standards.

Maintenance Finding

Description

Ground erosion present.

Tasks

Consider adding grass matting to prevent wear.

Note

Under stairs and unit.

Risk level:

Low

Risk score:

7

Finding Photos

Maintenance Finding

Description

Fittings are rusty.

Tasks

Replace.

Note

Bolt nuts are rusting.

Risk level:

Low

Risk score:

6

Finding Photos

Maintenance Finding

Description

There is significant corrosion on this item.

Tasks

De-scale back to good metal and coat with lead free paint, using appropriate precautions. Repairs may be necessary where corrosion is severe.

Note

Supports are starting to rust. Treat and repair then repaint.

Risk level:

Low

Risk score:

5

Finding Photos

Standard Compliance Finding

Description

Access fails the entrapment requirements.

Tasks

The unit was installed prior to the publication of the current standards. There is no requirement to make retrospective changes.

Risk level:

Low

Risk score:

5

Finding Photos

Standard Compliance Finding

Description

The spacing between the barrier bars is in excess of 89 mm.

Tasks

No reasonably practicable action is identified.

Risk level:

Low

Risk score:

6

Finding Photos