

TASK NO.	TASK/DESCRIPTION	NOTES
	H4 EXTERNAL DOORS, OPENINGS AND HATCHES	
H4.06	<p>Upper Deck Intakes and Watertight Openings</p>  <p>Numerous upper deck vent grills and hinged watertight openings have corroded beyond repair. Steel blanks to be manufactured and used to REPLACE existing openings. Relevant openings will be identified prior to Refit start date. PRESERVE on completion.</p> <p>ALLOW for 15 openings. ALLOW for 45m² REPRESENTATION.</p>	<p>Hotwork Required – Appropriate precautions to be taken iaw General 8.4.</p> <p>IAW Paint scheme -General 12 and Annex B refer.</p>

TASK NO.	TASK/DESCRIPTION	NOTES
H4 EXTERNAL DOORS, OPENINGS AND HATCHES		
H4.07	<p>Natural Vent Covers</p>  <p>01 deck stbd side. 4 in number vent openings heavily corroded with full thickness rust penetration. All 4 openings to be REMOVED, with blanks welded in place. Area to be REPRESENTED on completion.</p> <p>ALLOW for 4m² REPRESENTATION.</p>	<p>Hotwork Required – Appropriate precautions to be taken iaw General 8.4.</p> <p>I/AW Paint scheme -General 12 and Annex B refer.</p> <p>Contractor to dispose of removed items.</p>

TASK NO.	TASK/DESCRIPTION	NOTES
H4.08	<p data-bbox="400 383 842 414">Transom Access Door and Deck</p>  <p data-bbox="400 1272 1217 1473">Transom door closing mechanism is worn and regularly seizes, door does not seal properly (daylight can be seen through sealing faces when closed). Remove and REFURBISH door – to include new door seal. Platform support brackets and door frame have paint coating breakdown with active corrosion evident. REPRESENT affected areas. Chalk test to be carried out once door is refitted and door adjusted accordingly.</p> <p data-bbox="400 1487 1217 1545">Note: Wooden blank to be manufactured and fitted in place of rear door whilst REFURBISHMENT of door taking place.</p> <p data-bbox="400 1559 847 1590">ALLOW for 10m² REPRESENTATION.</p>	<p data-bbox="1248 387 1449 533">Wooden blank to be fitted whilst door is being REFURBISHED.</p> <p data-bbox="1248 562 1449 730">Hotwork Required – Appropriate precautions to be taken iaw General 8.4.</p> <p data-bbox="1248 759 1449 871">IAW Paint scheme -General 12 and Annex B refer.</p>