

TENDER CLARIFICATIONS 26TH MAY 2022

1. The upper cornice on the elevation of the 1901 building (mosaic façade) has deteriorated and would require repairing prior to installing lead flashing. A design detail has been created and can be found in the drawing titled '211042-CON-XX-GF-DR-S-4004'
2. For pricing please complete the revised pricing schedule which includes a section 7 covering the works detailed in drawing '211042-CON-XX-GF-DR-S-4004' the revised pricing document needed for submission is titled '01 - Schedules of Work - REV A - May 2022'. For clarity this supersedes the previous schedule.
3. Quality Submission word counts have been increased as per tenderer request to the below:
Q1: Resource & Experience = 1000 words
Q2: Health, Safety & Security = 1000 words
Q3: Sustainability = 750 words

Tim Hopkins

Head of Estates

26.05.22