



Comments: A high number of d fire doors have excessive gaps between the door and the frame.

Recommendations: A site inspection by a contractor to ascertain how many doors need attention/replacing as some may be able to be adjusted and some may need fully replacing.





Comments: A large number of self-closing devices have been adapted which has damaged the door and/or the door frame deeming the FD not fit for purpose.

Recommendations: A site inspection by a contractor to ascertain how many doors need attention/replacing as some may be able to be adjusted and some may need fully replacing.





Comments: A number of doors have seals missing or damaged.

Recommendations: New seals are placed either on the door or the frame.