


Rainwater gutters and downpipes are blocked or damaged in various locations on our site. It is a common occurrence for the gutters to overflow. We have identified 5 targeted areas, illustrated on the map below; that will require further investigation and a review of the gutter flow capacity, in addition remedial works will be required. *(Please see photographs on the following pages).*

*We suggest site visits, to assess access to these areas, for example access via MEWP etc.*



1b) Guttering & Downpipe above Out of Hours doors



*1b) Guttering & Downpipe above Out of Hours doors*





*1b) Guttering & Downpipe above Out of Hours doors*



2a) Guttering beside Plant Room





2b) Guttering beside Plant Room



*3a) Guttering above Server/Patch Panel Room*





*3b) Guttering above Server/Patch Panel Room*



4a) Above the FM Delivery Door



4b) Above the FM Delivery Door





5) In Front of car charger