

External Masonry Works

- ▲M1 Masonry repairs to North wall of vestry
- ▲M2 Masonry repairs to North wall of Chancel
- ▲M3 Masonry repairs to East wall of Chancel
- ▲M4 Masonry repairs to South wall of Chancel
- ▲M5 Masonry repairs to stone surround of south aisle east window
- ▲M6 Masonry repairs to buttress of south aisle south wall
- ▲M7 Masonry repairs to south wall of tower
- ▲M8 Masonry repairs to West wall of tower
- ▲M9 Masonry repairs to north tower buttresses and adjacent drainage gully
- ▲M10 Masonry repairs to north wall of nave
- ▲M11 Masonry repairs to west wall of north aisle
- ▲M12 Masonry repairs to north wall of north aisle



Refer to drawings by BHB Architects - Section 3

Various External Works

- ▲E1 External gully to be reformed
- ▲E2 Repairs to existing downpipe

Refer to drawings by BHB Architects - Section 3

Various External Works

- ▲E1 External gully to be reformed
- ▲E2 Repairs to existing downpipe

Refer to drawings by BHB Architects - Section 3

Surface Water Drainage Works

- ▲D1 Replacement of existing soakaway, drainage runs and installation of silt traps
- ▲D2 Replacement of existing soakaway, existing drainage runs to be retained
- ▲D3 Replacement of existing soakaway, existing drainage runs to be retained

Refer to proposed drainage drawings by FWH engineers - Section 6

Wall Paintings Works

●WP1








Late 17th century
Erdeswick wall paintings
Cleaning, repair and
conservation of painting
See report by Rickerby
& Shekede

●WP2



See report by Rickerby and Shekede - Section 7

Tomb Works

- ▲T1  Early 17th century chest tomb - Erdeswick family
- ▲T2  Early 17th century chest tomb - Erdeswick family
- ▲T3  Early 17th century chest tomb - Erdeswick family
- ▲T4  Early 17th century chest tomb - Erdeswick family
- ▲T5  Early 17th century tomb and monument of Samuel Erdeswick and his two wives

Cleaning, repair and preservation of late 17th century painted tombs
See report by Rickerby & Shekede - Section 7

Window Works

- wI repair west window in nave - complete removal
- sII repair south window in chancel - complete removal
- sIII repair south window in chancel - complete removal
- sIV repair 1st floor window of balcony - complete removal
- sV repair west window in south aisle - removal of 3 main lights
- sVII repair south window in south aisle - complete removal
- nVI repair west window in north aisle - top tracery light only
- nIII repair east window in vestry - top tracery casement only

See report by Jim Budd Stained Glass - Section 7

Painting Works

- P1  17th century framed painting of Royal Coat of Arms
Cleaning, repair and conservation of painting
See report by Hirst Conservation - Section 7