

Project:	Hellesdon Community Centre Refurbishment	Dagignari	ALH	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALN	Completed:	August 2021

Ref	Subject/Element Yes, No N/A		Identified Hazard	Action Code	Additional action or precautions or comments	
1.0	ADEQUACY OF BREIFING INFO M&E					
1.1	Is there a safety file for the premises?	No		С	Client to confrim	
1.2	Is there a written client brief?	No			M&E proposals reviewed by design team and client and approved.	
1.3	Has the designer visited site?	Yes				
1.4	Is there site survey information?	Yes			Limited survey notes and photos.	
1.5	Is there any info relating to site services?	Yes			Limited survey notes and photos. No details of external or underground services.	
1.6	Are there any existing drawings?	Yes			Layout only from architect.	



Project:	Hellesdon Community Centre Refurbishment	Docimori	ALH	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALM	Completed:	August 2021

Ref	Ref Subject/Element Yes,		Identified Hazard	Action Code	Additional action or precautions or comments
ELEC	TRICAL SECTION				
2.0	SITE IMPLICATIONS				
2.1	Any hazards from previous use?	No	Asbestos survey to be provided to contractors and appropriate measures taken.	C/A	
2.2	Any restrictions on development re:			-	
	- Location of sub-stations?	N/A		-	
	- Location of switch room?	No		-	
	- Position of external cable routes?	N/A	No alterations to external services proposed.	-	
	- Location of standby generator?			-	
	- Others?	No		-	



Project:	Hellesdon Community Centre Refurbishment			Date	
Client:	Hellesdon Parish Council	Designer:	ALH	Completed:	August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
3.0	ACCESS AND EGRESS				
3.1	Is access to site restricted?	No		С	Client to confirm.
3.2	Any restriction on delivery times?	No		С	Client to confirm.
3.3	Is road access adjacent to switch rooms?	No		-	
3.4	Are there steps up/down to switch room?	No		-	
3.5	Is the height/width of switch room door adequate?	Yes		-	
3.6	Is area of switch room adequate?	Yes		-	



Project:	Hellesdon Community Centre Refurbishment	Dooignor	ALH	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALI	Completed:	August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
4	EXISTING SERVICES				
4.1	Have all services been located and identified? - above ground - below ground	No	Possibility of unknown live services on the site.	С	
4.2	Can services be isolated if necessary?	Yes		-	

5	DEMOLITION/STRIPPING OUT			
5.1	Are there record drawings of existing installations?	No	-	
5.2	Have any tests for asbestos been carried out? Have materials containing asbestos been identified?	Unknown	С	Client to provide available information.



Project:	Hellesdon Community Centre Refurbishment	Dagignari	AT LI	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALH	Completed:	August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
5.3	Is a test for gases required?	N/A		-	
5.4	Is the conduit/trunking/equipment to be removed: Painted - Galvanised - Other?	Yes		А	
5.5	Can plant and equipment be handled manually?	Yes		-	
5.6	Are existing light fittings to be removed and disposed of?	Yes		А	
5.7	Have existing above ground services been located and identified?	No		А	



Project:	Hellesdon Community Centre Refurbishment	Dooignor	ALH	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALI	Completed:	August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
5.8	Is there a hazard to health from: dust - dirt Is this hazard in service ducts, floor ducts, ceilings, roof voids or any other areas?	Yes	Dust and debris from removal of existing installations.	A	

6.	0 HAZARDOUS MATERIAL				
6.	Are there any hazardous m stripping out work?	aterials in the Yes	Contractor to review items on removal for special consideration.	А	
6.	Any radio-active materials? I.e. old smoke detectors.	Yes		А	



Project:	Hellesdon Community Centre Refurbishment	Docimor	ALH	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALI	Completed:	August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
7.0	FIRE PRECAUTIONS				
7.1	Any permanent system available for use?	No	System will be replaced as part of the works an unavailable.	С	Main contractor to provide suitable arrangements.
7.2	Any protection required to heat/smoke detector heads?	N/A			
7.3	Can system-initiating zones be isolated if necessary?	N/A			

8	SITE INSTALLATION				
8.1	Has a storage area for materials been identified?	No	Contractor to agree with all parties on site and provide as required.	-	
8.2	Any means of escape routes to be maintained?	Yes		С	Main contractor to advise.



Project:	Hellesdon Community Centre Refurbishment	Docimor	ALH	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALI	Completed:	August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
					Installing contractor to provide
8.3	8.3 Any working heights of 2M?	Yes		Α	Installing contractor to provide RAMS.
8.4	Any heavy lifting involved?	Yes		Α	Installing contractor to provide RAMS.
8.5	Any use of solvent based products?	Yes	Contractors to confirm	А	
8.6	Fire protection measures?	Yes		С	Main contractor to advise

9.0	FUTURE ACCESS REQUIREMENTS			
9.1	Is adequate space provided for maintenance of the equipment?	Yes	А	
10	ISOLATION REQUIREMENTS			

Construction Design and Management Regulations M&E Designers Risk Assessment Project: Hellesdon Community Centre Refurbishment Client: Hellesdon Parish Council Designer: ALH August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
10.1	Has provision been made for isolation of services for maintenance, repair or replacement of: Plant? - Equipment? - Service runs? - Fittings?	Yes			

Construction Design and Management Regulations M&E Designers Risk Assessment Building Services Design Ltd **Project:** Hellesdon Community Centre Refurbishment Date Designer: ALH August 2021 Completed:

NOTE: Action Codes **A** – Method Statement Required, **B** – Action by Principal Designer, **C** – Action by Client

Hellesdon Parish Council

Client:

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
-----	-----------------	----------------	-------------------	----------------	--

MECH	MECHANICAL SECTION							
11	SITE IMPLICATIONS							
11.1	Any hazards from previous use?	No	Asbestos survey to be provided to contractors and appropriate measures taken.	C/A				
11.2	Any restrictions on development re:			-				
	- Location of Gas Supply?	Yes	No alterations to external services proposed.	-				
	- Position of external services routes?	N/A	No alterations to external services proposed.	-				
	- Others?	No		-				



Project:	Hellesdon Community Centre Refurbishment	Dooignor	ALH	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALI	Completed:	August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
1					
12	ACCESS AND EGRESS				
12.1	Is access to site restricted?	No		С	Client to confirm.
12.2	Any restriction on delivery times?	No		С	Client to confirm.
12.3	- Others?	No		-	

13	EXISTING SERVICES				
13.1	Have all services been located and identified? - above ground - below ground	No	External Gas & MCWS route not identified	С	Gas ECV hasn't been tested



Project:	Hellesdon Community Centre Refurbishment	Decianor	ALH	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALIT	Completed:	August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
13.2	Can services be isolated if necessary?	Yes		-	

14	DEMOLITION/STRIPPING OUT			
14.1	Are there record drawings of existing installations?	No	-	
14.2	Have any tests for asbestos been carried out? Have materials containing asbestos been identified?	Unknown	С	Client to provide available information.



Project:	Hellesdon Community Centre Refurbishment	Docionor	ALH	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALH	Completed:	August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
14.3	Is the duct equipment to be removed: Painted - Galvanised - Other?	Yes		А	
14.4	Can plant and equipment be handled manually?	No		Α	Large ducting, Fans, Boiler, Cylinder will need lifting equipment
14.5	Is there any Refrigeration equipment to be removed	Yes		А	
14.6	Have existing above ground services been located and identified?	No		А	
14.7	Is there a hazard to health from: dust - dirt Is this hazard in service ducts, floor ducts, ceilings, roof voids or any other areas?	Yes	Dust and debris from removal of existing installations.	A	



Project:	Hellesdon Community Centre Refurbishment	Dooignor	ALH	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALI	Completed:	August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
15	HAZARDOUS MATERIAL				
15.1	Are there any hazardous materials in the stripping out work?	Yes	Contractor to review items on removal for special consideration.	А	
15.2	Any Refrigerant Gasses	Yes		А	

17	SITE INSTALLATION				
17.1	Has a storage area for materials been identified?	No	Contractor to agree with all parties on site and provide as required.	-	
17.2	Any means of escape routes to be maintained?	Yes		С	Main contractor to advise.
17.3	Any working heights of 2M?	Yes		А	Installing contractor to provide RAMS.



Project:	Hellesdon Community Centre Refurbishment	Dosignor:	ALL	Date	August 2021
Client:	Hellesdon Parish Council	Designer:	ALH	Completed:	August 2021

Ref	Subject/Element	Yes, No N/A	Identified Hazard	Action Code	Additional action or precautions or comments
17.4	Any heavy lifting involved?	Yes		Α	Installing contractor to provide RAMS.
17.5	Have items that involve heavy lifting been identified?	Yes.	MVHR Units & AC External Condenser units.	А	Contractors to provide RAMS for items requiring specialist equipment/action.
17.6	Any use of solvent based products?	Yes	Contractors to confirm	А	
17.7	Is there safe access to ducts and ceilings?	Yes		-	
17.8	Fire protection measures?	Yes		С	Main contractor to advise
17.8	Hot Works	Yes		А	Installing contractor to provide RAMS.