

National Asset Delivery Technical Surveys and Testing

Site Information for 570135 M32 Eastville Viaduct – Noise Surveys

1 SITE INFORMATION

1.1 Site boundary, extents and access arrangements

The baseline noise monitoring locations are set out in Figure 1.1 and shown in Images 1.1 - 1.5. All of these locations are on public roads so no access arrangements with third parties are required. Traffic Management is required to secure a safe working area around the lighting columns.

Figure 1.1 Location of monitoring locations




Image 1.1 (Receptor 1 – Gable Road)



Image 1.2 (Receptor 2 – Gatton Road)



Image 1.3 (Receptor 3 – Stapleton Road)



Image 1.4 (Receptor 4 – Cottrell Road/ Stapleton Road)



Image 1.5 (Receptor 5 – Bell Hill)



1.2 Pavement

The lighting columns are located on public pavements which will need to be closed during installation and removal of the monitoring equipment.

1.3 Lighting Columns

The lighting columns are likely to be owned and maintained by Bristol City Council (BCC). Type and details to be obtained through liaison with the maintaining body. Permission to install the equipment from BCC will have to be sought prior to installation. The *Consultant* is required to obtain that approval and undertake any additional works that BCC may require to install the equipment.