

TASK NO.	TASK/DESCRIPTION	NOTES
	H6 EXTERNAL LADDERS	
H6.03	<p data-bbox="405 387 687 421"><b>Upper Deck Ladders</b></p>  <p data-bbox="400 1196 1214 1308">All upper deck ladders paint coatings are breaking down with active corrosion evident on ladder treads. Ladders to be SURVEYED and treads RENEWED as required. Ladder handrails also require SURVEY, RENEW as required and REPRESENTATION on completion.</p> <p data-bbox="400 1339 1214 1397">ALLOW for 10 Ladder rungs and 6 handrail RENEWAL. ALLOW for 300m<sup>2</sup> REPRESENTATION.</p>	<p data-bbox="1249 387 1449 562">Hotwork Required – Appropriate precautions to be taken iaw General 8.4.</p> <p data-bbox="1249 591 1449 703">IAW Paint scheme -General 12 and Annex B refer.</p> <p data-bbox="1249 732 1449 790">Complete IAW Ref. 5.</p>

TASK NO.	TASK/DESCRIPTION H6 EXTERNAL LADDERS	NOTES
H6.04	<p><b>Crane Deck Ladder</b></p>  <p>The crane deck is out of bounds for training exercises therefore a lockable 'No Access' grill is to be manufactured and fitted to the ladder cage. Ladder and cage to be REPRESENTED following removal of broken down paint coatings.</p> <p>ALLOW for 3m<sup>2</sup> REPRESENTATION.</p>	<p>IAW Paint scheme -General 12 and Annex B refer.</p>

TASK NO.	TASK/DESCRIPTION	NOTES
H7.01	<p data-bbox="400 383 863 416"><b>Steering Gear Compartment Bilge</b></p>  <p data-bbox="400 1648 1233 1733">The paint coatings have broken down allowing active surface corrosion on both port and stbd sides bilge wells. Area requires scaling back and cleaning before REPRESENTATION.</p> <p data-bbox="400 1744 970 1776">ALLOW for 8m<sup>2</sup> REPRESENTATION. either side.</p>	<p data-bbox="1249 383 1445 499">IAW Paint scheme -General 12 and Annex B refer.</p> <p data-bbox="1249 528 1410 645">Contractor to remove and dispose of all arisings.</p> <p data-bbox="1249 674 1445 837">Adequate ventilation to be arranged before work commences IAW General 3.2.</p>