

Customer Details

North Northamptonshire Council
New Shire Hall, Emery Crescent, Enterprise Campus,
Alconbury Weald,
Huntingdon
Cambridgeshire
PE28 4YE

Site Details

William Knibb Centre
Montagu St
Kettering
Northamptonshire, England
NN16 8AE

Job Details

Job Number: PM0000894/001/000

Job Type: Reactive / Call-out

Date Logged: 08/08/2024 11:37

Order Number:

Contact Name:

Date Complete: 15/08/2024 15:21

Description

Return to site to inspect YO009

(Not charging customer for return visit so to be scheduled when convenient)

Limitations, Notes & Scope of Work

14/08/2024 08:27 - work complete

15/08/2024 15:22 - inspection complete

All reasonable attempts have been made to undertake a thorough inspection to the fire resisting doors of the premise, in line with applicable guidance, legislation and manufacturer's instructions (if available). Our assessment does not include removal of architrave, hinges, closers or other decorative features of the fire door assembly (unless by prior agreement with the client). We also have not allowed for testing of fire door closing/holding from third-party equipment (such as those linked to fire alarm systems, or battery-powered acoustic devices) - unless where stated. If asbestos is suspected within, or surrounding the door set, we will undertake a visual inspection of the door in situ only. This is an assessment of the door's likelihood to resist fire and smoke, not a compliance check to certify doors installed by others - this is only possible when a new door set (including frame, ironmongery & certificates) are supplied and installed by a competent person from a single manufacturer. E&OE. Other limitations are listed above in the notes section.

Visits

Visit Date	Engineer	Customer	Status	Visit Complete
------------	----------	----------	--------	----------------

13:00	301 - Mark Dicks	North Northamptonshire Council	Aborted	13:30
	Customer Signature		Engineer Signature	

Print Name: 301 - Mark Dicks

Visit Date	Engineer	Customer	Status	Visit Complete
------------	----------	----------	--------	----------------

13:00	302 - Zak Clark-Monks	North Northamptonshire Council	Complete	15:30
	Customer Signature		Engineer Signature	

Print Name: 302 - Zak Clark-Monks

Visit Date	Engineer	Customer	Status	Visit Complete
------------	----------	----------	--------	----------------

12:24	301 - Mark Dicks	North Northamptonshire Council	Complete	15:21
	Customer Signature		Engineer Signature	

Print Name:

301 - Mark Dicks

1

M

A list of assets, their status, and any remedial work required can be seen overleaf ../

Assets Inspected					
Asset #	Description	Location	Notes / Action Required	Visit Status	Condition
YO009	Fire Door Single, timber, unglazed Lock/Latched. No certification seen on leaf,lock,latch,handle.	GF Photography	Hinges not certified Gap in door stop Holes to door faces Holes to edge of door Excessive gap to head Lock not certified Door not certified	Completed	FAIL (Major defect)

Photos of the assets, their condition and historical data can be seen in your client hub, along with the above information.
If you don't have access to your client hub, please contact the office on 01536 526138 / info@folgatesafety.co.uk