

Serial Number	Item Description		Packaging Level	Turnaround time (Business Days)	Strip Survey	Firm Price (ex Vat) (£) Year 1-7	Authorised Repair Threshold (Clause 46.5) Year 1	Authorised Repair Threshold (Clause 46.5) Year 2	Authorised Repair Threshold (Clause 46.5) Year 3	Authorised Repair Threshold (Clause 46.5) Year 4
	Ultra PCS Software Reference									
7	NSN:	7025993514124	N		Strip Survey Assessment					
	MoD Description:	DISPLAY UNIT								
	Ultra PCS PN	676300101								
	Ultra PCS Software Reference									
8	NSN:	2590993018377	N		Strip Survey Assessment					
	MoD Description:	CONTROL UNIT								
	Ultra PCS PN	676300102								
	Ultra PCS Software Reference									
9	NSN:	2590998132337	A		Strip Survey Assessment					
	MoD Description:	CONTROL UNIT								
	Ultra PCS PN	676300102								
	Ultra PCS Software Reference									
10	NSN:	5998990270854	N		Strip Survey Assessment					
	MoD Description:	CIRCUIT CARD ASSY								
	Ultra PCS PN	649500123								
	Ultra PCS Software Reference									
11	NSN:	1240996604273	N		Strip Survey Assessment					
	MoD Description:	CONTROLLER								
	Ultra PCS PN	649500100								
	Ultra PCS Software Reference									
12	NSN:	1290993834248	1		Strip Survey Assessment					
	MoD Description:	PANEL GUNNERS CO								

Serial Number	Item Description		Packaging Level	Turnaround time (Business Days)	Strip Survey	Firm Price (ex Vat) (£) Year 1-7	Authorised Repair Threshold (Clause 46.5) Year 1	Authorised Repair Threshold (Clause 46.5) Year 2	Authorised Repair Threshold (Clause 46.5) Year 3	Authorised Repair Threshold (Clause 46.5) Year 4
12	Ultra PCS PN	667700200								
	Ultra PCS Software Reference									
13	NSN:	6720993868233	N		Strip Survey Assessment					
	MoD Description:	CAMERA								
	Ultra PCS PN	6797 801 00								
	Ultra PCS Software Reference									
14	NSN:	5836999613623	A		Strip Survey Assessment					
	MoD Description:	VSPU								
	Ultra PCS PN	677280100								
	Ultra PCS Software Reference									
15	NSN:	5855992501892	A		Strip Survey Assessment					
	MoD Description:	ILLUMINATOR								
	Ultra PCS PN	6799 801 00								
	Ultra PCS Software Reference									
16	NSN:	5855998600335	N		Strip Survey Assessment					
	MoD Description:	ILLUMINATOR								
	Ultra PCS PN	6798 801 00								
	Ultra PCS Software Reference									
17	NSN:	6610998980458	N		Strip Survey Assessment					
	MoD Description:	CREW DISPLAY UNIT								
	Ultra PCS PN	6779 801 00								
	Ultra PCS Software Reference									
	NSN:	2540992127648								

Serial Number	Item Description		Packaging Level	Turnaround time (Business Days)	Strip Survey	Firm Price (ex Vat) (£) Year 1-7	Authorised Repair Threshold (Clause 46.5) Year 1	Authorised Repair Threshold (Clause 46.5) Year 2	Authorised Repair Threshold (Clause 46.5) Year 3	Authorised Repair Threshold (Clause 46.5) Year 4
	Ultra PCS Software Reference									
30	NSN:	2590996609074	N		Strip Survey Assessment					
	MoD Description:	CYLINDER								
	Ultra PCS PN	BS24-001								
31	NSN:	2590993252409	A		Strip Survey Assessment					
	MoD Description:	BOTTLE								
	Ultra PCS PN	BS06-002								
32	NSN:	2510993470510	N		Strip Survey Assessment					
	MoD Description:	CONTROLLER								
	Ultra PCS PN	850900100								
	Ultra PCS Software	SW850900101								

Authorised Repair Threshold (Clause 46.5) Year 5	Authorised Repair Threshold (Clause 46.5) Year 6	Authorised Repair Threshold (Clause 46.5) Year 7