

[illegible]

WARNING:
Asbestos Containing Vinyl
Floor Tiles in Room N. See
Asbestos Report.

To new kitchen at first floor, provide new Saniflow system for waste extract to sink to connect to existing foul drainage connection in tower.

Where Secondary Glazing is to be installed, this is to be laminated glass to B.S.6202 in extruded aluminium alloy, white finish. Minimum 100mm gap to be maintained between inner frame of existing timber window and secondary glazing frame. Secondary glazing to comply with Part K of the Building Regulations.

WARNING:
Potential Adhesives
Containing Gaskets In
Boiler House. See asbestos
Report.

[illegible]