

## Wetherby Close Play Area (Infant/Junior)

New seesaw – supply and install seesaw and wetpour



Wooden multiplay – Timber repair



Wooden beams – paint/stain





Slide – paint



Infant swing – Dig out loose posts and re-instate, paint frame





Springer Duck – Replace missing caps and wetpour strip repair



Spring flamingo – replace missing caps, wetpour strip repair



Spinner – wetpour strip repair



