




rev	date	amendment	dwn	chkd
A	07.06.19	Plinth bricks changed to regular, aluminium window cill added. Windows moved outward by 20mm	cad	gt




71 Typical window jamb plan detail




72 Typical System glazing jamb detail




73 Typical System glazing external corner post detail



74 Typical Detail between exist and new cavity walls and system glazing jamb



75 Typical System glazing internal corner post junction with internal door side panel



76 Typical System glazing external corner post junction with external door side panel

