

Query	Response
<p>Designed levels. There are no finished levels shown on the car park. At tender stage as explained we were advised to price on the basis of taken out the construction make up. Whilst for budget purposes this was ok in order to provide an accurate quotation we need the finished levels on a drawing.</p>	<p>Finished levels to be provided by 12A as per the rest of the site. 12A drawings 121519 E(90)001 (A) - 121519 E(90)003(A) show the GA for the Berrycombe Vale site.</p>
<p>Drawings 2002 rev 03 and LD-12 rev 02 show different surfacing specifications in the same areas (around the disabled bays)</p>	<p>We will update our drawings so that they align.</p>
<p>Existing cycleway. Can this be closed for the duration of the works or does it have to be maintained? If it must be maintained we will need to build a temporary cycleway around the perimeter of the site. If that is the case what specification does it need to be built too. Would sub-base suffice?</p>	<p>Not for Arup. Refer to Planning/TPI?</p>

<p>The coloured tarmac is stated as permeable, could we not apply thermoplastic or antiskid to delineate walkways?</p>	<p>Unclear as to the query? Is this asking if white lining can be applied to permeable tarmac or is it asking if the coloured tarmac can be removed if delineated with white lines?</p> <p>Minor white lining is acceptable, however large areas of coverings (antiskid) must be permeable.</p>
<p>Coach park – we need to provide 3 timber picnic benches – can we please have a specification and manufactures drawings. Also thinking about it they are shown on the grass area. Should they be bolted down and if so on to what?</p>	<p>Refer to NBS Specification Q50 230A (https://www.broxap.com/land-timber-picnic-unit.html). For fixing method, please refer to manufacturer's recommendations, alternatively use soft ground fixing metal anchors/straps.</p>
<p>Bus shelters – no details have been provided. Who is providing these and is a base required?</p>	<p>No bus shelters are shown, only bus stops.</p>
<p>Timber benches – same comments as coach park picnic table</p>	<p>Refer to NBS Specification Q50 220. If the specified bench is no longer available – please use Hodnet Seat (BX17 4010-RT) from Broxap in the same, Hardwood Iroko. (https://www.broxap.com/hodnet-seat.html). For fixing method, please refer to manufacturer's recommendations.</p>
<p>There appears to be 3 main changes o Concrete channel in the entrance – detail required</p>	<p>Unsure as to query/location of detail requested.</p>
<p>There appears to be 3 main changes o 20m of additional post and 3 rail fence</p>	<p>No query, however refer to LD59 for post and rail fence details.</p>
<p>There appears to be 3 main changes</p>	<p>Refer to NBS Specification Q50 190 (http://www.versauk.co.uk/Bollards/Timber.html#sthash.RGwUoLDD.dpbs</p>

o Bollards –
manufacturers
detail required
please

), our drawing LD58 detail: BD3. For fixing method, refer to manufacturer recommendations.