

## TENDER CLARIFICATIONS 17<sup>TH</sup> JUNE 2020

---

1. Architectural drawing LAB-649-PL-1100.Existing Plan
  - Was previously a duplication of LAB-649-PL-1200 Proposed Plan.
  - Has now been updated to be correct drawing of existing.
2. Structural drawing 306193-S-100B
  - Drawing has been updated and all other versions removed from portal. See below for previous clarification, now superseded.

~~Structural Drawing 306193-S-100B has been superseded.~~

  - ~~• Structural Drawing 306193-S-100B has been superseded by 306193-S-100B-REV-A which has been added as a PDF and CAD upload to the contracts finder webpage.~~
  - ~~• Please note the previous drawing is still currently accessible via the dropbox link for reference.~~
3. Structural drawing 306193-S-101A (showing structural steel details)
  - Drawing has been uploaded to tender portal.
4. MEP Drawing 5997-HAH-00-SW-DR-M-50-0100
  - Above MEP drawing was mislabelled, now corrected.
  - Drawing has not been changed.
5. Who is the fire alarm maintenance contractor?
  - The incumbent fire alarm maintenance contractor for the museum is Trinity Fire and Security Systems.
6. No external lighting is shown on the drawings of the chiller compound?
  - External lighting in the chiller compound is noted in the spec, but not on the drawing.
  - Allow for 2 number external lights, as specified Thorn Piazza.

Tim Hopkins

Head of Estates

16.06.20