


Legend

- Replace water table stones and base plinth stones, pin and glue
- Rebuild Flint
- Install new bricks
- Repoint
- Existing Bricks to be reused



Note: Do not scale from drawing, check dimensions on site

This drawing is copyright ©

Drawing Title	Job No	Dwg No	Rev	Scale	Drawn:MSA
Detail, Buttress Repair	590	/ 2103		1:20 @ A3	10/02/2017
Revision	Date				
	PCC and Churchwardens				
	Thetford Cemetery Chapel Repairs to South Side				
	© Nicholas Warns Architect Ltd.				
	64 Bishopgate Norwich, NR1 4AA			T: 01603 622056	
	info@nicholaswarns.com			F: 01603 627 393	