



**National Asset Delivery
Technical Surveys and Testing**

**Site Information for
SWAD 2023 Tree Condition Surveys:
A36 Bathampton to M27 Junction 2**

1 SITE INFORMATION

1.1 Site boundary, extents and access arrangements

This 2023 Tree Condition Survey is for the following length of the National Highways Strategic Road Network (SRN), of approximately 90 km:

- A36 Bathampton to M27 Junction 2 (A36 Marker Post 0/0 to 89/3)

The *Consultant* must inspect all trees alongside the trunk road length stated above where they are considered to be within falling distance of the highway, and in addition inspect all trees within National Highways soft estate that have the potential to affect pathways used by the public through or within plots (footpaths, cycleways, bridleways) and also inspect all trees within National Highways soft estate that are within falling distance of the estate boundary where they may present a hazard to third party property or users on other public and private roads and pathways. For all trees with identified hazards and / or defects, the *Consultant* must undertake a detailed Technical Survey (Formal Survey) to assess the level of risk and make management recommendations including any treatments and re-inspections if required before the next detailed inspection on this route programmed for June 2026.

No access should be made onto private land without prior consent of the landowner (and tenant, if applicable).

The *Consultant* must place and be competent to place 'Surveying' signs on the network where field staff are visible to road users for periods exceeding 15 minutes. Such signs are information signs, not instruction signs, therefore the person(s) placing them do not require Chapter 8 sector scheme certification. Signs must be placed 1.2m away from traffic and facing oncoming traffic.

If stopping or parking in the verge or a maintenance hard standing space, the survey vehicle must be marked up appropriately for Highways Maintenance (Chapter 8 compliant). If an unmarked private vehicle is used, it may only be used in the same way as any other road user (i.e. no stopping or parking in the verge, nor parking within maintenance hard standings).

Some stretches of the network may require temporary traffic management to safely inspect / survey the trees. These road lengths will need to be identified by the *Consultant* early on and details provided to the Technical Surveys Manager at SWSurveys@nationalhighways.co.uk

Traffic management and road space booking will be arranged by the Technical Surveys Manager and provided by National Highways supply chain at no cost to the *Consultant*.

Some 4 to 6 weeks is usually required to make the necessary arrangements for traffic management and it is subject to road space being available. The provider of traffic management would become Lead Contractor for these elements of the survey and their safety requirements will need to be complied with.

It is a requirement that all persons working on the National Highways network wear Class 3 high visibility long sleeved yellow jackets and trousers, white helmet, gloves, eye protection and protective footwear at all times. Other personal protective equipment identified in the *Consultant's* Risk Assessment must also be worn as and when appropriate.

It is prohibited to cross any live National Highways carriageway on foot, including slip lanes up to the node point where the National Highways network switches to County road. Crossing a live County road is not prohibited.

The Regional Operations Centre (ROC) must be advised in advance of accessing the network, then at arrival on site and finally on departure from site.

1.2 Pavement

No detail.

1.3 Drainage

No detail.

1.4 Geotechnical

No detail.

1.5 Soft Estate and Environment

This survey requires knowledge of the National Highways operational estate. The extent of the estate is contained within a GIS layer provided with this package.

Detailed requirements for this survey are provided separately in the 'Tree Condition Inspections / Surveys - Supply Chain Brief' for the 'SWAD 2023 Tree Condition Surveys – Trunk Roads: A36 Bathampton to M27 Junction 2'.

1.6 Traffic Signs, Road Markings

No detail.

1.7 Lighting

No detail.

1.8 Structures and Buildings

No detail.

1.9 Tunnels

No detail.

1.10 Technology

No detail.

1.11 Statutory Undertakers

No detail.

1.12 Traffic

No detail.