Supplier (Intellectual Property Owner)	Product Description	Date of Creation	Type of Intellectual Property	MOD pre-existing rights (DEFCONS)	Free Rights for Authority/ Successor Contractor to continue to Operate
	COMMUNICATION UNIT, NSN 0661-99/799-3596, OEM 668/GA/00479/000				IIS are prepared to offer supply and repair services of this item to the Authority / Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
Total Integrated Solutions Limited			Legacy		any form of agreement.
	CHARGER BATTERY, NSN 0661-99/535-6297, OEM 5230010268JE95		<u> </u>		IIS are prepared to other supply and repair services of this item to the Authority /
			Legacy		Successor. As of the date of this ITN return, no tenderer has requested pricing and/or any form of agreement.
	CASING SENTRY PANEL, NSN 0661-99/152-3767, OEM T900082A4		Legacy		IIS are prepared to offer supply and repair services of this item to the Authority /
					Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
			Legacy		any form of agreement.
	JUNCTION BOX CAMERA, NSN W648-99/372-4532, OEM ECCJB-BBV				Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
			Legacy		any form of agreement.
	JUNCTION BOX CAMERA, NSN W648-99/853-4077, OEM ECCJB-RLY				Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
Total Integrated Solutions Limited	SONO HON BOX ONMERN, NON WORD 33/000 FOR 7, OEM ECOUD RET		Legacy		any form of agreement.
					IIS are prepared to offer supply and repair services of this item to the Authority / Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
Total Integrated Solutions Limited	FLIGHT DECK FIXED CAMERA G.A., NSN W648-99/555-6216, 16042LJ15		Legacy		any form of agreement.
					IIS are prepared to offer supply and repair services of this item to the Authority /
Total Integrated Solutions Limited	CCTV CONTROL KEYBOARD G.A., NSN W648-99/512-9871, 16046LJ15		Logony		Successor. As of the date of this ITN return, no tenderer has requested pricing and/or any form of agreement.
			Legacy		IIS are prepared to offer supply and repair services of this item to the Authority /
Total Integrated Solutions Limited	WASHER UNIT G.A., NSN W648-99/853-8462, 16049LJ15				Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
			Legacy		any form of agreement.
Total Integrated Solutions Limited	CAMERA ASSEMBLY, NSN W648-99/841-7497, OEM SS-W-SS-630-ZL				Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
			Legacy		any form of agreement.
Total Integrated Solutions Limited	CAMERA ASSEMBLY, NSN W648-99/216-6363, OEM SS-W-FB-630-FL				IIS are prepared to offer supply and repair services of this item to the Authority / Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
	CAMERA ASSEMBET, NSN W040-99/210-0505, CEM 35-W-I B-050-I E		Legacy		any form of agreement.
Total Integrated Solutions Limited					IIS are prepared to offer supply and repair services of this item to the Authority / Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
	CAMERA ASSEMBLY, NSN W648-99/396-4692, OEM SS-N-BB-630-FL		Legacy		any form of agreement.
			Logacy		IIS are prepared to offer supply and repair services of this item to the Authority /
Total Integrated Solutions Limited	RESERVOIR POWER WASH, NSN W648-99/810-6301, OEM 10279CL95				Successor. As of the date of this ITN return, no tenderer has requested pricing and/or any form of agreement.
			Legacy		IIS are prepared to offer supply and repair services of this item to the Authority /
Total Integrated Solutions Limited	VESA MOUNTING PLATE & RAM MOUNT, NSN 5895-99-350-2714, OEM 16040LJ15				Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
	100401313		Legacy		any form of agreement. IIS are prepared to offer supply and repair services of this item to the Authority /
	17" LCD MONITOR MODIFIED INCLUDING MOUNTING PLATE, RAM MOUNT AND				Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
Total Integrated Solutions Limited	PSU BRACKET, NSN 5820-99-842-7242, OEM 16041LJ15		Legacy		any form of agreement.
	ISOLATION SWITCH PANEL PSU (24VAC), NSN 6130-99-258-3383, OEM				IIS are prepared to offer supply and repair services of this item to the Authority / Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
Total Integrated Solutions Limited	16944LJ16		Legacy		any form of agreement.
					IIS are prepared to offer supply and repair services of this item to the Authority / Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
Total Integrated Solutions Limited	CCTV CONTROL FLUSH KEYBOARD, NSN 5895-99-464-8919, OEM 16996LJ16		Legacy		any form of agreement.
			oguoj		IIS are prepared to offer supply and repair services of this item to the Authority /
Total Integrated Solutions Limited	QUAD VIDEO DISPLAY UNIT, NSN 5820-99-639-1982, OEM 16949LJ16				Successor. As of the date of this ITN return, no tenderer has requested pricing and/or any form of agreement.
			Legacy		IIS are prepared to offer supply and repair services of this item to the Authority /
	CAMERA ISOLATION SWITCH PANEL, NSN 5895-99-670-0099, OEM 16946LJ16				Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
Total Integrated Solutions Limited			Legacy		any form of agreement.
Total Integrated Solutions Limited	ISOLATION SWITCH PANEL PSU (27VAC), NSN 6130-99-670-0097, OEM				Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
	16945LJ16		Legacy		any form of agreement.
	PTZ CAMERA JUNCTION BOX AND CAMERA MOUNTING PLATE, NSN 5820-99-				IIS are prepared to offer supply and repair services of this item to the Authority / Successor. As of the date of this ITN return, no tenderer has requested pricing and/or
Total Integrated Solutions Limited	856-5030, OEM 16959LJ16		Legacy		any form of agreement.