
ISSUE 1



ISSUE 2

G/F double riser

Seal cable bunch

Seal around plastic conduit housing wires




ISSUE 3

Seal cable bunch



ISSUE 4

Infill void to wall



ISSUE 5

Seal around cable bunches and seal around metal cable trays

3 x cable tray

7 x cable bunches



ISSUE 6

G/F double riser

1723mm wide x 2083mm high x 120mm deep frame



ISSUE 7

G/F access door opposite flat 2

1020mm wide x 2075mm high x 120mm



ISSUE 8

690mm side x 2075mm



ISSUE 9



ISSUE 10



ISSUE 11



ISSUE 12
1700mm wide



ISSUE 13



ISSUE 14



ISSUE 15



ISSUE 16



ISSUE 17



ISSUE 18

1st floor double riser - 1

1320mm wide

FD60 required due to housing gas



ISSUE 19

1st floor double riser - 2



ISSUE 20



ISSUE 21



ISSUE 22



ISSUE 23




ISSUE 24

2nd floor double riser

Excessive foam in cupboard



ISSUE 25



ISSUE 26



ISSUE 27



ISSUE 28



ISSUE 29

Single riser

Wrap around pipework and seal cable bunch



ISSUE 30

Seal cables and perimeter seal



ISSUE 31

1st floor double riser



ISSUE 32



ISSUE 33



ISSUE 34



ISSUE 35

2nd riser cupboard 1st floor remove foam and seal



ISSUE 36

Remove foam and seal cables



ISSUE 37

1600mm wide x 2090mm high x 125mm deep

X 2 sets



ISSUE 38



ISSUE 39