Lift refurbishment

Date / company	Query	Response
02.09.2023	Please advise if it's only the hydraulic valve block that needs replacing or it is the complete hydraulic power unit?	We have spoken to the lift consultant and he advises that it is the complete hydraulic power unit that is to be replaced.