

lead flashings and
soakers to be
inspected and
replaced as
necessary with
code 4 lead to
match existing



cheeks and gable
to be re-clad in
unfinished cedar
TG&V boards to
match existing
size/profile

fixed light glazing to
be retained as
existing and any
rotten timbers to be
replaced with new
treated timber of
same size/profile as
existing. Window to
have new stained
finished to match
existing (Sadolin
Woodshield,
mahogany)

Rev

Project

Whitchurch Town Hall

Dwg No.

19.19.08

Scale @ A4

NTS

Date

09/20

Drawing

West elevation dormer repairs

Issued for:

LBC

© All documents remain the property of Hall & Ensom in perpetuity.

Hall&Ensom



Tel: 01256 889 851

www.hallandensom.co.uk