

_UKMCK\$DKA0: [DATA.SCRATCH]RCV_MSG_PRT.TXT;1084

8-NOV-2016 10:37

/21925 00000/2710/16 313 0300

/125/2320/007/01

/2711/-4/+02775.3 000.8 +00.00/16 312 1755 59.67/0

/9/09.348/0000/13

/4F46E909E260156AB00480000000000

/+227/+52.306/+004.797/089 000.5 000.5/94/16 313 0433/3/001.5 001.0

/-232/+46.887/-024.035/027 003.8 002.9/06/16 313 0609/1/020.4 012.7

/LASSIT

/ENDMSG

©ARC125 081016

DD EGQPZSZX

081016 LIJCYFYX

●/11181 00000/2470/16 313 1016

/915/2320

/FM ITMCC COSPAS-SARSAT BARI

TO FMCC NMCC TRMCC UKMCC GRMCC

REF 406 BEACON HEXACODE: D4664901DF3E311

COUNTRY: 675 / UGANDA

INFORMATION RECEIVED FROM RCC NAIROBI

QUOTE

NAME: NIL

TYPE: AIRCRAFT

R. MARK: 5X-BAZ

FLAG: UGANDA

POSITION: NAIROBI AIRPORT

RESULT: FALSE ALERT

REASON OF ACTIVATION: BEACON MISHANDLING

UNQUOTE

BEST REGARDS

ITMCC OPERATOR

QQQQ

/LASSIT

/ENDMSG