

ARUN DISTRICT COUNCIL PLAYGROUNDS (EAST) OPERATIONAL INSPECTIONS, WEEK COMMENCING 13th May 2024

OPERATIONAL INSPECTION SHEET

Site Name/Address		Woodlands Avenue Fitness Trail - Rustington										Inspected by:- Bruce Taunton	
Date of Inspection		14/05	Time	15:30	No. of Units on Site		10		Attachments		Around the Unit		
Piece/type of Equipment Fitness Equipment	Item	Paint Condition		Super-structure		Moving Parts		Yes		No		General comments	
		Yes	No	Yes	No	Yes	No	Yes	No	Yes	No		
Double Cross Country Skier	2	✓		✓		✓			✓			One fixing missing at bottom of south west arm. One foot plate damaged.	
Seated Chest Press	3	✓		✓		✓			✓			Rust on west arm. Corrosion on welds.	
Air Skier	4	✓		✓		✓			✓				
Arm & Pedal Bike	5	✓		✓		✓			✓			Handle grips stiff and need oiling	
Strength Trainer	6	✓		✓		✓			✓			Wheels becoming loose on spindle.	
Push-up / Dip Station	7	✓		✓					✓				
Double Air Walker	8	✓		✓		✓			✓			One footrest damaged. Faded graffiti on south post.	
Double Sit up Boards	9	✓		✓					✓			Slight surface damage to both boards.	
Double Rower	11	✓		✓		✓			✓			Bottom tube both end caps missing.	
Seated Leg Press	12	✓		✓		✓			✓			Slight surface damage to one seat. Faded graffiti on north seat and back rest	
Ancillary site items -													
Other Comments (i.e. condition of site, other equipment/furniture).													
Site - IF IMMEDIATE ACTION IS REQUIRED, MARK ACCORDINGLY													
Strength Trainer - Inhibitor/buffers removed as replacements are no longer commercially available. Some minor surface corrosion on number of unit joints & welds.													