| TASK NO. | TASK/DESCRIPTION  | NOTES  |
|----------|---|--|
|          | H5 TOPSIDES AND SUPERSTRUCTURE  | The southers   |
| H5.04    | Draught Marks   | IAW Paint<br>scheme -General<br>12 and Annex B<br>refer. |
|          |   |  |
|          | Fwd, Midships and Aft draught marks port and stbd are obscured with marine growth and paint coverings are degraded. All relevant areas to be cleaned and REPRESERVED (Black on topsides, white on boot toppings). |  |
|          | ALLOW for 6m <sup>2</sup> REPRESERVATION.   | -  |

| TASK NO. | TASK/DESCRIPTION<br>H5 TOPSIDES AND SUPERSTRUCTURE | NOTES  |
|----------|--|--|
| H5.03    | <image/> <image/> <image/> <image/> <image/>       | IAW Paint<br>scheme -General<br>12 and Annex B<br>refer.<br>To be completed<br>in conjunction<br>with H5.06. |

| TASK NO. | TASK/DESCRIPTION<br>H5 TOPSIDES AND SUPERSTRUCTURE   | NOTES  |
|----------|--|--|
| H5.05    | Draught Indicators   | IAW Paint<br>scheme -General<br>12 and Annex B<br>refer. |
|          | Port and stbd draught indicators are obscured, worn and difficult to identify. Indicators (2 x port, 2 x stbd) – REPRESERVE coatings.<br>ALLOW for 8m <sup>2</sup> REPRESERVATION. |  |

