

---

# Photographs

<p>Photograph 1 Main Hall</p>	
<p>Photograph 2 Main Hall</p>	
<p>Photograph 3 Main Hall</p>	

<p>Photograph 4 Main Hall</p>	 A photograph of a main hall. In the center, there are white-framed double doors with black handles. Above the doors is a green exit sign. To the left of the doors is a blue noticeboard with several papers pinned to it. To the right is a brown noticeboard with various notices. A red fire extinguisher is mounted on the wall to the right of the doors. The walls are a light beige color, and the ceiling has a circular recessed light fixture.
<p>Photograph 5 Cupboard 1</p>	 A photograph of a room with white walls and a white door on the left. A radiator is visible at the bottom left. In the center of the room, there is a metal rolling cart. To the right, several dark brown plastic chairs are stacked together.
<p>Photograph 6 Cupboard 1</p>	 A photograph of a room with white walls and a white door on the right. A ceiling light fixture is visible. In the center, several light brown plastic chairs are arranged in rows. A metal rolling cart is visible on the right side of the room.

Photograph 7  
Main Entrance  
Lobby



Photograph 8  
Main Entrance  
Lobby



---

<p>Photograph 9</p> <p>Main Entrance Lobby</p>	
<p>Photograph 10</p> <p>Main Entrance Lobby</p>	

Photograph 11  
Main Entrance  
Lobby



Photograph 12  
Men's WC



Photograph 13  
Men's WC



Photograph 14  
Men's WC



Photograph 15  
Ladies WC



Photograph 16  
Ladies WC



Photograph 17  
Disabled WC



Photograph 18  
Disabled WC



<p>Photograph 19 Disabled WC</p>	
<p>Photograph 20 Kitchen</p>	
<p>Photograph 21 Kitchen</p>	

Photograph 22

Kitchen



Photograph 23

Kitchen



Photograph 24  
Kitchen



Photograph 25  
Boiler Cupboard



Photograph 26  
Boiler Cupboard



Photograph 27  
Boiler Cupboard



Photograph 28  
Cupboard 4



Photograph 29  
Cupboard 4



Photograph 30

Storage / File Room



Photograph 31

Storage / File Room



Photograph 32  
Storage / File  
Room




Photograph 33  
Loft Void



Photograph 34  
Loft Void



<p>Photograph 35 Loft Void</p>	 A photograph showing the interior of a loft void. The structure consists of wooden rafters and joists. There is a large roll of yellow insulation material and several green pipes running through the space. A white rectangular object is visible among the rafters.
<p>Photograph 36 Front Elevation</p>	 A photograph of the front elevation of a single-story brick building. The building has a gabled roof and a sign that reads "Portfields Community Centre". There are bushes in the foreground and a blue sky in the background.
<p>Photograph 37 Front Elevation</p>	 A photograph of the front elevation of the building, focusing on the entrance. The entrance features a set of double glass doors with a metal handrail on either side. The building is constructed of red brick. There are signs on the wall, including one that says "KEEP WALKERS OFF" and another that says "Co".

<p>Photograph 38 Front Elevation</p>	 A photograph showing the front elevation of a brick building. The wall is made of red and brown bricks. There is a window with a dark frame. A white downpipe runs vertically down the side of the wall. The building is situated on a grassy area next to a green fence.
<p>Photograph 39 Front Elevation</p>	 A close-up photograph of a window frame on a brick wall. The window has a dark frame and a concrete sill. The brickwork is red and brown.
<p>Photograph 40 Left Elevation</p>	 A photograph showing the left elevation of a brick building. The building is made of red and brown bricks. There is a window. A green fence runs along the side of the building. The sky is blue with some clouds.

<p>Photograph 41 Left Elevation</p>	 A photograph showing the left elevation of a brick wall. The wall is constructed from multi-colored bricks in shades of red, orange, and grey. A small, dark-framed window is visible on the right side of the wall. In the foreground, there is a green bush and a gravel path. A black metal fence is visible in the background under a clear blue sky.
<p>Photograph 42 Left Elevation</p>	 A photograph showing the left elevation of a brick wall. The wall is made of multi-colored bricks. In the foreground, there are three concrete steps leading up to a wooden door. To the left, another brick wall is partially visible. The background shows a clear sky and some trees.
<p>Photograph 43 Left Elevation</p>	 A photograph showing the left elevation of a brick wall. The wall is made of multi-colored bricks. A dark door is visible on the right side of the wall. A white gutter runs vertically down the left side of the wall. In the foreground, there is a concrete path. The background shows a clear sky and some trees.

<p>Photograph 44 Rear Elevation</p>	 A close-up photograph of the rear elevation of a brick building. The wall is made of red bricks. On the left, there is a dark-colored door with a vertical glass panel. To the right of the door is a window with a dark frame. Above the window, there are two small, rectangular light fixtures. The building is situated on a concrete slab. To the right, a wooden fence is visible.
<p>Photograph 45 Rear Elevation</p>	 A wide-angle photograph of the rear elevation of a brick building. The building is a single-story structure with a grey roof. The front of the building features several dark-framed doors and windows. In front of the building is a paved area, and to the left, there is a green lawn. The sky is clear and blue.
<p>Photograph 46 Rear Elevation</p>	 A close-up photograph of the rear elevation of a brick building. The image shows a window with a dark frame and a brick wall. The bricks are red and arranged in a traditional pattern. The sky is clear and blue.

<p>Photograph 47</p> <p>Rear and Right-Hand Elevations</p>	 A photograph showing the rear and right-hand elevations of a single-story brick building. The building has a dark roof with a gutter and a downpipe. A paved area is visible in the foreground, and a black bin is located near the building's corner. The sky is clear and blue.
<p>Photograph 48</p> <p>Right Hand Elevation</p>	 A photograph showing the right-hand elevation of a brick building, viewed from a narrow paved alleyway. The brickwork is a mix of red and brown tones. A black bin is visible in the distance at the end of the alley. The sky is clear and blue.
<p>Photograph 49</p> <p>Right Hand Elevation</p>	 A photograph showing the right-hand elevation of a brick building. A window with a white mesh screen is visible. A black bin is positioned in the foreground on the paved area. A light fixture is mounted on the brick wall above the window. The sky is clear and blue.

Photograph 50  
Right Hand  
Elevation



Photograph 51  
Right Hand  
Elevation



<p>Photograph 52</p> <p>Car Park</p>	
<p>Photograph 53</p> <p>Car Park</p>	
<p>Photograph 54</p> <p>Car Park</p>	

---

Photograph 55

Car Park

