

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: <b>F6</b> DATE: 17/06/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Door (north) – 2040x1620. 2. Louvre (north) – 670x1850. 3. X2 openings with metal work still present (see photo). Opening in the metal work measured – 800x940. 4. Door (south) – 2040x1610. 5. Louvre (south) – 700x1185.	<ul style="list-style-type: none"><li>• Access restricted due to vegetation.</li><li>• Partially cleared of vegetation.</li><li>• Metal work present in building.</li><li>• [REDACTED]</li></ul>



Door; Louvre (south).

Door; Louvre (north).

Access.

Openings with metal work (east). All photos are ©Natural England.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: <b>K3</b> DATE: 17/06/2024	LOCATION:
MEASUREMENTS: 1. Door (north) – 1980x1670. 2. X4 windows (west) – 920x1720.	NOTES: <ul style="list-style-type: none"><li>• Cleared of vegetation.</li><li>• Access restricted due to rough/wet ground and vegetation.</li></ul>



Door (north).  
All photos are ©Natural England.

Windows (west).

Access.




HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

*All measurements are approximate (brick work to brick work) & in mm.*

BUILDING ID: <b>K4</b> DATE: 17/06/2024	LOCATION:
MEASUREMENTS:	NOTES:
<ol style="list-style-type: none"><li>1. Window (annex) (north) – 1060x1320.</li><li>2. X5 windows (north) – 2120x1330.</li><li>3. Window (west) – 2100x1330.</li><li>4. X2 windows (west) – 1400x1820.</li><li>5. Door (annex) (south) – 2900&amp;2200x2990.</li><li>6. Knocked through windows (south) – 2900x4650.</li><li>7. X3 windows (south) – 1400x1820.</li><li>8. Door (annex) (east) – 2050x1050.</li></ol>	<ul style="list-style-type: none"><li>• Access restricted due to vegetation.</li><li>• Partial clearance of vegetation.</li></ul>



Windows (south).  
Openings (south)



Windows (north).



Windows (west).

All photos are ©Natural England.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

*All measurements are approximate (brick work to brick work) & in mm.*

BUILDING ID: <b>LATRINE 28</b> DATE: 17/06/2024	LOCATION: locate.dress.danger
MEASUREMENTS:  1. Door (west) – 2020x840. 2. X2 window (west) – 620x620. 3. Window (east) – 630x1240.	NOTES:  • Restricted access due to vegetation. • <span style="background-color: black; color: black;">[REDACTED]</span>



Door; Windows (west).  
All photos are ©Natural England.

Window (east).



# HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

*All measurements are approximate (brick work to brick work) & in mm.*

BUILDING ID: <b>N5</b> DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Not measured due to flooding.	<ul style="list-style-type: none"> <li>• Not cleared of vegetation.</li> <li>• Not accessible due to vegetation and water levels.</li> <li>• Barn owls present.</li> </ul>



N5 Flooded.  
 All photos are ©Natural England.

Access.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: <b>N7</b> DATE: 17/06/2024	LOCATION: stages.oddly.finest
MEASUREMENTS:	NOTES:
1. X3 windows (glazed) (north) – 500x1610. 2. Door (west) – 2140x1220. 3. Louvre (west) – 765x1590. 4. X4 circular openings (south) – 460 diameter. 5. Door (east) – 2140x1220. 6. Louvre (east) – 765x1590.	<ul style="list-style-type: none"><li>• Mostly cleared of vegetation.</li><li>• Access restricted due to vegetation.</li><li>• Scrap metal present.</li></ul>



Door; Louvre (east).  
Circular openings (south). All photos are ©Natural England.

Windows (glazed) (north).

Access.



HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

BUILDING ID: <b>M2</b> DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
<ol style="list-style-type: none"><li>1. Door (north) - 2770x2460.</li><li>2. Lower hole (north) - 250x460.</li><li>3. X4 window openings (west) - 1010x1780.</li><li>4. X1 window opening (south) - 1010x1780.</li><li>5. X2 louvre (north)(south) - ~ 670x1260.</li><li>6. Distance between external pillars (west) from N to S:<ol style="list-style-type: none"><li>6.1. – 1940.</li><li>6.2. – 1890.</li><li>6.3. – 1890.</li><li>6.4. – 1950.</li></ol></li><li>7. Distance between external pillars (south) – 2480.</li></ol>	<ul style="list-style-type: none"><li>• Mostly cleared of vegetation.</li><li>• Access restricted due to single windblown tree.</li><li>• Obvious signs of previous public usage.</li><li>• Large amounts of detritus.</li></ul>



Door; Louvre; Holes (north).      Holes (north).      Louvre (south).  
Window openings (west)(south). All photos are ©Natural England.

HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

All measurements are approximate (brick work to brick work) & in mm.

<b>BUILDING ID: M3</b> <b>DATE: 17/06/2024</b>	<b>LOCATION:</b>
<b>MEASUREMENTS:</b>	<b>NOTES:</b>
1. Door (north) – 1980x1670. 2. X4 windows (west) – 920x1720.	<ul style="list-style-type: none"><li>• Restricted access due to vegetation.</li></ul>



Door (north).  
All photos are ©Natural England.

Windows (west).

Access.



# HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

*All measurements are approximate (brick work to brick work) & in mm.*

BUILDING ID: <b>S17</b> DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Door (west) – 2210x1070.	<ul style="list-style-type: none"> <li>• Clear of vegetation.</li> <li>• Access clear.</li> <li>• Previous door shuttering removed.</li> <li>• Barn owls present.</li> </ul>



Door opening (west).      Barn owl entrance.  
 All photos are ©Natural England.

BUILDING ID: <b>S18</b> DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Door (west) – 2230x1070.	<ul style="list-style-type: none"><li>• Clear of vegetation.</li><li>• Access clear.</li></ul>



Door (west).  
All photos are ©Natural England.



# HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

*All measurements are approximate (brick work to brick work) & in mm.*

BUILDING ID: <b>S19</b> DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Door (west) – unmeasured due to vegetation (appears standard).	<ul style="list-style-type: none"> <li>• Not cleared of vegetation.</li> <li>• Not accessible.</li> <li>• Presumed un-swept?</li> <li>• Barn owls present.</li> </ul>



Access. Door (west).  
 All photos are ©Natural England.

# HOLTON HEATH (NORTH) – STRUCTURAL OPENINGS AUDIT

*All measurements are approximate (brick work to brick work) & in mm.*

BUILDING ID: <b>S21</b> DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Door opening (west) – 2220x1060.	<ul style="list-style-type: none"> <li>• Mostly cleared of vegetation.</li> <li>• Access restricted due to vegetation.</li> <li>• Previous door shuttering removed.</li> </ul>



Door opening (west).  
All photos are ©Natural England.



BUILDING ID: <b>M6 (ANNEX)</b> DATE: 17/06/2024	LOCATION:
MEASUREMENTS:	NOTES:
1.	<div></div> <ul style="list-style-type: none"><li>• Restricted access due to vegetation.</li></ul>



All photos are ©Natural England.

BUILDING ID: <b>M7 (ANNEX)</b> DATE: 17/06/2024	LOCATION:
MEASUREMENTS:	NOTES:
1.	<ul style="list-style-type: none"><li>• Inaccessible due to vegetation.</li><li>• Similar building type to M6</li></ul>



BUILDING ID: <b>N3 (ANNEX)</b> DATE: 24/05/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Window (north) – 1010x1310. 2. Door (west) - 2230x1650. 3. Door (west) – 2210x1650 4. Door (south) – 3000&2310x2920. 5. Door (east) – 2000x1040.	<ul style="list-style-type: none"><li>• Restricted access due to vegetation and flooding.</li></ul>

BUILDING ID: <b>N4 (ANNEX)</b> DATE: 17/06/2024	LOCATION:
MEASUREMENTS:	NOTES:
1. Window (north) – 1010x1320. 2. Door (west) – 2250x1640. 3. Door (west) – 2250x1650. 4. Door (partially obstructed) (south) – 3060&2250x2900. 5. Door (east) – 2050x1040.	<ul style="list-style-type: none"><li>• Access restricted due to vegetation and flooding.</li></ul>

S1



