





KWT South Blean Culvert Repairs 1 Drawing ref: KWT_CR1_21_A

Feature	
Existing ground	Existing culvert pipe
Fill	Rebar
Cut	Concrete mix sandbag
Indication of adjoining feature	Precast concrete pipe
Water	Stone
Water control pipe	Water flow
Twinwall pipe	Geotextile



Date: 30/07/2021

1 centimeter = 1.1 meters







Reproduced from the digital Ordnance Survey map by permission of Ordnance Survey on behalf of The Controller of Her Majesty's Stationery Office.
©Crown Copyright. All rights reserved. RSPB licence 100021787



Figure 1 3a Culvert Repair 1 South Blean

KWT West Blean Large Bund/Culvert 1 Drawing ref: KWT_LBC1_21_A

Feature	
	Existing ground
	Fill
	Cut
	Indication of adjoining feature
	Water
	Water control pipe
	Twinwall pipe
	Existing culvert pipe
	Rebar
	Concrete mix sandbag
	Precast concrete pipe
	Stone
	Geotextile



Date: 30/07/2021

1 centimeter = 1.1 meters

0 1.25 2.5 5 Meters

Reproduced from the digital Ordnance Survey map by permission of Ordnance Survey on behalf of The Controller of Her Majesty's Stationery Office.
©Crown Copyright. All rights reserved. RSPB licence 100021787



Figure 2 2a.1 Large earth bund/ culvert KWT West Blean