Bideford Pannier Market 07/04/2025 1454

## **OUTLINE SCOPE OF WORKS WITH SITE IMAGES**

## Outline scope of works

**Description** Areas / detail. Site setup and access. External and internal scaffolding to roofs of Pannier Market and Butcher's Row. Timber roof structure repair. Allowance for underlying wet rot decays. Some material replacement but mostly splint repairs. Roofing renewal. Renew sloped slate roofs and low-profile sheet roofs. Assumed 80% renewal. Assess and upgrade rainwater disposal system. Rainwater disposal system. Inclusion of additional timber structure. External window upgrade. Replace large windows with double-glazed units and upgrade clerestory windows with appropriate toughened glass, allowing for some opening lights to improve roof access. Excludes Butcher's Row and Market Place shop units. External Masonry. Allowance for brick, stone, ceramic tile, mortar maintenance. Electrical services Minor upgrades to lighting, small power, fire detection, WIFI,

Plumbing upgrades. Public WCs.

Heating. Possible removal of heaters suspended from ceiling, replaced

with lower level radiant panels / bench heaters.

Security and build off the existing system.

Decoration. Supplementary decoration on part to some areas of the building.

Bideford Pannier Market 07/04/2025 1454

## Site images



1. Butchers Row: Exterior from Grenville Street (North East Elevation).



2. Butcher's Row: Combination of slate and corrugated sheet roofing.

Bideford Pannier Market 07/04/2025 1454



3. Market Hall: Interior looking North West. Sarking boards to underside of slate roof.



4. Market Hall: Exterior from Honestone Street (South West Elevation).



5. Market Hall: Exterior from Market Place, showing North Elevation.