

Resurfacing Salts Play Park Pathways

IMAGES

Image 1 – Site Aerial View




Image 2 – Access to site (red arrows), and Site compound area (marked with an X)



Image 3 – The pathways (marked in blue)




Image 4 – In wet weather areas of the pathways are prone to extreme puddling.



Image 5 – 2 areas (Toddlers - Area 1; and under 5s - Area 2) may be resurfaced (a few months after the pathways are resurfaced), most likely with a bonded rubber mulch, and extended to the pathways.



Images 6-18 - The current pathways







