



The Play Inspection Company Ltd
Unit 5 Glenmore Business Park
Blackhill Road
Poole
Dorset
BH16 6NL
01202 590675

Woodlands Recreation Ground Fitness Equipment

Inspection Ref: 2333056

Site Ref: 22733

Operational Inspection - 3-April-2024 - 12:41 Inspector Dom Park (RPII Annual Inspector)

Risk Assessment: 9 Low Risk



Location:

The site is partially overlooked by properties in the local community

Disabled Access:

Some accessible features; an area that presents difficulties to the majority of people with disabilities but in favourable circumstances and certainly in partnership can be accessed.